



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20007810/Gvf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 04-08-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4655J	Veh. Inspected	SLT 1769L
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT20060010	Excess (\$)	0.00
Assign From	CARINE KEK	Assign Date	29/07/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GP71121025	Colour	BLUE
Odometer	192495	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	ACHILLES	6 mm
L/H Front Tyre	185/60 R15	ACHILLES	6 mm
R/H Rear Tyre	185/60 R15	ACHILLES	6 mm
L/H Rear Tyre	185/60 R15	ACHILLES	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/06/2020	Inspection Date	03/06/2020
Survey held at	1 Kaki Bukit Ave 6 Autobay @ Kaki Bukit #01-60		
Repairer	RELIABLE CARZ PTE LTD		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------