

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DMPCSNW00055642003

Accident Date : 13-Jul-2020

Our Ref : 020074 / CHAN

No. : 06194

Date : 15-Jul-2020

PAGE : 1

CHINA TAIPING INSURANCE (SINGAPORE) P/L
3 ANSON ROAD
#16-00
SPRINGLEAF TOWER
Singapore 079909

ESTIMATED COST OF REPAIR FOR VOLVO S60 T2 SLD2982P

1 pc Front n/s fender
1 pc Front n/s fender inner shield
1 pc Front n/s side mirror housing
1 pc Front n/s mirror cover
1 pc Front n/s mirror cover lamp
1 pc Front n/s mirror glass

Bt 850.00 ✓
Svc 150.00 ✓
Cra 500.00 ✓
Mis 200.00 ✓
Mis 90.00 ✓
Mtg Cra 180.00 ✓

1,970.00
Add: 15% : 295.50

1820.00
293.00
2113.00
2,265.50

1 pc Front n/s sport rim

Dd 800.00 sn ✓

To check and adjust wheel alignment

65.00 60

To putty and spray replaced parts

500 1,000.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500
800.00

Total : S\$ 4,930.50

Singapore Dollars Four Thousand Nine Hundred
and Thirty and Cents Fifty Only

4 sum
3200.00

P 2093.00
SN 800.00
L 1110.00
2003.00
800.00
3202.40

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DMPCSNW00055642003
Accident Date : 13-Jul-2020

No. : 06194

Date : 15-Jul-2020

Our Ref : 020074 / CHAN

PAGE : 1

CHINA TAIPING INSURANCE (SINGAPORE) P/L
3 ANSON ROAD
#16-00
SPRINGLEAF TOWER
Singapore 079909

Not Authored
LI Pump &
Repair After Paint
4 days

ESTIMATED COST OF REPAIR FOR VOLVO S60 T2 SLD2982P

1 pc Front n/s fender
1 pc Front n/s fender inner shield
1 pc Front n/s side mirror housing
1 pc Front n/s mirror cover
1 pc Front n/s mirror cover lamp
1 pc Front n/s mirror glass

By 1,093.00 ✓
199.00 *7x*
em 700.80 ✓
n/s 300.40 ✓
n/s 110.70 ✓
my em 227.90 ✓

2,631.80

Less 10% : 263.18

2432.80
243.28
2189.52

1 pc Front n/s sport rim

2,368.62
800.00 sn ✓

To check and adjust wheel alignment

65.00 *60*

To putty and spray replaced parts

550 1,000.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500
800.00

Total : S\$ 5,033.62

Singapore Dollars Five Thousand and Thirty Three
and Cents Sixty Two Only

4/5 sum
3250.00
ok 12/8
KENNETH PUS
COATMAN
TKS

P 2189.52
SN 800.00
L 1110.00
4099.52
819.90
3279.62

5f3
862
u