

ASS. REC. BY:

REF:

CT2 / 2000 7814/Kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : DMPCSNW00055642003
Accident Date : 13-Jul-2020

No. : 06194

Date : 15-Jul-2020

Our Ref : 020074 / CHAN

PAGE : 1

CHINA TAIPING INSURANCE (SINGAPORE) P/L
3 ANSON ROAD
#16-00
SPRINGLEAF TOWER
Singapore 079909

Not Authored
LLP @ 3250/
Beating After Paint
4 days

ESTIMATED COST OF REPAIR FOR VOLVO S60 T2 SLD2982P

1 pc Front n/s fender
1 pc Front n/s fender inner shield
1 pc Front n/s side mirror housing
1 pc Front n/s mirror cover
1 pc Front n/s mirror cover lamp
1 pc Front n/s mirror glass

By 1,093.00 ✓
Sm 199.00 X
cm 700.80 ✓
m 300.40 ✓
m 110.70 ✓
mg cm 227.90 ✓

2,631.80

Less 10% : 263.18

1 pc Front n/s sport rim

Net 2,368.62 ✓
800.00 sn

To check and adjust wheel alignment

65.00 *60*

To putty and spray replaced parts

550 1,000.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500
800.00

Total : S\$ 5,033.62

Singapore Dollars Five Thousand and Thirty Three
and Cents Sixty Two Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: