

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9715X**

AAD2007-099

*NOT WITHHOLD**61 Rmp 840501*

27 JUL 2020

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident:  
 Third Party Insurer:  
 Date of Registration:

**SHD 9715X**

VF1ABL15AUC276046

RENAULT

LATITUDE

26.7.2020

FCIL

04/12/2013

| PART                                     | LIST                            |     |
|------------------------------------------|---------------------------------|-----|
| 1 BUMPER COVER FRT                       | \$ <i>mgm</i> 747.20            | ✓   |
| 1 BUMPER SPOILER FRT                     | \$ <i>sn</i> 344.70             | X   |
| 1 BUMPER ABSORBER FRT                    | \$ <i>sn</i> 394.68             | X   |
| 1 BUMPER BRACKET FRT LH (Headlamp Lower) | \$ <i>sn</i> 116.47             | X   |
| 1 BUMPER RETAINER FRT LH                 | \$ <i>cm</i> 101.40             | ✓   |
| 1 BUMPER UNDERTRAY FRT                   | \$ <i>sn</i> 292.50             | X   |
| 1 BUMPER GRILLE LOWER FRT                | \$ <i>sn</i> 147.00             | X   |
| 1 HEADLAMP LH                            | \$ <i>mgm</i> 743.60            | ✓   |
| 1 HEADLAMP PANEL FRT LH                  | \$ <i>R</i> 128.30              | X   |
| 1 FENDER PANEL FRT LH                    | \$ <i>R</i> 437.10              | ✓   |
| 1 WHEELARCH FRT LH                       | \$ <i>cm</i> 191.40             | ✓   |
| 1 FENDER BRACKET FRT LH                  | \$ <i>sn</i> 106.40             | } X |
| 1 FENDER INSULATOR LH                    | \$ <i>sn</i> 66.30              |     |
| 1 RADIATOR GRILLE                        | \$ <i>sn</i> 969.90             |     |
| 1 RADIATOR GRILLE BADGE 'RENAULT'        | \$ <i>sn</i> 225.36             |     |
| 1 RADIATOR GRILLE FRAME                  | \$ <i>sn</i> 686.00             |     |
| 1 FRAME FULL SUPPORT PANEL               | \$ <i>sn</i> 592.70             |     |
| 1 BONNET                                 | \$ <i>R</i> 1,312.70            |     |
| 1 BONNET HINGE LH                        | \$ <i>R</i> 236.50              |     |
| 1 AIR CLEANER LOWER                      | \$ <i>sn</i> 271.26             |     |
| 1 AIR CLEANER HOSE                       | \$ <i>sn</i> 175.85             |     |
| 1 AIR CLEANER BOX                        | \$ <i>sn</i> 464.20             | } X |
| 1 DOOR PANEL FRT LH                      | \$ <i>R</i> 2,844.66            |     |
| 1 DOOR MIRROR ASSY LH                    | \$ <i>cm</i> <i>sn</i> 1,483.40 |     |
| 1 DOOR HINGE UPPER LH                    | \$ <i>R</i> 274.50              |     |
| 1 DOOR HINGE LOWER LH                    | \$ <i>R</i> 300.55              | } X |
| 1 DOOR CHECK FRT LH                      | \$ <i>sn</i> 90.90              |     |
| 1 DOOR FINISHER FRT LH                   | \$ <i>sn</i> 258.90             |     |

|       |                               |    |    |           |   |   |
|-------|-------------------------------|----|----|-----------|---|---|
| 1     | DOOR FINISHER CLIP KIT FRT LH | \$ | nn | 94.00     | } | X |
| 1     | DOOR HANDLE OUTER FRT LH      | \$ | sn | 169.50    |   |   |
| 1     | DOOR PANEL REAR LH            | \$ | n  | 2,844.66  |   |   |
| 1     | LOWER ARM LH                  | \$ | sn | 192.70    |   |   |
| 1     | ABSORBER FRT LH               | \$ | sn | 274.10    |   |   |
| 1     | KNUCKLE ARM LH                | \$ | sn | 481.50    |   |   |
| 1     | DRIVESHAFT LH                 | \$ | n  | 1,355.70  |   |   |
| 1     | KNUCKLE HUB+BEARING LH        | \$ | nn | 272.30    |   |   |
| 1     | SUBFRAME OUTER FRT            | \$ | sn | 1,094.20  |   |   |
| TOTAL |                               | \$ |    | 20,783.08 |   |   |
| 10%   |                               | \$ |    | 2,078.31  |   |   |
|       |                               | \$ |    | 18,704.78 |   |   |

### Special Nett

|       |                                 |    |    |          |   |   |
|-------|---------------------------------|----|----|----------|---|---|
| 1     | BUMPER CLIP FRT                 | \$ | nn | 75.00    | } | X |
| 1     | BUMPER BRACKET CLIP FRT LH      | \$ | nn | 60.00    |   |   |
| 1     | BUMPER RETAINER CLIP FRT LH     | \$ | nn | 65.00    |   |   |
| 1     | BUMPER GRILLE LOWER CLIP        | \$ | nn | 69.00    |   |   |
| 1     | BUMPER SPOILER CLIP             | \$ | nn | 60.00    |   |   |
| 1SET  | FRAME FULL SUPPORT PANEL CLIP   | \$ | nn | 70.00    |   |   |
| 2     | FRAME FULL SUPPORT PANEL NUT    | \$ | nn | 45.00    |   |   |
| 2     | FRAME FULL SUPPORT PANEL STUD   | \$ | nn | 45.00    |   |   |
| 1     | WHEELARCH CLIP FRT LH           | \$ | nn | 65.00    | } | X |
| 1     | FRONT LEFT TYRE                 | \$ | sn | 300.00   |   |   |
| 1     | FRONT LEFT TYRE RIM             | \$ | sn | 380.00   |   |   |
| 1SET  | Front licence plate with holder | \$ | sn | 100.00   |   |   |
| 1SET  | RADIATOR GRILLE SCREW           | \$ | nn | 50.00    |   |   |
| 1SET  | RADIATOR GRILLE FRAME CLIP      | \$ | nn | 55.00    |   |   |
| 1     | FRONT DOOR STICKER 'Trans-Cab'  | \$ | nn | 80.00    |   |   |
| 1     | FRONT DOOR STICKER 'Classic'    | \$ | nn | 80.00    |   |   |
| 1     | REAR DOOR STICKER "6555-3333"   | \$ | nn | 100.00   |   |   |
| TOTAL |                                 | \$ |    | 1,699.00 |   |   |

### Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9715X

AAD2007-099

**TOTAL PARTS \$ 20,403.78**

### LABOUR



|                                                                                                                           |    |          |      |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|------|
| Putty and spray painting of the affected portion.                                                                         | \$ | 4,000.00 | 8801 |
| To transfer of rear door fittings, attachment and perform water seepage test.                                             | \$ | ~ 170.00 | X    |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 4,000.00 | 5001 |
| To transfer of front fender fittings, attachment and perform water seepage test.                                          | \$ | ~ 170.00 | X    |
| To transfer of bonnet fittings, attachment and perform water seepage test.                                                | \$ | ~ 170.00 | X    |
| To check steering geometry and computer wheel alignment                                                                   | \$ | ~ 220.00 | X    |
| To transfer of front bumper fittings, attachment and perform water seepage test.                                          | \$ | ~ 170.00 | X    |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | ~ 170.00 | X    |
| To transfer of front door fittings, attachment and perform water seepage test.                                            | \$ | ~ 170.00 | X    |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | ~ 380.00 | X    |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00   | 201  |

AAD2007-099

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9715X**

|                                                                                               |    |          |   |
|-----------------------------------------------------------------------------------------------|----|----------|---|
| To dismantle and refit front end suspension, undercarriage parts, final checking and testing. | \$ | ~ 380.00 | X |
|-----------------------------------------------------------------------------------------------|----|----------|---|

To rust-proofing and apply undercoat of the affected areas.

\$ 250.00 30/

To check ABS and brake efficiency, final checking and testing.

\$ 380.00 X

To dismantle and refit engine cross-member and engine mounting.

\$ 380.00 X

**TOTAL \$ 11,180.00**

**Over All Total \$ 31,583.78**

**LUMP SUM (REPAIR DAY)**

20 DAYS

3 days

**For Official Use**

Prepared By : \_\_\_\_\_  
(Accident Dept)

Verify By : \_\_\_\_\_  
(Accident Workshop)

Checked By : \_\_\_\_\_  
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: