

ESTIMATE FOR SLA3132K

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Mr Chua

15 Tampines Central 7
#03-11 The Tampines Trilliant
Singapore 528771

Mobile: +6590991236

Vehicle & Document Information

WIP No 44027
Reg No/Reg Date SLA3132K / 03/02/2015
Date In/Mileage 107436
Chassis No WDD2060402R034410
Engine No 27491030263073
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 027 755 Tenorite Gr/ 041 101 ARTICO Blac

Account No Terms Date/Time Printed CSE Operator
CSI00003 Cash 29/07/2020/ 10:28 VS 356 / Vincent Seah

Description of Goods / Services

Qty Unit Price Disc% Amount

M BPNSUN				POLICY NO/ACC DATE : DNM120035711801 / 29.07.2020			
TOW IN/EXCESS				29.07.2020 //			
DATE IN/DATE SURVEY: 29.07.2020 //							
BY/AUTHORIZED ON :							
S BPNTOW				150.00			
TOWING				0.10 380.00			
A BPILAB				60.00			
"USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT"							
S BPNSUB				120.00			
SUPPLY 1 PC NUMBER PLATE WITH HOUSING.NETT							
FRONT							
A BPILAB				540.00			
REMOVE & REPLACE HEADLAMP WITH FOCUS ADJUSTMENT.NETT							
A BPILAB				960.00			
INSPECT & CONDUCT WHEEL ALIGNMENT.NETT							
A BPILAB				5280.00			
"REMOVE & REPLACE RADIATOR COOLING SYSTEM, CONDENSER WITH VACUUM AND RECHARGE OF REFRIGERANT.NETT"							
A BPILAB				3000.00			
REMOVE & REPLACE ON FRONT BUMPER, RHF/LHF FENDER, BONNET, FRONT SUPPORT PANEL							
A BPIRES							
RESPRAY ON FRONT BUMPER, BONNET, RHF/LHF FENDER				1.00	127.51	00.00	127.51
M RHF FENDER OUTER LINEAR <i>X 50L</i>				1.00	28.52	00.00	28.52
M UPPER BUMPER COVER SEALING <i>neu</i>				1.00	127.51	00.00	127.51
M LHF FENDER OUTER LINEAR <i>cut</i>				4.00	5.87	00.00	23.48
M RIVET <i>neu</i>				1.00	929.45	00.00	929.45
M LEFT FRONT FENDER <i>St</i>				1.00	929.45	00.00	929.45
M RIGHT FRONT FENDER <i>Repair</i>				1.00	1580.69	00.00	1580.69
M FRONT BUMPER <i>To be</i>				1.00	1231.65	00.00	1231.65
M RADAR SENSOR <i>? neu</i>							

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 6388
Fax: 6779 5383
www.mercedes-benz.com.sg

 Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

27x29=679

250+675+60+80+110=1175