



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI20007818/R1qf3e2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 07-09-2020



Code : UOI2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLA 3132K
Policy No.	DHOM120035711801	Coverage (\$)	0.00
Claim No.	M12D13642008	Excess (\$)	750.00
Assign From	JOSEPHINE WONG	Assign Date	29/07/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180 AV	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2050402R034410	Colour	GREY
Odometer	107436	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/50 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/07/2020	Inspection Date	29/07/2020
Survey held at	188 Pandan Loop		
Repairer	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$80,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------