

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 29-Jul-20

INSURANCE: EQ

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHD6528P

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR BUMPER <i>town cut</i>	1	\$ 647.31	\$ 647.31
REAR BUMPER LOWER COVER NH	1	\$ 779.99	\$ 779.99
REAR BUMPER SIDE RETAINER NH	1	\$ 159.08	\$ 159.08
REAR BUMPER CLIPS <i>new</i>	1	\$ 31.05	\$ 31.05
REAR BUMPER UPPER STOPPER (LH/RH) NH	2	\$ 107.84	\$ 215.68
SEAL, REAR BUMPER SIDE, LH NS	1	\$ 209.47	\$ 209.47
REAR BUMPER UNDER SIDE COVER (LH) NH	1	\$ 327.47	\$ 327.47
ARM SUB-ASSY, REAR BUMPER, LH NS	1	\$ 197.05	\$ 197.05
TAIL LAMP ASSY (UPPER) <i>cut</i>	1	\$ 787.48	\$ 787.48
TAIL LAMP ASSY (LOWER) <i>crack</i>	1	\$ 774.07	\$ 774.07
TAIL LAMP QUARTER PANEL NH	1	\$ 304.88	\$ 304.88
TAIL LAMP SIDE COVER NH	1	\$ 361.34	\$ 361.34
REAR TAILLAMP GUIDE - WHITE NH	1	\$ 134.52	\$ 134.52
REAR FIBER TOOL BOX TRIM (LH) NH	1	\$ 844.08	\$ 844.08
SPARE TYRE SIDE PANEL (LH) NH	1	\$ 277.36	\$ 277.36
REAR FENDER, LH <i>3mc</i>	1	\$ 1,181.00	\$ 1,181.00
REAR FENDER INNER PANEL (LH) NH	1	\$ 1,027.57	\$ 1,027.57
REAR FENDER OUTER PANEL, LH <i>repair</i>	1	\$ 685.99	\$ 685.99
REAR FENDER REINFORCEMENT, ROCKER, PANEL, LH NH	1	\$ 779.57	\$ 779.57
REAR FLOOR PANEL SIDE (LH) NH	1	\$ 389.86	\$ 389.86
REAR FENDER SHIELD (LH) <i>deformed</i>	1	\$ 245.88	\$ 245.88
REAR FENDER TRIMBOARD (LH) NH	1	\$ 1,023.34	\$ 1,023.34
REAR FENDER AIR DUCT NH	1	\$ 233.04	\$ 233.04
PANEL SUB-ASSY, REAR DOOR, LH <i>dent</i>	1	\$ 1,776.09	\$ 1,776.09
REAR DOOR HINGE UPPER NH	1	\$ 116.17	\$ 116.17
REAR DOOR HINGE LOWER NH	1	\$ 116.17	\$ 116.17
REAR DOOR CHECK NH	1	\$ 215.96	\$ 215.96
REAR DOOR TRIMBOARD NH	1	\$ 1,023.34	\$ 1,023.34
MOTOR, POWER WINDOW REGULATOR FRT, LH NH	1	\$ 1,329.35	\$ 1,329.35
REGULATOR, FRONT DOOR WINDOW REAR, LH NH	1	\$ 322.39	\$ 322.39
REAR DOOR OUTER HANDLE <i>cut</i>	1	\$ 131.27	\$ 131.27
REAR DOOR OUTER MOULDING <i>svg</i>	1	\$ 181.52	\$ 181.52
PANEL SUB-ASSY, FRONT DOOR, LH <i>dent</i>	1	\$ 1,784.14	\$ 1,784.14
FRONT DOOR OUTER HANDLE (LH) <i>cut</i>	1	\$ 534.82	\$ 534.82
REGULATOR, FRONT DOOR WINDOW FRT, LH NH	1	\$ 322.39	\$ 322.39
MIRROR ASSY, OUTER REAR VIEW, LH <i>broken</i>	1	\$ 2,440.06	\$ 2,440.06
MOULDING, REAR DOOR WINDOW, FRONT LH <i>svg</i>	1	\$ 97.68	\$ 97.68
Rocker Panel Outer Garnish <i>broken cut</i>	1	\$ 813.02	\$ 813.02
Rocker Panel Outer NH	1	\$ 733.70	\$ 733.70
REAR TYRE (LH) <i>town 60% depreciation SN</i>	1	\$ 304.88	\$ 304.88
REAR TYRE RIM (LH) <i>distort</i>	1	\$ 2,194.88	\$ 2,194.88
REAR WHEEL HUB CAP (LH) <i>cut</i>	1	\$ 250.82	\$ 250.82

REAR WHEEL BEARING & HUB assy <i>Dom</i>	1	\$ 861.30	\$ 861.30	✓
REAR CROSS MEMBER <i>5t</i>	1	\$ 3,105.86	\$ 3,105.86	✓
REAR SHOCK ABSORBER <i>distan</i>	1	\$ 166.98	\$ 166.98	✓
REAR SHOCK ABSORBER MOUNTING <i>NH</i>	1	\$ 176.86	\$ 176.86	X
REAR LOWER ARM <i>distan</i>	1	\$ 702.22	\$ 702.22	✓
REAR UPPER ARM <i>distan</i>	1	\$ 503.62	\$ 503.62	✓
REAR KNUCKLE ARM <i>distan</i>	1	\$ 1,144.16	\$ 1,144.16	✓
REAR COIL SPRING <i>NH</i>	1	\$ 270.16	\$ 270.16	X
REAR COIL SPRING MOUNTING <i>NH</i>	1	\$ 177.43	\$ 177.43	X
REAR BRAKE ABS SENSOR (WIRE) <i>NH</i>	1	\$ 393.53	\$ 393.53	X
REAR STABILIZER BAR <i>NH</i>	1	\$ 439.68	\$ 439.68	X
REAR STABILIZER LINK <i>NH</i>	1	\$ 213.98	\$ 213.98	X
REAR TRAILING ARM <i>distan</i>	1	\$ 443.49	\$ 443.49	✓
REAR ASSIST ARM <i>distan</i>	1	\$ 483.02	\$ 483.02	✓
REAR HEIGHT SENSOR LH only <i>Dom/5t</i>	1	\$ 1,114.10	\$ 1,114.10	✓
REAR BRAKE CALIPER <i>NH</i>	1	\$ 1,189.75	\$ 1,189.75	X
FRONT BUMPER COVER <i>distan</i>	1	\$ 705.61	\$ 705.61	✓
FRONT BUMPER CLIPS <i>Hec</i>	1	\$ 31.05	\$ 31.05	✓
FRONT BUMPER SIDE RETAINER <i>NH</i>	1	\$ 108.69	\$ 108.69	X
FENDER SUB-ASSY, FRONT LH <i>Dom/5t</i>	1	\$ 1,334.29	\$ 1,334.29	✓
FRONT FENDER SHIELD <i>SVC</i>	1	\$ 280.18	\$ 280.18	X
FRONT FENDER SHIELD CLIP <i>NH</i>	1	\$ 21.03	\$ 21.03	X
FRONT FENDER HYBRID EMBLEM, LH <i>Hec</i>	1	\$ 122.09	\$ 122.09	✓
FRONT WHEEL RIM <i>distan</i>	1	\$ 2,216.83	\$ 2,216.83	✓
FRONT WHEEL HUB CAP <i>CW</i>	1	\$ 248.14	\$ 248.14	✓
FRONT WHEEL HUB BEARING <i>Dom</i>	1	\$ 790.36	\$ 790.36	✓
FRONT SUSPENSION LOWER ARM (LH) <i>distan</i>	1	\$ 891.93	\$ 891.93	✓
FRONT SHOCK ABSORBER (LH) <i>NH</i>	1	\$ 562.06	\$ 562.06	X
ABSORBER TOP MOUNTING <i>NH</i>	1	\$ 276.94	\$ 276.94	X
FRONT DRIVE SHAFT (LH) <i>NH</i>	1	\$ 2,489.89	\$ 2,489.89	X
RACK & PINION ASSY <i>NH</i>	1	\$ 2,288.46	\$ 2,288.46	X
BAR, STABILIZER <i>NH</i>	1	\$ 497.41	\$ 497.41	X
LINK ASSY, FRONT STABILIZER, LH <i>NH</i>	1	\$ 277.78	\$ 277.78	X
KNUCKLE, STEERING, LH <i>distan</i>	1	\$ 819.80	\$ 819.80	✓
JOINT ASSY, LOWER BALL, FRONT (LH) <i>NH</i>	1	\$ 282.27	\$ 282.27	X
DISC, FRONT <i>NH</i>	1	\$ 593.78	\$ 593.78	X
END SUB-ASSY, TIE ROD, LH <i>NH</i>	1	\$ 224.85	\$ 224.85	X
SENSOR, SPEED, FRONT LH <i>NH</i>	1	\$ 630.23	\$ 630.23	X
		\$ -	\$ -	
SUB TOTAL			\$ 53,385.53	
LESS 20% <i>25%</i>			\$ 10,677.11	
DISCOUNTED TOTAL			\$ 42,708.42	
REAR BUMPER REVERSE SENSOR <i>NH</i> SN	1	\$ 191.54	\$ 191.54	X
REAR DOOR COMFORT & APPS STICKER <i>Hec</i> SN	1	\$ 112.92	\$ 112.92	✓
FRONT DOOR COMFORT LOGO <i>Hec</i> SN	1	\$ 105.86	\$ 105.86	✓
FRONT TYRE (LH) <i>NH</i> SN	1	\$ 304.88	\$ 304.88	X
SUB TOTAL			\$ 715.21	
Labour Charge				
Panel Beating	1	\$1,600.00	\$ 1,600.00	1060/-

Spray Painting Charge	1	\$1,400.00	\$ 1,400.00
Wiring Charge	1	\$180.00	\$ 180.00
Tuff Kote	1	\$160.00	\$ 160.00
Towing Charge	1	\$80.00	\$ 80.00
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$ 150.00
Remove/Refix Undercarriage (RR)	1	\$400.00	\$ 400.00
Transfer of Door Mechanism FRONT	1	\$80.00	\$ 80.00
Re-set Frt Power Window System	1	\$200.00	\$ 200.00
Transfer of Door Mechanism REAR	1	\$80.00	\$ 80.00
Re-set Rear Power Window System	1	\$200.00	\$ 200.00
Four Wheel Alignment	1	\$120.00	\$ 120.00
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$ 400.00
Front Chassis Alignment Charge	1	\$220.00	\$ 220.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$ 550.00
TOTAL LABOUR			\$ 5,820.00
ESTIMATE TOTAL			\$ 49,243.63

1000/-
30/-
40/-
44
80/-
150/-
60/-
44
60/-
44
60/-
150/-
44
280/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

29/07/2020 @ 1700hrs

Not Arrived 11 days.
Part by Part.

Tyler

2KK Auto

Photo after repair
with damaged
parts.

Check part prices.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 4-Aug-20

INSURANCE: EQ

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHD 6528P (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
LOCK ASSY FUEL LID <i>Dem</i>	1	\$496.00	\$ 496.00
SUB TOTAL			\$496.00
LESS 20%			\$99.20
DISCOUNTED TOTAL			\$396.80
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Singh
2KK Auto
[Signature]