

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jul 2020 Edit Reg		29 Jul 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ANG XIAOTING , ID: S8200647H									
Main Claimant: SBS TRANSIT LTD									
Vehicle Reg. No.: SMB8005U		Date of Loss: 25/07/2020 13:00 - :59 [62 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 3794053682SG		Policy/Cover Note No.: 1900010125 (Comprehensive) Coverage: 27/12/2018 - 26/12/2020							
Vehicle Reg. No. (Insured): SMG6540C		Policy No. (Claimant): D-20095429MFBP							
		Excess:							
Repairer: SBS Transit Ltd (YCK) 3 Yio Chu Kang Crescent, 786010 Yio Chu Kang - Tel: 63754173									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Joanne] Joanne-LF.yong@aig.com									
Claimant's Insurer: MS First Capital Insurance Ltd (HQ) - Tel: 62222311									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 11/08/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
AIG_SG (30/07/2020): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMB8005U (3794053682SG)**
[SMG6540C]

TP

SBS TRANSIT LTD
Jul 25 2020 1:00PM
[ANG XIAOTING]
SBS Transit Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/08/20 23:46	Chassis Number	 Load JPG	
2	03/08/20 23:46	Odometer Reading	 Load JPG	
3	03/08/20 23:46	General View	 Load JPG	
4	03/08/20 23:46	General View	 Load JPG	
5	03/08/20 23:46	General View	 Load JPG	
6	03/08/20 23:46	General View	 Load JPG	
7	03/08/20 23:46	General View	 Load JPG	
8	03/08/20 23:46	General View	 Load JPG	
9	03/08/20 23:46	General View	 Load JPG	
10	03/08/20 23:46	General View	 Load JPG	
11	03/08/20 23:46	General View	 Load JPG	
12	03/08/20 23:46	General View	 Load JPG	
13	03/08/20 23:46	General View	 Load JPG	
14	03/08/20 23:46	General View	 Load JPG	
15	03/08/20 23:46	General View	 Load JPG	
16	03/08/20 23:46	General View	 Load JPG	
17	03/08/20 23:46	General View	 Load JPG	
18	03/08/20 23:46	General View	 Load JPG	
19	03/08/20 23:46	General View	 Load JPG	
20	03/08/20 23:46	General View	 Load JPG	
21	03/08/20 23:46	General View	 Load JPG	
22	03/08/20 23:46	General View	 Load JPG	
23	03/08/20 23:46	General View	 Load JPG	
24	03/08/20 23:46	General View	 Load JPG	
25	03/08/20 23:46	General View	 Load JPG	
26	03/08/20 23:46	General View	 Load JPG	
27	03/08/20 23:46	General View	 Load JPG	
28	03/08/20 23:46	General View	 Load JPG	
29	03/08/20 23:46	General View	 Load JPG	
30	03/08/20 23:46	General View	 Load JPG	
31	03/08/20 23:46	General View	 Load JPG	
32	03/08/20 23:46	General View	 Load JPG	
33	03/08/20 23:46	General View	 Load JPG	
34	03/08/20 23:46	General View	 Load JPG	
35	03/08/20 23:46	General View	 Load JPG	
36	03/08/20 23:46	General View	 Load JPG	
37	03/08/20 23:46	General View	 Load JPG	
38	03/08/20 23:46	General View	 Load JPG	
39	03/08/20 23:46	General View	 Load JPG	
40	03/08/20 23:46	General View	 Load JPG	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	03/08/20 23:46	General View	Load JPG	☒
42	03/08/20 23:46	General View	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/07/20 14:55	ACKNOWLEDGEMENT EMAIL TO AIG DD 29.07.2020	Load PDF	
2	29/07/20 14:55	EMAIL FROM AIG DD 29.07.2020	Load PDF	
3	03/08/20 08:53	TP GIA REPORT	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/07/20 17:12	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20007822/QKA3S2**Date:** 08/10/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900010125
Claimant Vehicle No :	SMB8005U	Insured Vehicle No :	SMG6540C
Date of Loss:	25/07/2020	Nature of Claim:	TP
		Claim No:	3794053682SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB8005U	Engine No:	50338151553815
Make & Model:	MAN NG363F (A24), 10.5 D (A)	Chassis No:	WMAA24ZZ2E7002230
Reg. Date:	29/04/2015 (Man. Year: 2014)	Odometer:	297048 km
Colour:	Green		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6/6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	29/07/2020		
Date Inspected:	29/07/2020	Inspected At:	SBS Transit Ltd (YCK) 3 Yio Chu Kang Crescent Singapore 786010
Estimated Period of Repair:	5.0 days		

Adjuster: OI SUN PIN**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Crushed	0.00 F	*- F
2	1		*FRT BUMPER LOWER CENTER	Crushed	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	Bent	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT LOWER	Bent	0.00 F	*- F
5	1		*FRT PANEL BONNET	Crushed	0.00 F	*- F
6	1		*FRT PANEL EMBLEM	Necessary	0.00 F	*- F
7	1		*FRT SIGNAL LAMP LH	Crushed	0.00 F	*- F
8	1		*FRT LH HEADLAMP ASSY	Crushed	0.00 F	*- F
9	1		*FRT WIPER ARM	Scratched	0.00 F	*- F
10	1		*FRONT LH DOOR BRACKET	Crushed	0.00 F	*- F
11	1		*FRONT LH DOOR RUBBER	Cut	0.00 F	*- F
					Total Parts (S\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >