



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

CTP Insured's Veh No : GBD9341L
Date of Accident : 29 July 2020

not Authorized
29/7/20

2/s # 4500

Mr Ho Chun Kwong

Date : 29 July 2020

12 day
Zhanghua Alu repair

Estimate To Repair SGN5973C - Toyota COROLLAALTIS 1.6 AUTO
Chassis No : MR053ZEC107133837

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bootlid <i>3odg</i>	\$ 840.00
02	1 pc	bootlid centre logo badge <i>neu</i>	\$ 38.50
03	1 pc	bootlid corolla badge <i>neu</i>	\$ 48.00
04	1 pc	bootlid altis badge <i>neu</i>	\$ 39.80
05	1 pc	bootlid 1.6 badge <i>neu</i>	\$ 37.50
06	1 pc	bootlid LX badge <i>NF</i>	\$ 39.80
07	1 pc	bootlid lock top <i>11</i>	\$ 102.80
08	1 pc	bootlid lock latch bottom <i>11</i>	\$ 48.00
09	1 pc	bootlid weatherstrip <i>1m</i>	\$ 175.00
10	4 pc	bootlid rubber stopper @ \$8.10 <i>11</i>	\$ 32.40
11	3 ps	bootlid inner trim clip @ \$5.00 <i>11</i>	\$ 15.00
12	1 pc	rear end panel <i>n</i>	\$ 552.80
13	1 pc	rear end panel inner trim <i>11</i>	\$ 198.50
14	1 pc	rear bumper <i>Dis</i>	\$ 499.00
15	2 ps	rear bumper bracket @ \$45.00 <i>11</i>	\$ 90.00
16	1 pc	rear bumper absorber foam <i>11</i>	\$ 99.90
17	2 ps	rear bumper side retainer @ \$28.00 <i>Self</i>	\$ 56.00
18	8 ps	rear bumper fastener clip @ \$3.80 <i>neu</i>	\$ 30.40
19	2 ps	rear bumper reflector @ \$75.00 <i>NF</i>	\$ 150.00
20	2 ps	rear bumper side holder @ \$5.00 <i>11</i>	\$ 10.00
21	2 ps	rear lamp @ \$435.00 <i>0/s crn 285.10</i>	\$ 870.00
22	2 ps	rear lamp lower bracket @ \$45.00 <i>11</i>	\$ 90.00
23	4 ps	rear lamp lower clip holder @ \$5.00 <i>11</i>	\$ 20.00
24	1 pc	n/s rear door <i>3odg</i>	\$ 925.00
25	1 pc	n/s rear door weatherstrip <i>neu</i>	\$ 178.00
26	1 pc	n/s rear door power window motor <i>JM</i>	\$ 509.10
27	1 pc	n/s rear door regulator <i>Self</i>	\$ 225.80
28	1 pc	n/s rear door outer weatherstrip chrome moulding <i>Self</i>	\$ 125.00
29	1 pc	n/s rear door inner trimboard <i>waped</i>	\$ 715.30
30	1 pc	n/s rear door 1/4 glass pillar <i>11</i>	\$ 165.80
31	1 pc	n/s rear door 1/4 glass weatherstrip <i>11</i>	\$ 115.80
32	1 pc	n/s rear door window frame black tape <i>NF</i>	\$ 95.80
33	1 pc	n/s rear door window frame garnish <i>11</i>	\$ 99.80
34	1 pc	n/s rear door inner lock <i>JM</i>	\$ 480.80
35	1 pc	n/s rear door inner lock latch <i>11</i>	\$ 85.00
36	1 pc	n/s rear door hinge top <i>11</i>	\$ 85.00
37	1 pc	n/s rear door hinge bottom <i>11</i>	\$ 85.00
38	1 pc	n/s rear door checker/arrestor <i>11</i>	\$ 139.80
39	1 pc	n/s rear door window glass channel weatherstrip <i>11</i>	\$ 158.00

5/28.3



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

CTP Insured's Veh No : GBD9341L

Date of Accident : 29 July 2020

Mr Ho Chun Kwong

Date : 29 July 2020

Estimate To Repair SGN5973C - Toyota COROLLAALTIS 1.6 AUTO

Chassis No : MR053ZEC107133837

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
40	1 pc	n/s rear door glass <i>shedded</i>	\$ 350.00 ✓
41	1 pc	n/s rear wheel bearing with hub <i>17</i>	\$ 675.80 ✓
42	1 pc	n/s rear axle <i>R</i>	\$ 650.00 X
43	1 pc	n/s rear shock absorber <i>17</i>	\$ 221.50 X
44	2 ps	rear fender @ \$850.00 <i>n/s bodywork ok</i>	\$ 1,700.00 1/2 ✓
45	1 pc	n/s rear fender inner trimboard <i>17</i>	\$ 280.00 X
46	1 pc	n/s rear fender wheel house panel <i>R</i>	\$ 650.00 X
47	1 pc	n/s rocker panel <i>bodywork</i>	\$ 550.00 ✓
48	1 pc	n/s rocker panel garnish <i>17</i>	\$ 125.00 X
			\$ 13,474.70 <i>69583</i>
		Less 25 %	\$ 3,368.68
			\$ 10,106.03
<u>SPECIAL NETT ITEMS</u>			
49	1 pc	rear license plate <i>17</i>	\$ 60.00 X
50	1 set	rear bumper reverse sensor <i>17</i>	\$ 320.00 X
51	1 pc	n/s rear wheel rim <i>one</i>	\$ 350.00 ✓
52	1 pc	n/s rear wheel tyre <i>put</i>	\$ 180.00 <i>(102 90)</i>
53	1 pc	rear windscreen glass sealant <i>net</i>	\$ 150.00 <i>40</i>
54	1 pc	rear windscreen glass inner sponge seal <i>net</i>	\$ 100.00 <i>30</i>
			\$ 1,160.00 <i>510</i>
<u>LABOUR & MISC. CHARGES</u>			
01		Towing charges.	\$ 150.00 <i>100</i>
02		To rust-proofing of the affected areas.	\$ 220.00 <i>100</i>
03		To check steering geometry and computer wheel alignment.	\$ 80.00 <i>380</i>
04		To transfer of n/s rear tyre, rim and on wheel balancing.	\$ 30.00 ✓
05		To remove and refit rear windscreen glass.	\$ 120.00 ✓
06		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 60.00 ✓
07		To check electrical lighting concerned.	\$ 60.00 <i>20</i>
08		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 250.00 <i>220</i>
09		To reinstall of rear bumper parking sensor.	\$ 80.00 <i>40</i>
10		To transfer of n/s rear door fittings and perform water seepage test.	\$ 80.00 <i>60</i>
11		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,600.00 <i>1500</i>



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

CTP Insured's Veh No : GBD9341L
Date of Accident : 29 July 2020

Mr Ho Chun Kwong

Date : 29 July 2020

Estimate To Repair SGN5973C - Toyota COROLLA ALTIS 1.6 AUTO
Chassis No : MR053ZEC107133837

S/No	Quantity	Description	Amount
12		LABOUR & MISC. CHARGES Putty and spray painting of the affected portion.	\$ 1,300.00 \$ 4,030.00
		Total	\$ 15,296.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1200

L 3500
S.N 510
P-5718.72