



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005728
INV Date 19/08/2020
Reference CC4/FCI20007824/Kds3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLU 5007X
Insured Veh. SHA 2636C
Claim No. D20002977MFSH
Policy No. D-20094922MFSH
Accident Date 23/07/2020
Inspection Date 11/08/2020

Description	Total
Survey Inspection	214.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	214.00
GST (7%)	14.98
Grand Total	228.98

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20007824/Kds3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-08-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2636C	Veh. Inspected	SLU 5007X	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20002977MFSH	Excess (\$)	0.00	
Assign From	HENG DING CHAO	Assign Date	29/07/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES E220D (A)	c.c	1950	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDD2132042A177693	Colour	METALLIC BLUE	
Odometer	52524	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	PIRELLI	8 mm	
L/H Front Tyre	245/45 R18	PIRELLI	8 mm	
R/H Rear Tyre	245/45 R18	PIRELLI	8 mm	
L/H Rear Tyre	245/45 R18	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/07/2020	Inspection Date	11/08/2020	
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 5007X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO REPAIR & SPRAY RIM.	NOT NECESSARY	120.00	-
	TO REPAIR,PANEL BEAT ON RIGHT REAR FENDER & AFFECTED DOOR IN ORDER TO FACILITATE RESPRAY JOB.		400.00	300.00
	TO PUTTY,PRIMER & SPRAY PAINT ON RIFGT FRT DOOR,REAR DOOR,REAR FENDER & REAR BUMPER USING 2K PAINT.		1,100.00	660.00
			1,620.00	960.00
GRAND TOTAL			1,620.00	960.00

RECOMMENDED COST OF REPAIRS			960.00
------------------------------------	--	--	---------------

Report Ref No. CC4/FCI20007824/Kds3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 5007X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 5007X

RE-INSPECTION

