

**Adjustment On Repair Costs And Replacement Of Parts:**

| S/No | Qty  | Descriptions                             | Assessed Condition | Estimate by Workshop (\$) | Revised Amount (\$) |
|------|------|------------------------------------------|--------------------|---------------------------|---------------------|
|      |      | <u>PARTS REPLACEMENT – LIST ITEMS</u>    |                    |                           |                     |
| 1    | 1pc  | Front bumper                             | Dented/Torn        | 1,318.07                  | 1,318.07            |
| 2    | 1pc  | Front bumper lower grille                | Serviceable        | 147.66                    | -                   |
| 3    | 1pc  | Front bumper grille RH                   | Deformed           | 61.27                     | 61.27               |
| 4    | 1pc  | Front bumper grille LH                   | Deformed           | 61.27                     | 61.27               |
| 5    | 1pc  | Front bumper emblem (logo)               | Necessary          | 67.08                     | 67.08               |
| 6    | 1pc  | Front bumper reinforcement               | Repair             | 396.60                    | -                   |
| 7    | 1pc  | Front bumper top seal                    | Necessary          | 24.28                     | 24.28               |
| 8    | 1pc  | Front bumper under cover                 | Serviceable        | 283.45                    | -                   |
| 9    | 6pcs | Front parking sensor @ \$314.20          | 4pcs Damaged       | 1,885.20                  | 1,256.80            |
| 10   | 4pcs | Front parking sensor seal @ \$6.29       | Necessary          | 25.16                     | 25.16               |
| 11   | 1pc  | Front grille                             | Broken             | 844.38                    | 844.38              |
| 12   | 1pc  | Front grille emblem                      | Broken             | 406.32                    | 406.32              |
| 13   | 1pc  | Front impact sensor                      | Damaged            | 1,238.78                  | 1,238.78            |
| 14   | 2pcs | Headlamp @ \$976.52                      | N/S Grazed         | 1,953.04                  | 976.52              |
| 15   | 1pc  | Tailgate                                 | Dented/Warped      | 1,976.23                  | 1,976.23            |
| 16   | 1pc  | Tailgate emblem (logo)                   | Necessary          | 52.38                     | 52.38               |
| 17   | 1pc  | Tailgate emblem (A200)                   | Necessary          | 84.48                     | 84.48               |
| 18   | 1pc  | Tailgate emblem (C&C)                    | Necessary          | 62.10                     | 62.10               |
| 19   | 1pc  | Tailgate glass moulding C/W glass        | Necessary          | 601.25                    | 601.25              |
| 20   | 1pc  | Tailgate lock                            | Serviceable        | 200.03                    | -                   |
| 21   | 1pc  | Tailgate weatherstrip                    | Distorted          | 193.78                    | 193.78              |
| 22   | 1pc  | Rear bumper                              | Dented/Broken      | 1,698.00                  | 1,698.00            |
| 23   | 1pc  | Rear bumper lower lid                    | Grazed/Deformed    | 302.36                    | 302.36              |
| 24   | 1pc  | Rear bumper center guide                 | Broken             | 101.98                    | 101.98              |
| 25   | 1pc  | Rear bumper reinforcement                | Dented/Bent        | 497.20                    | 497.20              |
| 26   | 2pcs | Rear bumper side guide @ \$53.62         | Broken             | 107.24                    | 107.24              |
| 27   | 4pcs | Rear bumper parking sensor @ \$314.20    | Damaged            | 1,256.80                  | 1,256.80            |
| 28   | 4pcs | Rear bumper parking sensor seal @ \$6.29 | Necessary          | 25.16                     | 25.16               |
| 29   | 1pc  | Rear end panel                           | Repair             | 967.46                    | -                   |
|      |      |                                          |                    | 16,839.01                 | 13,238.89           |
|      |      | Less 10%                                 |                    | (1,683.90)                | (1,323.88)          |
|      |      | Sub total                                |                    | 15,155.11                 | 11,915.01           |