

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 May 2019 Edit Reg		03 May 2019 00:00 Edit Adj Rpt	S\$3,700.00 Edit Estimates	S\$3,700.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BLUE STAR CONCIERGE PTE LTD , Co. Reg. No.: 201506692D		
Main Claimant:	JAG LIMO SERVICE'S , Co. Reg. No.: -		
Vehicle Reg. No.:	SLN8523P	Date of Loss:	30/04/2019 00:00 - :59 [23 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9000689932SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SKV6596L	Policy No. (Claimant):	A29085546MCX
		Excess:	
Repairer:	Supreme Auto Service Pte Ltd (HQ) 176 Sin Ming Drive #02-01, Sin Ming Autocare, 575721 Sin Ming - Tel: 6452 0715		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 02/09/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (31/08/2020): **Report Send Back Alerts - SLN8523P (TP)**
- AIG_SG (08/05/2019): **Request To Upload TP GIA Report**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*SLN8523P (9000689932SG)
[SKV6596L]
TP
JAG LIMO SERVICE'S
Apr 30 2019 12:00AM
[BLUE STAR CONCIERGE PTE LTD]
Supreme Auto Service Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼
------------------	---------------	--------------------	--------------	--------------	---

Letters/Correspondences					1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit		

Photos/Images					3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	04/05/20 14:00	General View		Load JPG	☒	
2	04/05/20 14:00	General View		Load JPG	☒	
3	04/05/20 14:00	General View		Load JPG	☒	
4	04/05/20 14:00	General View		Load JPG	☒	
5	04/05/20 14:00	General View		Load JPG	☒	
6	04/05/20 14:00	General View		Load JPG	☒	
7	04/05/20 14:00	General View		Load JPG	☒	
8	04/05/20 14:00	General View		Load JPG	☒	
9	04/05/20 14:00	General View		Load JPG	☒	
10	04/05/20 14:00	General View		Load JPG	☒	
11	04/05/20 14:00	General View		Load JPG	☒	
12	04/05/20 14:00	General View		Load JPG	☒	
13	04/05/20 14:00	Odometer Reading		Load JPG	☒	
14	04/05/20 14:00	General View		Load JPG	☒	
15	04/05/20 14:00	Chassis Number		Load JPG	☒	
16	04/05/20 14:00	General View		Load JPG	☒	

Documentation					1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	07/05/19 16:24	EMAIL FROM AIG DD 03052019		Load PDF		
2	07/05/19 16:24	WKSP NOTICE		Load PDF		
3	08/05/19 10:15	TP ESTIMATE- MARKED		Load PDF		
4	09/05/19 10:27	TP GIA REPORT		Load PDF		
5	22/05/19 17:13	EMAIL TO OI		Load PDF		
6	04/05/20 14:09	EMAIL TO AIG DD 040520		Load PDF		
7	16/10/20 11:35	INVOICE NO DATED 13.05.2020		Load PDF		
8	16/10/20 11:43	Authorisation to Act		Load PDF		
9	16/10/20 11:43	LOD		Load PDF		
10	16/10/20 11:43	LTA SEARCH		Load PDF		
11	16/10/20 11:43	Release Voucher		Load PDF		
12	16/10/20 11:43	WORKSHOP INVOICE		Load PDF		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	08/05/19 11:07	OI GIA report		Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKV6596L (Insd veh)	Model:	OPEL ASTRA ST 999CC (A)
	SLN8523P (TP veh)		
Date of Accident:	30/04/2019		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				9,575.00
Final Repair Cost	:	\$				3,700.00
Loss of Use	:	\$				250.00
						5.00 days at \$50.00 per day
Rental (if any)	:	\$				days
LTA / GIA Search Fee	:	\$				7.49
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				3,957.49

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Supreme Auto Service Pte Ltd	: \$	3,957.49
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

16 Oct
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19008010/KEA3S2-1**Date:** 16/10/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLN8523P**Insured Vehicle No :** SKV6596L

Date of Loss: 30/04/2019

Nature of Claim: TP

Claim No: 9000689932SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLN8523P**

Make & Model: OPEL ASTRA ST, 999cc (A)

Engine No: B1163497HRXX0024

Reg. Date: 19/05/2017 (Man. Year: 2017)

Chassis No: W0LBE8EA9H8046691

Colour: Metallic Black

Odometer: 160411 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 3 mm

Rear Left Side: Bridgestone 2 mm

Front Right Side: Bridgestone 3 mm

Rear Right Side: Bridgestone 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,030.00	4,198.50	3,831.50	47.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,545.00	1,060.00	485.00	31.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,575.00	5,258.50	4,316.50	45.08
Approved Total (Overridden) (\$\$)		3,700.00		
Nett Amount (\$\$)	9,575.00	3,700.00	5,875.00	61.36
+ Loss of Use (5.0 x S\$50.00/day) (\$\$)		250.00		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		3,957.49		

INSPECTION

Date of Assignment: 03/05/2019

Date Inspected: 06/05/2019 Inspected At:

Supreme Auto Service Pte Ltd (HQ)
176 Sin Ming Drive #02-01, Sin Ming Autocare
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	1,680.00 F	*1,500.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	780.00 F	*- FL
3	1		*FRONT BUMPER SPONGE	Serviceable	495.00 F	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Serviceable	178.00 F	*- FL
5	1		*FRONT FENDER DUST COVER	Cracked	289.00 F	*289.00 FL
6	1		*FOG LAMP	Serviceable	368.00 F	*- FL
7	1		*FOG LAMP COVER	Serviceable	96.00 F	*- FL
8	1		*HEAD LAMP	Cut	970.00 F	*820.00 FL
9	1		*FRONT GRILLE	Serviceable	408.00 F	*- FL
10	1		*FRONT SHOCK ABSORBER	Bent	465.00 F	*465.00 FL
11	1		*FRONT LOWER ARM	Distorted	386.00 F	*386.00 FL
12	1		*FRONT KNUCKLE ARM	Bent	397.00 F	*397.00 FL
13	1		*FRONT WHEEL BEARING	Necessary	288.00 F	*288.00 FL
14	1		*ALLOY RIM	Dented / Scratched	580.00 F	*520.00 FL
15	2		*PARKING SENSOR	Serviceable	650.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,030.00	4,665.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	466.50
Total Parts (S\$)	8,030.00	4,198.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE ALL PARTS MENTIONED ABOVE, PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS.	New	500.00	350.00
2	TO CHECK WIRING SYSTEM.	New	50.00	20.00
3	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS.	New	600.00	400.00
4	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE TO REPAIR.	New	150.00	140.00
5	TO REPLACE ALLOY RIM AND PERFORM WHEEL BALANCING.	New	60.00	20.00
6	TO MACHINE PRESS WHEELS BEARING.	New	40.00	20.00
7	TO PERFORM 4 WHEELS COMOUTERISED ALIGNMENT.	New	85.00	60.00
8	TO INSTALL PARKING SENSORS.	New	60.00	50.00
Gross Labour Cost (\$\$)			1,545.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >