

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:201004495R RCB NO:201004495R

M/S : AIG INSURANCE**Estimate No : M001683****Date: : 29/07/2020****Veh Reg No : SLR4523U****Make/Model : MAZDA3****ATTN : Motor Claim Department****Chassis No : JM6BN22A8H0162240****Your Ref No: : SLR4523U****Engine No: P520454474****Claim Type : THIRD PARTY****Reg. Date : 16/08/2017****Accident Date : 24/07/2020****Estimate Repair Cost to Vehicle No : SLR4523U****PAGE:3/3**

S/N	Description	Quantity	Unit	Price	Amount
	<u>SPECIAL NETT</u>			<u>S\$</u>	<u>S\$</u>
51	Rear Windscreen Gum	1	PCS	80.00	80.00 40
52	Rear Bumper Sensor	1	PCS	300.00	300.00 200
53	Front Number Plate	1	PCS	50.00	50.00 40
TOTAL				430.00	430.00
	<u>LABOUR CHARGES</u>			<u>S\$</u>	<u>S\$</u>
45	Towing				na 50.00 X
46	Check Wiring				80.00 30
47	Rust Proofing				80.00 ✓
48	To Remove & Refit Rear WindScreen				160.00 120
49	To Remove & Replace Bumper Sensor				80.00 50
50	To Remove & Replace Exhaust				80.00 60
51	To Remove & Refit rear Seat and Upholstery				160.00 80
52	To Spray Painting				1100.00 ✓
53	Panel Beating				2200.00 1800
TOTAL					3990.00

OVERALL TOTAL	15668.56
----------------------	-----------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR FOCUS AUTO PTE LTD**AUTHORISE SIGNATURE**

2-10862
 20%
 9-8689.60
 S.V. 280.00
 L-3320.00
 12289.60
 20%
 9831.68