

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd
 3 Anson Road 51 Ubi Ave 1 #01-25
 #16-00 Springleaf Tower Paya Ubi Industrial Park
 Singapore 079909 Singapore 408933

Attn: Angie Foo Date: 03 Aug 2020

Preliminary Advice

Insured Vehicle No	:	11022400X		
TP Vehicle No	:	SKX6866Y	Accident Date	: 28/07/2020
Make	:	TOYOTA HARRIER	Assignment Date	: 30/07/2020
Date of Inspection	:	30/07/2020	Est. Duration of Repair	: 10
Inspection At	:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 21,480.00 (SN + LABOUR ONLY)
Revised Amount	:	S\$ 4,140.00
Check Items (Estimated)	:	S\$ 1,520.00
Total	:	S\$ 5,660.00
Lump Sum Repair		:

Total Loss Consideration

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :