

陳林摩哆私人有限公司

TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

MS FCIL Insured's Veh No : SH9180L

Date of Accident : 25 July 2020

Messrs BIS Motoring Pte Ltd

Date : 27 July 2020

Estimate To Repair SMG4227X - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : KNAHU815VJ7211460

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper <i>DIS</i>	\$ 695.00
02	1 pc	front bumper side retainer n/s <i>Barf</i>	\$ 23.00
03	1 pc	front bumper centre grille <i>11</i>	\$ 428.00
04	1 pc	front bumper lower grille <i>De</i>	\$ 159.00
05	1 pc	front bumper parking sensor - inner <i>NF</i>	\$ 162.00
06	1 pc	front bumper parking sensor holder <i>NF</i>	\$ 23.00
07	1 pc	front bumper top rubber seal <i>nu</i>	\$ 28.00
08	1 pc	radiator grille <i>11</i>	\$ 428.00
09	1 pc	front bumper reinforcement <i>11</i>	\$ 389.00
10	1 pc	front bumper foam <i>11</i>	\$ 68.00
11	2 ps	aircon condenser air guide @ \$24.00 <i>11</i>	\$ 48.00
12	1 pc	n/s headlamp <i>cu</i>	\$ 1,558.00
13	1 pc	n/s headlamp bracket <i>cu</i>	\$ 23.00
14	1 pc	front support panel top garnish <i>11</i>	\$ 58.00
15	1 pc	n/s front fender <i>Barf/Barf</i>	\$ 425.00
16	1 pc	n/s front fender inner cowling <i>to in</i>	\$ 75.00
17	6 ps	n/s front fender inner cowling clips @ \$4.50 <i>nu</i>	\$ 27.00
18	1 pc	front bumper fog lamp n/s <i>cu</i>	\$ 206.00
19	1 pc	front bumper fog lamp cover n/s <i>cu</i>	\$ 115.00
		Less 10 %	\$ 4,938.00
			\$ 493.80
		<u>SPECIAL NETT ITEMS</u>	\$ 4,444.20
20	1 pc	n/s front wheel rim <i>cu</i>	\$ 750.00
21	1 pc	n/s front wheel tyre <i>11</i>	\$ 250.00
			\$ 1,000.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of tyre, rim and on wheel balancing.	\$ 50.00
02		To check steering geometry and computer wheel alignment.	\$ 80.00
03		To rust-proofing of the affected areas.	\$ 150.00
04		To check electrical lighting concerned.	\$ 80.00
05		To reinstall of front bumper parking sensor.	\$ 80.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 550.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

MS FCIL Insured's Veh No : SH9180L
Date of Accident : 25 July 2020

Messrs BIS Motoring Pte Ltd

Date : 27 July 2020

Estimate To Repair SMG4227X - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7211460

S/No	Quantity	Description	Amount
07		<u>LABOUR & MISC. CHARGES</u>	
		Putty and spray painting of the affected portion.	\$ 750.00
			\$ 1,740.00
		Total	\$ 7,184.20
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			

400