



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:	GBH 8231 G
MAKE & MODEL:	TOYOTA HIACE
MILEAGE:	
TYRE:	
CHASSIS NUM:	

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	BONNET	X 1	\$952.00
2	BONNET LOCK	X 1	\$375.00
3	BONNET LOCK CATCH	X 1	\$102.00
4	BONNET HINGE (L+R)	X 2	NIL
5	BONNET STOPPER (L+R)	X 2	NIL
6	BONNET RUBBER STRIP	X 2	NIL
7	BONNET LOGO (TOYOTA)	X 1	\$98.00
8	FRONT SIDE PANEL (L+R)	X 2	\$984.00
9	FRONT GRILLE (TOP)	X 1	\$731.00
10	FRONT GRILLE (BOTTOM)	de X 1	\$545.00
11	HEADLAMP (L+R)	\$2722.00 LH/RH X 2	\$5761.00
12	HEADLAMP PANEL (L+R)	X 2	\$822.00
13	FRONT BUMPER	de X 1	\$995.00
14	FRONT BUMPER RETAINER (L+R)	LH/RH X 2	\$276.00
15	FRONT BUMPER BRACKET (L+R)	LH/RH X 2	NIL
16	FRONT BUMPER REINFORCEMENT BAR	bt X 1	\$749.00
17	FRONT BUMPER BEAM	X 1	NIL
18	FRONT BUMPER GRILLE	de X 1	\$581.00
19	FRONT BUMPER TOW COVER (L+R)	X 2	NIL
20	FRONT BUMPER FOG LAMP GARNISH (L+R)	\$211.00 LH/RH X 2	\$422.00
21	FRONT SUPPORT PANEL	X 1	\$1075.00
22	AIRCON BLOWER BOX	X 1	\$610.00
23	AIRCON CONDENSOR	X 1	\$1211.00
24	HIGH PRESSURE HOSE	X 1	\$479.00
25	LOW PRESSURE HOSE	X 1	\$451.00
26	RADIATOR	X 1	\$1423.00
27	RADIATOR SPARE TANK	X 1	\$181.00
28	SUCTION PIPE	X 1	\$272.00
29	DISCHARGE PIPE	X 1	\$367.00
30	RADIATOR FAN COWLING	X 1	\$812.00
31	RADIATOR FAN BLADE	X 1	\$185.00
32	RADIATOR FAN MOTOR	X 1	\$753.00
33	WIPER WASHER TANK	X 1	\$165.00
34	WIPER WASHER MOTOR	X 1	\$279.00
35	FRONT DRIVER SEAT	drunk price X 1	\$1980.00
36	FRONT DRIVER SEATBELT	X 1	\$922.00
37	REAR WINDSCREEN MOULDING	rel X 1	\$312.00
38	TAILGATE	bt X 1	\$2142.00
39	TAILGATE LOGO (TOYOTA)	rel X 1	\$97.00

40	TAILGATE EMBLEM STICKER (TOYOTA)	nee ✓	1	\$ 291.00
41	TAILGATE EMBLEM STICKER (HIACE)	nee ✓	1	\$ 105.00
42	TAILGATE HANDLE	aut ✓	1	\$ 424.00
43	TAILGATE LOCK CYLINDER	X	1	\$ 298.00
44	TAILGATE HANDLE SWITCH	X	1	\$ 315.00
45	TAILGATE CARPLATE LAMP	X	1	\$ 198.00
46	TAILGATE SWITCH	X	1	\$ 180.00
47	TAILGATE LOCK	bt ✓	1	\$ 367.00
48	TAILGATE LOCK COVER	X	1	NIL
49	TAILGATE LOCK CATCH	X	1	\$ 92.00
50	TAILGATE DAMPER (L+R)	X	2	\$ 668.00
51	TAILGATE HINGE (L+R)	X	2	\$ 310.00
52	TAILGATE WEATHERSTRIP	aut ✓	1	\$ 321.00
53	TAIL LAMP (L+R)	\$ 525.00 - LKra ✓ XRY2	2	\$ 1050.00
54	TAIL LAMP PANEL (L+R)	X	2	\$ 876.00
55	REAR BUMPER	de ✓	1	\$ 1003.00
56	REAR BUMPER RETAINER (L+R)	X	2	\$ 278.00
57	REAR BUMPER BRACKET (L+R)	X	2	\$ 624.00
58	REAR BUMPER REINFORCEMENT BAR	X	1	NIL
59	REAR SIDE BUMPER (L+R)	X	2	\$ 820.00
60	REAR SIDE BUMPER RETAINER (L+R)	X	2	\$ 282.00
61	REAR FENDER (L+R)	X	2	\$ 7892.00
62	REAR FENDER SIDE INNER TRIM (L+R)	X	2	\$ 262.00
63	REAR FENDER DOOR GUIDE (L+R)	X	2	\$ 678.00
64	REAR FENDER DOOR GUIDE END (L+R)	X	2	\$ 580.00
65	REAR FENDER AIR VENT (L+R)	X	2	\$ 284.00
66	REAR FENDER COWLING (L+R)	X	2	\$ 522.00
67	REAR FENDER MUDFLAP (L+R)	X	2	\$ 290.00
68	REAR QUARTER PANEL (L+R)	X	2	\$ 828.00
69	END PANEL	bt ✓	1	\$ 1025.00
70	END PANEL TOP GARNISH	X	1	\$ 322.00
71	FLOOR PANEL	X	1	\$ 3730.00
72	REAR SPARE TYRE BRACKET	X	1	\$ 157.00
73	EXHAUST PIPE	X	1	\$ 985.00
74	EXHAUST GASKET	X	1	\$ 110.00
75	EXHAUST BRACKET (L+R)	X	2	\$ 186.00
76	EXHAUST HEAT SHIELD	X	1	\$ 321.00
77	FRONT BUMPER SCUFF - 1577 \$ 1201		1	\$ 2291.00
78	TAIL GATE LAMP - 1577 \$ 278			
		SUBTOTAL		\$ -
		LESS 25%		\$ -
		PARTS TOTAL		\$ -
SPECIAL NETT			QTY	PRICE
1	FRONT BUMPER CLIPS	30 nee ✓	10	\$ 100.00
2	FRONT CARPLATE	30 bt ✓	1	\$ 120.00
3	FRONT CARPLATE CLIPS	X	1	\$ 120.00
4	RADIATOR COOLANT	X	1	\$ 120.00

5	REAR WINDSCREEN SEALANT		1	\$ 200.00
6	TAILGATE INNER BOARD	dash piece	1	\$ 2,000.00
7	TAILGATE INNER BOARD CLIPS		10	\$ 100.00
8	REAR TAILGATE STICKER (SPEED)		1	\$ 100.00
9	REAR TAILGATE STICKER (PAX)		1	\$ 100.00
10	TAILGATE REVERSE CAMERA	X	1	\$ 850.00
11	REAR CARPLATE	X	1	\$ 120.00
12	REAR BUMPER CLIPS		10	\$ 100.00
13	REAR BUMPER REVERSE SENSOR		2	\$ 400.00
14	REAR FENDER SEALANT	X	1	\$ 400.00
15	REAR FENDER INNER BOARD (L+R)	X	2	\$ 8,000.00
16	REAR FENDER INNER BOARD CLIPS	X	20	\$ 200.00
17	REAR FENDER COWLING CLIPS	X	20	\$ 200.00
18	REAR MUDFLAP CLIPS	X	10	\$ 100.00
19	REAR QUARTER PANEL SEALANT	X	1	\$ 160.00
20	END PANEL SEALANT		1	\$ 200.00
21	FLOOR PANEL TOP MAT	X	1	\$ 6,000.00
22	FLOOR PANEL TOP BOARD	X	1	\$ 9,500.00
23	FLOOR PANEL SEALANT	X	1	\$ 450.00
SPECIAL NETT TOTAL				\$ 26,980.00
LABOUR				QTY PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN		1	\$ 8,100.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA		1	\$ 5,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA		1	\$ 600.00
4	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	X	1	\$ 250.00
5	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	X	1	\$ 150.00
6	TO RNR FRONT DRIVER SEAT		1	\$ 800.00
7	TO RNR FRONT DRIVER SEATBELT	X	1	\$ 400.00
8	TO RNR REAR WINDSCREEN		1	\$ 400.00
9	TO RNR REAR BOOT MECHANISM		1	\$ 500.00
10	TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS		1	\$ 800.00
11	TO RNR REVERSE SENSOR & CHECK FUNCTION.		1	\$ 150.00
12	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	X	1	\$ 400.00
13	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION		1	\$ 150.00
14	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	X	1	\$ 800.00
15	TO DO WATER LEAK TEST .	X	1	\$ 120.00
16	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	X	1	\$ 250.00
17	TO RNR FUEL TANK TO ASSIST WORK LOAD	X	1	\$ 450.00
TOTAL				\$11,620.00
GRAND TOTAL COST				\$ 38,600.00



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

GBH 8231 G
TOYOTA HIACE

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT WIRE HARNESS <i>am</i> ✓	1	\$ 1872.00
2	REAR END PANEL <i>inner</i> <i>bt</i> ✓	1	\$ 1092.00
3	REAR TAILGATE BOARD <i>am</i> ✓	1	\$ 479.00
	SUBTOTAL		
	LESS 25%		
	PARTS TOTAL		
	SPECIAL NETT	QTY	PRICE
	SPECIAL NETT TOTAL		\$ -
	LABOUR	QTY	PRICE
1.	TO RNR FRANT DRIVER SENT	1.	\$ 17.20
	TOTAL		
	GRAND TOTAL COST		

~~P = 19.168.5~~

P = 19.168.5

SW 888.00

25 = 4010.80

24,066

(2)