

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

Store (LKK)

## ESTIMATE OF REPAIR

Veh# GZ713G

Model:

NISSAN  
(23/11/2005)

Accident Date : 29/7/2020

Location : BKE TOWARDS SLE

3P:

GBJ9759J (Lonpac)

30/7/20, 2-30 pm  
L/S  
By AL Ry - 12 days

| S/Nos         | Qty   | Description                                   | List \$  | S/Nett \$ | Nett \$          |
|---------------|-------|-----------------------------------------------|----------|-----------|------------------|
| 1             | 1 pc  | Rear tail gate                                | -        | -         | 1,450.00         |
| 2             | 1 pc  | Rear tail-gate aluminium cover                | -        | 800.00    | 1,600.00         |
| 3             | 50pcs | Rear tail-gate aluminium rivets               | -        | 50.00     | 30.00            |
| 4             | 1 pc  | Rear tail-gate n/s lock                       | -        | -         | 123.50           |
| 5             | 1 pc  | Rear tail-gate n/s lock lower                 | -        | -         | 203.20           |
| 6             | 2 pcs | Rear tail-gate n/s rubber stopper             | -        | 52.00     | 75.00            |
| 7             | 1 pc  | Rear tail-gate lower panel                    | -        | -         | 796.70           |
| 8             | 3 pcs | Rear tail-gate hinges pins                    | -        | 12.00     | -                |
| 9             | 1 pc  | Rear tail-gate 70KMPH emblem                  | -        | 20.00     | -                |
| 10            | 1 pc  | Rear tail-gate NISSAN emblem                  | -        | 106.50    | -                |
| 11            | 1 pc  | Rear n/s tail-lamp                            | -        | -         | 378.70           |
| 12            | 2 pcs | Rear n/s tail-lamp bracket                    | -        | -         | 163.90           |
| 13            | 1 pc  | Rear n/s stopper                              | -        | 86.20     | -                |
| 14            | 2 pcs | Rear o/s & n/s reverse sensor                 | -        | 280.00    | -                |
| 15            | 10pcs | Rear carriage bracket                         | -        | 200.00    | -                |
| 16            | 10pcs | Rear carriage screw                           | -        | 150.00    | -                |
| 17            | 10pcs | Rear carriage rubber                          | -        | 120.00    | -                |
| 18            | 1 pc  | Rear n/s side gate                            | -        | -         | 1,980.60         |
| 19            | 5 pcs | Rear n/s tail-gate hinges pin                 | -        | 20.00     | -                |
| 20            | 1 pc  | Rear n/s tail-gate aluminium cover            | -        | 600.00    | -                |
| 21            | 30pcs | Rear n/s tail-gate aluminium rivets           | -        | 30.00     | -                |
| 22            | 1 pc  | Front o/s signal lamp                         | -        | -         | 385.60           |
| 23            | 1 pc  | Front bumper                                  | -        | -         | 546.20           |
| 24            | 1 pc  | Front o/s step garnish                        | -        | -         | 213.60           |
| 25            | 1 pc  | Front o/s door sticker                        | -        | 30.00     | -                |
| Sub-Total:    |       |                                               | 0.00     | 2556.70   | 6,242.00         |
| After Less %: |       |                                               | 30%      | 0%        | 0%               |
| After Less %: |       |                                               | 0.00     | 2556.70   | 5617.80          |
| <b>Labour</b> |       |                                               |          |           |                  |
| 1             |       | To dismantle damaged, straighten and welding. | 1,200.00 | -         | 900.00           |
| 2             |       | To spray painting                             | 1,200.00 | -         | 900.00           |
| 3             |       | To re-align, remove and refit rear carriage   | 900.00   | -         | 500.00           |
| 4             |       | To check wiring.                              | 100.00   | -         | 30.00            |
| 5             |       | To re-seal anti-rust.                         | 100.00   | -         | 30.00            |
| Sub-Total:    |       |                                               |          | 3,500.00  |                  |
| <b>Total:</b> |       |                                               |          |           | <b>11,674.50</b> |

Parts

248 / 110

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

Parts - 3872.20  
- 10%  
3439.98

Nett - 943.20

Labour - 2360

= 6743.18



Supp - 192.50

6935.68

L/S - 5548.54

= 5550

Chan San Choon  
Director  
DipEng, AAE MIMI, MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

6743.18 8778 1999 Mobil 1

Acknowledged by Repairer

Signature: GZ713G ESTIMATEPg1

Date:



PAYNOW