

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 18 Aug 2020

**Preliminary Advice**

|                    |                                                                                                                   |                         |              |
|--------------------|-------------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : GBC2035Y                                                                                                        | Accident Date           | : 29/07/2020 |
| TP Vehicle No      | : SLQ1132P                                                                                                        | Assignment Date         | : 30/07/2020 |
| Make               | : BMW X1                                                                                                          | Est. Duration of Repair | : 5          |
| Date of Inspection | : 17/08/2020                                                                                                      |                         |              |
| Inspection At      | : PERFORMANCE MOTORS LIMITED (ALEXANDRA)<br>303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE<br>SINGAPORE 159941 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 16,441.51 |
| Revised Amount              | :S\$ | 7,211.00  |
| Check Items (Estimated)     | :S\$ | 6,816.81  |
| Total                       | :S\$ | 14,027.81 |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :