

SERVICE ESTIMATE

88367 - C00001

SL: SERVICE SALES - PC

Ms Tay Lin Yuan, Ivy

8 Jansen Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 17/06/2020

WIP No. . : 23050

Veh.In/Out:

*Tel.No. . : Mobile: 91866307

Reg.No. . : SLV82E

Reg.date . : 28/02/2014

Mileage . : 0

Chassis No: SAJAC05M9EPU17026

Singapore 548390

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Ms Tay Lin Yuan, Ivy

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, BUMPER BARCKETS, LHR FENDER, LHR TAILLAMP, ETC.		0	5500.00	0	5,500.00 S	3200	
800	TO PUTTY AND SPRAY PAINT ON REAR BUMPER, LHR FENDER, ETC.		0	3200.00	0	3,200.00 S	1500.00	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		0	525.00	0	525.00 S	X NN	
802	TO REMOVE AND INSTALL REAR BOOT COMPARTMENT PARTS		0	1800.00	0	1,800.00 S	X NN	
802	TO REMOVE AND INSTALL INTERIOR PARTS		0	3600.00	0	3,600.00 S	850.00	
802	TO REPLACE REAR WINDSCREEN		0	600.00	0	600.00 S	✓	
0080	TO INSTALL REAR WINDSCREEN SOLAR FILM		0	280.00	0	280.00 S	✓	
	LAMP CLUSTER LH XF S ✓ CRA	1.0	EA	1045.90		1,045.90 S	(941.31)	
	BUMPER COVER REAR XF X SVC	1.0	EA	2132.50		2,132.50 S		

Luo Qiang - 82880282

Luo Qiang @ LKK Auto. Com

04/8/2020

Before part photos.

7 Days

REPAIR LIMIT: \$14K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

88367 - C00001 SL: SERVICE SALES - PC

Ms Tay Lin Yuan, Ivy
8 Jansen Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 17/06/2020

WIP No. . : 23050

Veh.In/Out:

*Tel.No. . : Mobile: 91866307

Reg.No. . : SLV82E

Reg.date. : 28/02/2014

Mileage . : 0

Chassis No: SAJAC05M9EPU17026

Singapore 548390

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Ms Tay Lin Yuan, Ivy

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	------	-----	-------	-------	-----	--------	---

REAR VALANCE V6 S207	X	NN	1.0	EA	641.10		641.10	S
BUMPER BRACKET REAR	X	NN	1.0	EA	53.60		53.60	S
BUMPER BRACKET REAR	X	NN	1.0	EA	53.60		53.60	S
BUMPER BRACKET REAR	X	NN	1.0	EA	133.00		133.00	S
ADHESIVE SEALER FL2	X	NN	1.0	EA	703.00		703.00	S
SOUND DEADENING PAD	X	NN	1.0	EA	525.40		525.40	S
FENDER PANEL REAR LH	✓	BUC	1.0	EA	5184.20		5,184.20	S (4665.78)
WINDSCREEN REAR S207	✓	NEC	1.0	EA	1131.10		1,131.10	S (1017.99)
D WINDSCREEN SEALA	X	NN	2.0	EA	149.40		298.80	S
D PRIMER GLASS & P	✓	NEC	1.0	EA	39.30		39.30	S (35.37)
D GLASS CLEANER H	✓	NEC	1.0	EA	58.20		58.20	S (52.38)
WINDSCREEN SPACER	✓	NEC	4.0	EA	8.30		33.20	S (29.88)
SUPP: WINDSCREEN SEALANT	✓	NEC	2.0	EA	155.10		310.20	S (279.18)
SOUND DEADENING PAD	✓	NEC	1.0	EA	525.40		525.40	S (472.86)

TOTAL: \$7494.75

Gross Total. 27,537.90

Labour Total	15,505.00
Parts Total	12,032.90
Package Total	0.00

Net.....	27,537.90
GST @ 7.0%	1,927.65
Total.....	29,465.55
Paid.....	0.00
Please Pay..	29,465.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated