

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 42530

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0510/2020/NS
Date : 22-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

4 days ok - Carrine 24/11/2020

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ong Thian Hock
Address : 27 upper Serangoon View
#01-13
Singapore 534045
Telephone : (HP) +65 90905550
Type of Claim : Third Party Claim
Policy No. : 1900007600-01
Vehicle No : **SDP 5550 P**
Model Code : Q5 SPORT 2.0 TFSI QU
Model / Year : Jan-19
Engine No : DAX 050787
Chassis No : WAUZZZF9Y9K2023974
Mileage : -
Date In : -
Estimated By : Allan Wu
Accident Date : 22-Jul-20
Place of Accident : Airport Rd Towards Macpherson Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDP 5550 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	\$ 360.00
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assv.	S/N \$ 480.00	
3	To renew rear windscreen to facilitate rear lid renewal.	S/N \$ 480.00	
4	To install rear windscreen solar film.	S/N \$ 400.00	
5	To carry out water seepage test on rear windscreen.	S/N \$ 200.00	
6	To dismantle and renew rear bumper to rear lid. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,400.00	\$ 500.00
7	To respray rear bumper, rear lower bumper, rear lid and both rear wheel arch trims.	\$ 4,000.00	\$ 2,050.00
8	To renew rhs rear exhaust silencer and align to	S/N \$ 480.00	\$ 480.00
9	To apply paint coating on rear bumper.	S/N \$ 250.00	\$ 250.00
10	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 9,242.00	\$ 3,832.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDP 5550 P

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	REAR BUMPER - UPPER	\$ 1,724.00	\$ 1,379.20
2	REAR BUMPER - LOWER	\$ 1,182.00	\$ 945.60
3	REAR BUMPER SPOILER	\$ 830.00	\$ 663.60
4	REAR BUMPER TOWING EYE COVER - RH	\$ 29.00	
5	REAR BUMPER CLOSING ELEMENT - LH / RH	2 \$ 190.00	\$ 75.84
6	REAR BUMPER TRIM - RH	\$ 234.00	\$ 187.20
7	TAIL LIGHT - RH	\$ 691.00	\$ 552.80
8	BOOT LID CONTROL UNIT	\$ 399.00	
9	REAR PARKING AID SENSOR	2 TBC	
10	REAR PARKING AID SEAL RING	4 \$ 14.00	
11	REAR BUMPER WIRING SET	\$ 485.00	
12	REAR BUMPER CARRIER	\$ 911.00	
13	REAR BUMPER HOLDING STRAP	\$ 166.00	\$ 132.80
14	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 166.00	
15	REAR BUMPER FOAM FILLER PIECE - RH	\$ 62.00	
16	REAR LID	\$ 4,168.00	
17	REAR LID ATTACHMENT PARTS	\$ 120.00	
18	REAR LID FLAP GASKET	\$ 383.00	
19	REAR LID LOCK	\$ 227.00	
20	REAR LID LOCK STRIKER	\$ 85.00	
SUB TOTAL SPARE PARTS		: \$ 12,066.00	\$ 3,937.04

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDP 5550 P

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f		\$ 3,937.04
21	PACKING ADHESIVE		\$ 18.00	\$ 14.40
22	AUDI EMBLEM		\$ 122.00	\$ 97.60
23	Q5 INSCRIPTION		\$ 95.00	\$ 75.36
24	QUATTRO INSCRIPTION		\$ 95.00	\$ 75.36
25	SPOILER FIXING PARTS		\$ 32.00	
26	REAR WINDSCREEN		\$ 1,131.00	
27	PRIMER		\$ 19.00	
28	REAR SPOILER - LH / RH	2	\$ 462.00	
29	REAR SILENCER		\$ 1,344.00	\$ 1,075.20
30	REAR SILENCER DUAL CLIP		\$ 54.00	
31	REAR SILENCER BRACKET	2	\$ 113.00	
32	REAR WHEEL COVER - LH / RH	2	\$ 1,154.00	\$ 922.40
33	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
34	REAR NO PLATE	S/N	\$ 60.00	
35	SUPPLEMENTARY		\$ 1,131.00	\$ 736.00
36	SUNDRIES		\$ 300.00	\$ 141.12
TOTAL SPARE PARTS		:	\$ 18,396.00	\$ 7,074.48
TOTAL LABOUR CHARGES		:	\$ 9,242.00	\$ 3,832.00
GRAND TOTAL		:	\$ 27,638.00	\$ 10,906.48

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0510/2020/NS

Date

7-Aug-20

Service Advisor

Glory Tan

Pages

1 OF 1

Regn No

SDP 5550 P

Model No

Q5 SPORT 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
Parts			
1	Centre exhaust silencer bent	\$ 966.00	\$ 736.00
2	Dual clip nn	\$ 108.00	
3	Bracket nn	\$ 57.00	

TOTAL

\$ 1,131.00 \$ 736.00

For Premium Automobiles Pte Ltd

Authorised Signature