

Car-in 4/8/2020

WP-42530

Kiam/Hong

4 days

Reise

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6641 1183

Telefax

Material List for Accident Vehicle Regn No. SDP 5550 P

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	REAR BUMPER - UPPER <i>2</i>	\$ ✓ 1,724.00	1379.2
2	REAR BUMPER - LOWER <i>2</i>	\$ ✓ 1,182.00	945.6
3	REAR BUMPER SPOILER <i>2</i>	\$ ✓ 830.00	663.6
4	REAR BUMPER TOWING EYE COVER - RH <i>new</i>	\$ ✗ 29.00	
5	REAR BUMPER CLOSING ELEMENT - LH (RH) <i>2</i>	\$ ✓ 190.00	75.84
6	REAR BUMPER TRIM - RH	\$ ✓ 234.00	187.2
7	TAIL LIGHT - RH <i>Cracked</i>	\$ ✓ 691.00	552.8
8	BOOT LID CONTROL UNIT <i>new</i>	\$ ✗ 399.00	
9	REAR PARKING AID SENSOR <i>2</i>	✗ TBC	
10	REAR PARKING AID SEAL RING <i>4</i>	\$ ✗ 14.00	
11	REAR BUMPER WIRING SET <i>new</i>	\$ ✗ 485.00	
12	REAR BUMPER CARRIER <i>2</i> NN	\$ ✗ 911.00	
13	REAR BUMPER HOLDING STRAP <i>new</i>	\$ ✓ 166.00	132.8
14	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i> 2	\$ ✗ 166.00	
15	REAR BUMPER FOAM FILLER PIECE - RH <i>?</i> NN	\$ ✗ 62.00	
16	REAR LID <i>Repair</i>	\$ ✗ 4,168.00	
17	REAR LID ATTACHMENT PARTS <i>2</i>	\$ ✗ 120.00	
18	REAR LID FLAP GASKET	\$ ✗ 383.00	
19	REAR LID LOCK <i>new</i>	\$ ✗ 227.00	
20	REAR LID LOCK STRIKER	\$ ✗ 85.00	
SUB TOTAL SPARE PARTS		: \$ 12,066.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6041 1183

Telefax

Material List for Accident Vehicle Regn No. SDP 5550 P

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
21	PACKING ADHESIVE ? NEC	\$ 18.00	? 14.4
22	AUDI EMBLEM	\$ 122.00	✓ 97.6
23	Q5 INSCRIPTION	\$ 95.00	✓ 75.36
24	QUATTRO INSCRIPTION	\$ 95.00	✓ 75.36
25	SPOILER FIXING PARTS	\$ 32.00	✗
26	REAR WINDSCREEN	\$ 1,131.00	✗
27	PRIMER	\$ 19.00	✗
28	REAR SPOILER - LH / RH	2 \$ 462.00	✗
29	REAR SILENCER	\$ 1,344.00	✓ 1075.2
30	REAR SILENCER DUAL CLIP	\$ 54.00	✗
31	REAR SILENCER BRACKET	2 \$ 113.00	? ✗
32	REAR WHEEL COVER - LH / RH	2 \$ 1,154.00	✓ 922.4
33	REAR WINDSCREEN SEALANT	S/N \$ 200.00	✗
34	REAR NO PLATE	S/N \$ 60.00	✗
35	SUNDRIES ? NEC	\$ 300.00	? 141.12
TOTAL SPARE PARTS		:	\$ 17,265.00
TOTAL LABOUR CHARGES		:	\$ 8,992.00
GRAND TOTAL		:	\$ 26,257.00

All charges are not inclusive of GST

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett

Resurveyed
Adrian L
04/08/20 ✓ H.S.
Add 1 day for
exhaust.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDP 5550 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	✓ ✓
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00	X
3	To renew rear windscreen to facilitate rear lid renewal.	S/N \$ 480.00	X
4	To install rear windscreen solar film.	S/N \$ 400.00	X
5	To carry out water seepage test on rear windscreen.	S/N \$ 200.00	X
6	To dismantle and renew rear bumper to rear lid. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,400.00	500 ✓ 500
7	To respray rear bumper, rear lower bumper, rear lid and both rear wheel arch trims.	✓ 2050 \$ 4,000.00	550 x 3 = 1650 2050 wheel flex x 2 = 2000 x 400
8	To renew rhs rear exhaust silencer and align to position.	S/N \$ ✓ 480.00	✓ H.C.S. 04/08/20
9	To apply paint coating on rear bumper.	S/N ✓ TBC	? 250
10	To carry out diagnostic check.	S/N \$ ✓ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,992.00	