

Car-in 4/8/2020

WP-42530

Kiam/Hong

4 days

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

Perise

Material List for Accident Vehicle Regn No. SDP 5550 P

|                       |                                                  | Damage Parts & Prices |         |
|-----------------------|--------------------------------------------------|-----------------------|---------|
| S/N                   | Parts Description                                | S/NETT                | REMARKS |
| 1                     | REAR BUMPER - UPPER <i>2</i>                     | \$ 1,724.00           | ✓       |
| 2                     | REAR BUMPER - LOWER <i>2</i>                     | \$ 1,182.00           | ✓       |
| 3                     | REAR BUMPER SPOILER <i>2</i>                     | \$ 830.00             | ✓       |
| 4                     | REAR BUMPER TOWING EYE COVER - RH <i>new</i>     | \$ 29.00              | ✓       |
| 5                     | REAR BUMPER CLOSING ELEMENT - LH (RH) <i>2</i>   | \$ 190.00             | ✓       |
| 6                     | REAR BUMPER TRIM - RH <i>?</i>                   | \$ 234.00             | ?       |
| 7                     | TAIL LIGHT - RH <i>Cracked</i>                   | \$ 691.00             | ✓       |
| 8                     | BOOT LID CONTROL UNIT <i>new</i>                 | \$ 399.00             | ✓       |
| 9                     | REAR PARKING AID SENSOR <i>2</i>                 | TBC                   | ✓       |
| 10                    | REAR PARKING AID SEAL RING <i>4</i>              | \$ 14.00              | ✓       |
| 11                    | REAR BUMPER WIRING SET <i>new</i>                | \$ 485.00             | ✓       |
| 12                    | REAR BUMPER CARRIER <i>?</i>                     | \$ 911.00             | ✓       |
| 13                    | REAR BUMPER HOLDING STRAP <i>new</i>             | \$ 166.00             | ✓       |
| 14                    | REAR BUMPER GUIDE SECTION - LH / RH <i>new 2</i> | \$ 166.00             | ✓       |
| 15                    | REAR BUMPER FOAM FILLER PIECE - RH <i>?</i>      | \$ 62.00              | ✓       |
| 16                    | REAR LID <i>Repairs</i>                          | \$ 4,168.00           | ✓       |
| 17                    | REAR LID ATTACHMENT PARTS <i>2</i>               | \$ 120.00             | ✓       |
| 18                    | REAR LID FLAP GASKET                             | \$ 383.00             | ✓       |
| 19                    | REAR LID LOCK <i>new</i>                         | \$ 227.00             | ✓       |
| 20                    | REAR LID LOCK STRIKER                            | \$ 85.00              | ✓       |
| SUB TOTAL SPARE PARTS |                                                  | : \$ 12,066.00        |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6041 1183

Telefax

## Material List for Accident Vehicle Regn No. SDP 5550 P

|                      |                                | Damage Parts & Prices |         |
|----------------------|--------------------------------|-----------------------|---------|
| S/N                  | Parts Description              | S/NETT                | REMARKS |
| 21                   | PACKING ADHESIVE ?             | \$ 18.00 ?            |         |
| 22                   | AUDI EMBLEM                    | \$ 122.00 ✓           |         |
| 23                   | Q5 INSCRIPTION } New           | \$ 95.00 ✓            |         |
| 24                   | QUATTRO INSCRIPTION            | \$ 95.00 ✓            |         |
| 25                   | SPOILER FIXING PARTS New       | \$ 32.00 ✓            |         |
| 26                   | REAR WINDSCREEN } New          | \$ 1,131.00 ✓         |         |
| 27                   | PRIMER                         | \$ 19.00 ✓            |         |
| 28                   | REAR SPOILER - LH / RH } New   | 2 \$ 462.00 ✓         |         |
| 29                   | REAR SILENCER } Dented         | \$ 1,344.00 ✓         |         |
| 30                   | REAR SILENCER DUAL CLIP } New  | \$ 54.00 ✓            |         |
| 31                   | REAR SILENCER BRACKET ?        | 2 \$ 113.00 ✓ ?       |         |
| 32                   | REAR WHEEL COVER - LH / RH New | 2 \$ 1,154.00 ✓       |         |
| 33                   | REAR WINDSCREEN SEALANT New    | S/N \$ 200.00 ✓       |         |
| 34                   | REAR NO PLATE New              | S/N \$ 60.00 ✓        |         |
| 35                   | SUNDRIES ?                     | \$ 300.00 ?           |         |
| TOTAL SPARE PARTS    |                                | : \$ 17,265.00        |         |
| TOTAL LABOUR CHARGES |                                | : \$ 8,992.00         |         |
| GRAND TOTAL          |                                | : \$ 26,257.00        |         |

All charges are not inclusive of GST

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett

Resurveyed  
Adrian L  
04/08/20 ✓ H.S.  
Add 1 day for  
exhaust.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SDP 5550 P

| S/N                         | Nature of Jobs                                                                                                             | Estimated Charges    | Surveyor's Recommendations                  |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------------------------|
| 1                           | To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.            | S/N \$ 360.00        | ✓                                           |
| 2                           | To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.               | S/N \$ 480.00        | X                                           |
| 3                           | To renew rear windscreen to facilitate rear lid renewal.                                                                   | S/N \$ 480.00        | X                                           |
| 4                           | To install rear windscreen solar film.                                                                                     | S/N \$ 400.00        | X                                           |
| 5                           | To carry out water seepage test on rear windscreen.                                                                        | S/N \$ 200.00        | X                                           |
| 6                           | To dismantle and renew rear bumper to rear lid. Re-organise rear crash management components. Reinstall all parts removed. | \$ 2,400.00          | 500                                         |
| 7                           | To respray rear bumper, rear lower bumper, rear lid and both rear wheel arch trims.                                        | \$ 4,000.00          | 550 x 3 = 1650<br>wheel fl x 2 = 2000 x 400 |
| 8                           | To renew rhs rear exhaust silencer and align to position.                                                                  | S/N \$ 480.00        | ✓                                           |
| 9                           | To apply paint coating on rear bumper.                                                                                     | S/N TBC              | ?                                           |
| 10                          | To carry out diagnostic check.                                                                                             | S/N \$ 192.00        | ✓                                           |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                            | <b>: \$ 8,992.00</b> |                                             |

AP.S 04/08/20