

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 42530

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0510/2020/NS
Date : 22-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ong Thian Hock
Address : 27 upper Serangoon View
#01-13
Singapore 534045
Telephone : (HP) +65 90905550
Type of Claim : Third Party Claim
Policy No. : 1900007600-01
Vehicle No : **SDP 5550 P**
Model Code : Q5 SPORT 2.0 TFSI QU
Model / Year : Jan-19
Engine No : DAX 050787
Chassis No : WAUZZZF9K2023974
Mileage : -
Date In : -
Estimated By : Allan Wu
Accident Date : 22-Jul-20
Place of Accident : Airport Rd Towards Macpherson Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6356 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDP 5550 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	✓
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00	X
3	To renew rear windscreen to facilitate rear lid renewal.	S/N \$ 480.00	X
4	To install rear windscreen solar film.	S/N \$ 400.00	X
5	To carry out water seepage test on rear windscreen.	S/N \$ 200.00	X
6	To dismantle and renew rear bumper to rear lid. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,400.00	500
7	To respray rear bumper, rear lower bumper, rear lid and both rear wheel arch trims.	\$ 4,000.00	550 x 3 = 1650 wheel Arc x 2 = 200 x 2 = 400
8	To renew rhs rear exhaust silencer and align to position.	S/N \$ 480.00	X
9	To apply paint coating on rear bumper.	S/N TBC	?
10	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,992.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDP 5550 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER - UPPER <i>3x hand</i>	\$ 1,724.00	✓
2	REAR BUMPER - LOWER <i>1x hand</i>	\$ 1,182.00	✓
3	REAR BUMPER SPOILER <i>2x hand</i>	\$ 830.00	✓
4	REAR BUMPER TOWING EYE COVER - RH <i>new</i>	\$ 29.00	+
5	REAR BUMPER CLOSING ELEMENT - LH / RH ? 2	\$ 190.00	?
6	REAR BUMPER TRIM - RH ?	\$ 234.00	?
7	TAIL LIGHT - RH <i>Cracked</i>	\$ 691.00	✓
8	BOOT LID CONTROL UNIT <i>new</i>	\$ 399.00	+
9	REAR PARKING AID SENSOR <i>2x new</i> 2	TBC	+
10	REAR PARKING AID SEAL RING <i>4x new</i> 4	\$ 14.00	+
11	REAR BUMPER WIRING SET <i>new</i>	\$ 485.00	+
12	REAR BUMPER CARRIER ?	\$ 911.00	?
13	REAR BUMPER HOLDING STRAP ?	\$ 166.00	?
14	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i> 2	\$ 166.00	?
15	REAR BUMPER FOAM FILLER PIECE - RH ?	\$ 62.00	?
16	REAR LID <i>Repis</i>	\$ 4,168.00	+
17	REAR LID ATTACHMENT PARTS <i>2</i>	\$ 120.00	+
18	REAR LID FLAP GASKET	\$ 383.00	+
19	REAR LID LOCK <i>new</i>	\$ 227.00	+
20	REAR LID LOCK STRIKER <i>new</i>	\$ 85.00	+
SUB TOTAL SPARE PARTS		: \$ 12,066.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDP 5550 P

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
21	PACKING ADHESIVE ?	\$ 18.00 ?	
22	AUDI EMBLEM } new	\$ 122.00 ✓	
23	Q5 INSCRIPTION } new	\$ 95.00 ✓	
24	QUATTRO INSCRIPTION } new	\$ 95.00 ✓	
25	SPOILER FIXING PARTS new	\$ 32.00 ✓	
26	REAR WINDSCREEN } new	\$ 1,131.00 ✓	
27	PRIMER } new	\$ 19.00 ✓	
28	REAR SPOILER - LH / RH } new	2 \$ 462.00 ✓	
29	REAR SILENCER } new	\$ 1,344.00 ✓	
30	REAR SILENCER DUAL CLIP } new	\$ 54.00 ✓	
31	REAR SILENCER BRACKET } new	2 \$ 113.00 ✓	
32	REAR WHEEL COVER - LH / RH new	2 \$ 1,154.00 ✓	
33	REAR WINDSCREEN SEALANT new	S/N \$ 200.00 ✓	
34	REAR NO PLATE new	S/N \$ 60.00 ✓	
35	SUNDRIES ?	\$ 300.00 ?	
TOTAL SPARE PARTS		: \$ 17,265.00	
TOTAL LABOUR CHARGES		: \$ 8,992.00	
GRAND TOTAL		: \$ 26,257.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 30/07/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

LKK Auto Consult must be notified by the Repairer of the following:

- To resurvey before starting spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant