

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 42817

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0516/2020/NS
Date : 27-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Disha Singhvi Khosla
Address : 179 Tanjong Pagar Road
#10-26
Singapore 436608
Telephone : HP +65 96529225
Type of Claim : Own Damage Claim
Policy No. : 1800042897-01
Vehicle No : **SLZ 2507 M**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : Apr-18
Engine No : DAX 030922
Chassis No : WAUZZZF9J2129663
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Jul-20
Place of Accident : KK Hospital Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2123 Fax: 6841 1181

Telefax

Estimated Labour Charges for Accident Vehicle. SLZ 2507 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,200.00 500 ✓	✓
3	To respray rear top bumper, rear lower bumper and both rear wheel arch trims. ✓✓	\$ 2,800.00 1500 ✓	550 x 2 = 1100 200 x 2 = 400 Wheel Arch
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 4,552.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 2507 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER - UPPER } Regis	\$ 1,724.00	+
2	REAR BUMPER - LOWER } Regis	\$ 1,182.00	+
3	REAR BUMPER SPOILER	\$ 830.00	✓ 663.60
4	REAR BUMPER TOWING EYE COVER - RH } Not	\$ 29.00	+
5	REAR BUMPER CLOSING ELEMENT - RH } Not	\$ 95.00	+
6	REAR BUMPER TRIM - RH	\$ 234.00	+
7	TAIL LIGHT - RH	\$ 691.00	✓ 552.80
8	BOOT LID CONTROL UNIT	\$ 399.00	+
9	REAR BUMPER CARRIER	\$ 911.00	+
10	REAR BUMPER HOLDING STRAP	\$ 166.00	✓
11	REAR PARKING AID SENSOR	2 TBC	+
12	REAR WHEEL COVER - LH / RH	2 \$ 1,154.00	✓ 922.40
13	SUNDRIES	\$ 300.00	X
TOTAL SPARE PARTS CHARGES		: \$ 7,715.00	
TOTAL LABOUR CHARGES		: \$ 4,552.00	
GRAND TOTAL		: \$ 12,267.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Name

Adnan Ling
30/07/20

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: XRP Authorized, 03 Days

- Third party's involvement without Prejudice' basis
- No illegal mod. features, is allowed
- Supplementary terms must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 42817

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0516/2020/NS
Date : 27-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,
3 days ok - 02/12/2020 - Garrine

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Disha Singhvi Khosla
Address : 179 Tan Jong Rhu Road
#10-26
Singapore 436608
Telephone : HP +65 96529225
Type of Claim : Own Damage Claim
Policy No. : 1800042897-01
Vehicle No : **SLZ 2507 M**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : Apr-18
Engine No : DAX 030922
Chassis No : WAUZZZF9J2129663
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Jul-20
Place of Accident : KK Hospital Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle, SLZ 2507 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to	S/N \$ 360.00 \$	360.00
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts	\$ 1,200.00 \$	500.00
3	To respray rear top bumper, rear lower bumper and both rear wheel arch trims.	\$ 2,800.00 \$	1,500.00
4	To carry out diagnostic check.	S/N \$ 192.00 \$	192.00
TOTAL LABOUR CHARGES		: \$ 4,552.00 \$	2,552.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 2507 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER - UPPER	\$ 1,724.00	
2	REAR BUMPER - LOWER	\$ 1,182.00	
3	REAR BUMPER SPOILER	\$ 830.00	\$ 663.60
4	REAR BUMPER TOWING EYE COVER - RH	\$ 29.00	
5	REAR BUMPER CLOSING ELEMENT - RH	\$ 95.00	
6	REAR BUMPER TRIM - RH	\$ 234.00	
7	TAIL LIGHT - RH	\$ 691.00	\$ 552.80
8	BOOT LID CONTROL UNIT	\$ 399.00	
9	REAR BUMPER CARRIER	\$ 911.00	
10	REAR BUMPER HOLDING STRAP	\$ 166.00	
11	REAR PARKING AID SENSOR	2 TBC	
12	REAR WHEEL COVER - LH / RH	2 \$ 1,154.00	\$ 922.40
13	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 7,715.00	\$ 2,136.80
TOTAL LABOUR CHARGES		: \$ 4,552.00	\$ 2,552.00
GRAND TOTAL		: \$ 12,267.00	\$ 4,690.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.