

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 30.07.2020

3P INSURANCE: AIG

MODEL: HYUNDAI I 40

SURVEYOR:

VEH NO.: SHC8983A

MVA: OLIVIA

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper	1		\$1,106.00 de/
	Rear Bumper Centre Moulding Assy	1		\$451.25 X un
	Rear Bumper Reflector Lamp(LH)	1		\$31.90 aa/
	Rear Bumper Towing Cover	1		\$98.80 m/
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00 de/
	Rear Bumper Reinforcement Bracket	1		\$80.30 X un
	Rear Bumper Reinforcement	1		\$428.40 aa/
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00 aa/
	Rear Bumper Bracket	1		\$35.60 aa/
	Rear Bumper Sponge	1		\$119.50 de/
	Rear Bumper Under Cover	1		\$228.00 X un
	Rear Bumper Protector (LH)	1		\$33.20 X un
	Tail Lamp (LH)	1		\$697.80 aa/
	Tail Lamp Quarter Panel (LH)	1		\$226.50 bt/
	Tail Lamp Panel Top (LH)	1		\$545.90 bt/
	Tail Lamp Lower Panel (LH)	1		\$225.60 bt/
	Rear Fender (LH)	1		\$2,171.40 bt/
	Exhaust Silencer(LH)	1		\$967.70 R/bt/
	Exhaust Pipe Centre	1		\$730.10 X bt/
	Rear Windscreen Moulding	1		\$51.80 aa/
	Front Door (RH)	1		\$2,256.40 Rx
	Front Bumper Cover	1		\$1,052.20 de/
	Front Bumper Sponge	1		\$99.20 X un
	Front Bumper Reinforcement	1		\$438.40 X un
	Front Bumper Grille (RH)	1		\$93.60 aa/
	Front Bumper Centre Grille	1		\$114.00 aa/
	Front Bumper Lip	1		\$54.00 X un
	Front Fender (RH)	1		\$663.00 bt/
	Headlamp Support Panel Assy	1		\$907.40 X un
	Headlamp (RH)	1		\$1,388.00 aa/
	Headlamp Support Top Cover	1		\$222.60 X un
	Headlamp Halogen Bulb (RH)	1		\$14.40 X un.
SPARE PARTS SUB TOTAL			\$15,709.95	10924.80
LESS 20%			\$3,141.99	
DISCOUNTED SPARE PARTS TOTAL			\$12,567.96	

QTY	DESCRIPTION	QTY	LIST PRICE	REMARKS
1	Rear Bumper Rubber Mat	1	\$50.00	Nett cut ✓
1	Rear Bumper Reverse Sensor	1	\$180.00	Nett new ✓
1	Rear Bumper Advertisement Logo	1	\$50.00	Nett new ✓
1	Rear Windscreen Sealant	1	\$46.00	Nett new ✓
1	Front Door ComfortDelGro Stickers (RH)	1	\$75.00	Nett new ✓
NETT TOTAL			\$401.00	401
SPARE PARTS & NETT TOTAL			\$12,968.96	
	Panel Beating		\$2,000.00	1400
	Spray Painting		\$1,500.00	1400.
	Remove/Refix Reverse Sensor		\$120.00	30.
	Towing Fee		\$60.00	✓ towing group.
	Remove/Refix Upholstery, etc		\$150.00	60.
	Remove/Refix Rear Windscreen		\$150.00	120.
	4 wheel Alignment		\$120.00	80.
LABOUR TOTAL			\$4,100.00	3150
ESTIMATE TOTAL			\$17,068.96	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Taylor 92493749
 1/5 Repair after repair
 30/7/20 @ 4pm
 7 days
 Taylor @ 16 hours on.

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

VEHICLE : SHC8983A TYPE OF CLAIM : TP
 MODEL : HYUNDAI I 40 SURVEYOR : TAUFIKH
 JOB NO : 305413845 DATE : 05/08/20

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

S/No	DESCRIPTION	QTY	ESTIMATE \$	REMARKS
1	BOOTLID	1	2174.90	ht ✓
2	BOOTLID-CRDI PLATE	1	27.90	neu ✓
3	BOOTLID I40 EMBLEM (I40)	1	27.90	neu ✓
4	BOOTLID 'H' EMBLEM	1	28.70	neu ✓
5	WHEEL CAP FRT RH	1	107.10	de ✓
1	BOOTLID COMFORTDELGRO STICKER	1	30.00	NETT neu ✓
2	BOOTLID TEL NO. STICKER	1	30.00	NETT neu ✓

2366.50

60

10924.80 + 2366.50
 13291.30
 20% - 10633.04

Supp SN - 60
 SN - 401

Labr - 3150
 14248.04

11,400 #

7 days