## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

DATE: 30.07.2020

3P INSURANCE: AIG

MODEL: HYUNDAI 1 40

SURVEYOR: \_\_\_\_

MVA: OLIVIA

VEH NO.: SHC8983A

NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper	1		\$1,106.00
	Rear Bumper Centre Moulding Assy	1		<b>\$</b> 451. <b>2</b> 5
	Rear Bumper Reflector Lamp(LH)	1		\$31.90
	Rear Bumper Towing Cover	1		\$98.80
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00
	Rear Bumper Reinforcement Bracket	1		\$80.30
	Rear Bumper Reinforcement	1		\$428.40
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00
	Rear Bumper Bracket	1		\$35.60
	Rear Bumper Sponge	1		\$119.50
	Rear Bumper Under Cover	1		\$228.00
- 1	Rear Bumper Protector (LH)	1		\$33.20
	Tail Lamp (LH)	1		\$697.80
	Tail Lamp Quarter Panel (LH)	1		\$226.50
- 1	Tail Lamp Panel Top (LH)	1		\$545.90
1	Tail Lamp Lower Panel (LH)	1		\$225.60
	Rear Fender (LH)	1		\$2,171.40
1	Exhaust Silencer(LH)	1		\$967.70
ı	Exhaust Pipe Centre	1		\$730.10
ŀ	Rear Windscreen Moulding	1		\$51.80
	Front Door (RH)	1		\$2,256.40
ŀ	Front Bumper Cover	1		\$1,052.20
1	Front Bumper Sponge	1		\$99.20
F	Front Bumper Reinforcement	1		\$438.40
F	Front Bumper Grille (RH)	1		\$93.60
F	Front Bumper Centre Grille	1		\$114.00
F	Front Bumper Lip	1		\$54.00
F	Front Fender (RH)	1		\$663.00
	Headlamp Support Panel Assy	1		\$907.40
ŀ	Headlamp (RH)	1	l	\$1,388.00
ŀ	Headlamp Support Top Cover	1	1	\$222.60
1	Headlamp Halogen Bulb (RH)	1		\$14.40
	SPARE PARTS SUB TOTAL		ŀ	\$15,709.95
	LESS 20%		Γ	\$3,141.99
- 1	DISCOUNTED SPARE PARTS TOTAL			\$12,567.96

DESCRIPTION	QTY	LIST PRICE	REMARKS	
			250.00	<b>N</b> 1
	1			
Rear Bumper Reverse Sensor	1		1 1	
Rear Bumper Advertisement Logo	1			
Rear Windscreen Sealant	1			
Front Door ComfortDelGro Stickers (RH)	1		\$75.00	Nett
NETT TOTA	4		\$401.00	
SPARE PARTS & NETT TOTA	4		\$12,968.96	
Panel Restine				1400
	1 1		\$2,000.00	// co
		^	\$1,500.00	700.
		i	\$120.00	<u> </u>
1		1	\$60.00	10 J.
				60.
· ·····os / ····g·····ic··it			\$120.00	20 -
LABOUR TOTAL		Į.	\$4,100.00	
ESTIMATE TOTAL		ŀ	\$17,068.96	
The same of the sa	Rear Bumper Rubber Mat Rear Bumper Reverse Sensor Rear Bumper Advertisement Logo Rear Windscreen Sealant Front Door ComfortDelGro Stickers (RH)  NETT TOTA  SPARE PARTS & NETT TOTA  Panel Beating Spray Painting Remove/Refix Reverse Sensor Towing Fee Remove/Refix Upholstery, etc Remove/Refix Rear Windscreen 4 wheel Alighment  LABOUR TOTAL	Rear Bumper Rubber Mat Rear Bumper Reverse Sensor Rear Bumper Advertisement Logo 1 Rear Windscreen Sealant 1 Front Door ComfortDelGro Stickers (RH) 1  NETT TOTAL  SPARE PARTS & NETT TOTAL  Panel Beating Spray Painting Remove/Refix Reverse Sensor Towing Fee Remove/Refix Upholstery, etc Remove/Refix Rear Windscreen 4 wheel Alighment  LABOUR TOTAL	Rear Bumper Rubber Mat Rear Bumper Reverse Sensor Rear Bumper Advertisement Logo Rear Windscreen Sealant Front Door ComfortDelGro Stickers (RH)  NETT TOTAL  SPARE PARTS & NETT TOTAL  Panel Beating Spray Painting Remove/Refix Reverse Sensor Towing Fee Remove/Refix Upholstery, etc Remove/Refix Rear Windscreen 4 wheel Alighment  LABOUR TOTAL	Rear Bumper Rubber Mat Rear Bumper Reverse Sensor Rear Bumper Reverse Sensor Rear Bumper Advertisement Logo Rear Windscreen Sealant Rear Windscreen Remove/Refix Reverse Sensor Remove/Refix Reverse Sensor Remove/Refix Upholstery, etc Remove/Refix Rear Windscreen Remove/Refix Rear Windscreen Remove/Refix Rear Windscreen Remove/Refix Rear Windscreen LABOUR TOTAL Rear Sealant Rear Windscreen LABOUR TOTAL Rear Windscreen Rear Windscreen Rear Windscreen LABOUR TOTAL Rear Windscreen Rear Windscre

Touth 97495749 1/5 Romy after repor's 30/7/20 C 4pm ofdays tagtin 3 lehantonn.

prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Fload Singapore 579701 Maintine + 95 6383 6280 Facsimile + 65 6280 9755

Workshops 59 Loyang Drive Singapore 508969 183 Sin Meng Drive Singapore 575717 45 Pandan Road Singapore 500288

engko Lgop Singapore 798156 nga Kadul May ungapore 718791

Date/Time: 30.07.2020 12:04

Page: 1

eam:	ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO.: 305413845
TOMER	And Reputit II (observe	akter filologie i estador del resultante en entendada en elegación del entendada anticidade del como del conse	REGN NO. SHC8983A	MILEAGE
ns.	COMFORT TRANSPORTATION PTE 7010045	LTD	MAKE HYUNDAI	FUEL EF
TOMER I	383 SIN MING DRIVE Singapore SINGAPORE 575717		MODEL <b>I-4</b> 0 29	.07.2020 16:50
(R)	65508755		YR OF MANU 19.05.2016	TARGET DATE
(P) . OUNT CARD NO.			CHASSIS CODE KMHLB41UMGU089815	COMPLETION DATE/TIME:
DONTC	AND NO.	in dia caran-nous in industria: in mannous in industrial discount and a second of the	20 010	Bernor may make the second of


JOB DESCRIPTION

Accident Date: 29.07.2020 NATURE: 3P 29.07.2020

S/NO

LABOR CODE

DESCRIPTION



TAKE PHOTOGRAPH BEFORE / AFTER SPRAY PAINTING

ledgement Slip	Exit Pass			
SERVICE ADVISOR	CUSTOMER'S SIGNATURE			
KED & PASSED OUT BY:				
KEO & DACCED OUT BY				

o: SHC8983A OLIVIA

Vehicle No.: SHC8983A

X Service Advisor Signature/Date Name of Service Advisor Date
 ■ Service Review Revi

aturned to Service Reception upon collection To be kept by Security Guard