



MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Steve (LKK)

WHL P/L
30/7/20, 3.00pm

Estimation

Date:

24/7/2020

Vehicle:

SMN7614E

Make / Model:

KIA CERATO FORTE

Chassis No:

KNAF3416MK5027265

5 dys

L/S, RYAL sy

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	REAR BUMPER / OR	1	\$ 798.00	\$ 798.00
2	REAR BUMPER LOWER LIP / OR	1	\$ 463.00	\$ 463.00
3	REAR BUMPER BRACKET LH	1	\$ 98.00	\$ 98.00
4	REAR BUMPER BRACKET RH	1	\$ 98.00	\$ 98.00
5	REAR BUMPER REINFORCEMENT / OR	1	\$ 380.00	\$ 380.00
6	REAR BUMPER SIDE RETAINER LH / OR	1	\$ 35.00	\$ 35.00
7	REAR BUMPER SIDE RETAINER RH / OR	1	\$ 35.00	\$ 35.00
8	REAR BUMPER LOWER LIP SPOILER	1	\$ 434.00	\$ 434.00
9	REAR BUMPER LAMP LH	1	\$ 155.00	\$ 155.00
10	REAR BUMPER LAMP OUTER GARNISH LH	1	\$ 107.00	\$ 107.00
11	REAR BUMPER LAMP RH	1	\$ 155.00	\$ 155.00
12	REAR BUMPER LAMP OUTER GARNISH RH / CR	1	\$ 107.00	\$ 107.00
13	REAR BOOTLID / DP	1	\$ 954.00	\$ 954.00
14	REAR BOOTLID LOCK / OT	1	\$ 212.00	\$ 212.00
15	REAR BOOTLID LOCK CATCH X	1	\$ 60.00	\$ 60.00
16	REAR BOOTLID EMBLEM LOGO / MC	1	\$ 57.00	\$ 57.00
17	REAR BOOTLID EMBLEM CERATO / M	1	\$ 49.00	\$ 49.00
18	REAR BOOTLID INNER TRIM BOARD X	1	\$ 95.00	\$ 95.00
19	REAR BOOTLID LAMP LH / OR	1	\$ 405.00	\$ 405.00
20	REAR BOOTLID LAMP RH / CR	1	\$ 405.00	\$ 405.00
21	REAR BOOTLID CENTER LAMP / OR	1	\$ 410.00	\$ 410.00
22	REAR BOOT WEATHER STRIPE / CR	1	\$ 102.00	\$ 102.00
23	REAR TAILLAMP LH	1	\$ 609.00	\$ 609.00
24	REAR TAILLAMP RH	1	\$ 609.00	\$ 609.00
25	REAR END PANEL / DP	1	\$ 665.00	\$ 665.00
26	REAR END PANEL TOP GARNISH / CR	1	\$ 160.00	\$ 160.00
27	REAR KEYLESS SENSOR	1	\$ 175.00	\$ 175.00
28	REAR SPARE TYRE TOP COVER X	1	\$ 260.00	\$ 260.00
				\$ 7,657.00
			Less 10%	\$ 765.70
			Total	\$ 6,891.30

SMN7614E

S/Nett items:				
1	REAR REVERSE SENSOR	1 SET	\$ 250.00	\$ 250.00
2	REAR REVERSE CAMERA	1 SET	\$ 300.00	\$ 300.00
3	REAR NUMBER PLATE WITH CASING	1	\$ 60.00	\$ 60.00
4	REAR BUMPER CLIP	1 SET	\$ 80.00	\$ 80.00
5	REAR END PANEL GARNISH CLIP	1 SET	\$ 30.00	\$ 30.00
6	FLOOR PANEL SEALANT	1	\$ 50.00	\$ 50.00
7	END PANEL SEALANT	1	\$ 50.00	\$ 50.00
8	MISCELLANEOUS	1	\$ 200.00	\$ 200.00
				\$ 1,020.00

SMN7614E

Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00
3	REPAIR AND STRAIGHTEN EXHAUST PIPE	1	\$ 150.00	\$ 150.00
4	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 150.00	\$ 150.00
5	REMOVE AND TRANSFER ALL REAR BOOTLID FITTING	1	\$ 150.00	\$ 150.00
6	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 120.00	\$ 120.00
7	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
8	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
9	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
10	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00
				\$ 3,150.00
			Parts Replacement Amount	\$ 7,911.30
			Total Amount for Labour	\$ 3,150.00
			Total Amount	\$ 11,061.30

Supplementary

① Reverse sensor x4. ?

② Rear Tailamp outer cover LH. / CH

③ Rear Tailamp outer cover RH. / CH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: