



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 27/07/2020

Cecilia Low 63896530

Attn: The Motor Claims Department

WITHOUT PREJUDICE

Your Insured veh no :SGQ 1488 Y

China Taiping Insurance (S) Pte Ltd

Xiao Chen

(By Email Only)

3 Anson oad

#16-00

Spring Leaf Tower

Singapore 079909

Dear Sir / Madam

JTFHT02PX00002298

Estimate Cost of repair no Toyota Hiace Van GBA 1242 H & SGQ 1488 Y on 24072020 1@143000

To Supply :-

1pc	Rear boot cover	<i>Dislud</i>		\$ 2,110.10	<i>1855</i>
1pc	Rear boot cover rubber	<i>cut</i>		\$ 321.30	
1pc	Rear rubber bracket	<i>re m</i>		\$ 201.00	
1pc	Rear boot cover 70km/h	<i>re</i>		\$ 31.10	<i>10(SN)</i>
1pc	Rear boot cover 7pax	<i>re</i>		\$ 30.30	<i>10(SN)</i>
1pc	Rear boot cover inner lock	<i>Jamud</i>		\$ 213.40	
1pc	Rear boot cover garnish	<i>Rejs</i>		\$ 148.30	
2pcs	Rear lamp assy	<i>cut</i>	\$ 297.50	\$ 595.00	
1pc	Rear panel outter	<i>dentid</i>		\$ 251.30	
1pc	Rear panel inner	<i>dentid</i>		\$ 296.30	
1pc	Rear bumper	<i>Dislud</i>		\$ 415.30	
10pcs	Rear bumper clips	<i>re</i>		\$ 60.00	<i>30</i>
2pcs	Rear bumper side retainer	<i>re</i>	\$ 65.30	\$ 130.60	
1set	Revers sensor	<i>Demid</i>		\$ 492.60	<i>200(SN)</i>
1pc	Rear boot cover mirror	<i>Re m</i>		\$ 396.30	
1pc	Rear spare tyre bracket	<i>Best.</i>		\$ 299.60	
1pc	Rear spray tyre rim	<i>re m</i>		\$ 200.00	
1pc	Rear boot cover inner rim box	<i>re m</i>		\$ 301.30	
1pc	Rear boot cover logo	<i>re c</i>		\$ 78.10	
2pcs	Rear lamp lower garnish	<i>Rejs</i>	\$ 113.30	\$ 226.60	
2pcs	Rear lamp low garnish retainer	<i>Re m</i>	\$ 60.70	\$ 121.40	
				\$ 6,919.90	<i>4485.90</i>
				\$ 1,729.98	<i>3364.42</i>
				\$ 5,189.93	<i>S.N: 220</i>



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 27/07/2020

Attn: The Motor Claims Department

Your Insured veh no :SGQ 1488 Y

China Taiping Insurance (S) Pte Ltd

3 Anson oad

#16-00

Spring Leaf Tower

Singapore 079909

WITHOUT PREJUDICE

(By Email Only)

Dear Sir / Madam

Page .2

Estimate Cost of repair no Toyota Hiace Van GBA 1242 H & SGQ 1488 Y on 24072020 1@143000

To Supply :-

\$ 5,189.93

1pc Rear windscreen glass inner seal

3pc

\$ ~~55.00~~ S/nett *40*

1pc Rear windscreen sealant

80

\$ ~~55.00~~ S/nett *40*

To dismantl & replace damage parts, panel beat where necessary.

\$ ~~1,250.00~~ *800*

To putty, apply primer & spray paint on the affected portion.

\$ ~~1,250.00~~ *800*

labour charge to remove & refix windscreen

1720

\$ ~~140.00~~ *120*

\$ 7,939.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5384.42

Admin Ly

4/s: 4.3K 1/s 30/07/20

06 Days