

Not Authored
L/Sing Q

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHD 390H

AAD2007-114

Vehicle No.: 30 JUL 2020
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHD 390H
VF1ABL15AUC283248
RENAULT
LATITUDE
28.7.2020

30-09-16

PART	
1	DOOR PANEL REAR LH
1	DOOR LOCK REAR LH
1	FENDER PANEL REAR LH
1	FENDER PANEL INNER TRIM REAR LH
1	WHEELARCH REAR LH
1	FENDER INNER BOARD LH
1	FENDER PANEL INNER REAR LH
1	FUEL FLAP
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET SIDE LH REAR
1	BUMPER RETAINER LH REAR
1	TAILLAMP LH
1	KNUCKLE ARM REAR LH
1	LOWER ARM REAR LH
1	KNUCKLE HUB+BEARING LH
1	ABSORBER REAR
1	AXLE SPRING ARM LH
1	SUBFRAME ARM REAR LH
1	RODE - LONG REAR LH

LIST	
\$	11 2,844.66 X
\$	11 468.20 X
\$	12 1,933.20 ✓
\$	12 671.45 X
\$	12 275.40 X
\$	12 561.40 X
\$	12 1,241.60 X
\$	12 244.70 X
\$	12 561.70 ✓
\$	12 411.90 X
\$	12 80.80 ✓
\$	12 54.20 X
\$	12 401.40
\$	12 472.10
\$	12 543.50
\$	12 272.30
\$	12 217.30
\$	12 220.60
\$	12 198.33
\$	12 120.16

TOTAL \$ 11,794.90
10% \$ 1,179.49
\$ 10,615.41

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	12 100.00 X
1	FENDER INNER TRIM CLIP LH	\$	12 60.00 X
1SET	FENDER WHEELARCH REAR LH CLIP	\$	12 70.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 390H**AAD2007-114**

2	REAR WINDSCREEN SEALANT	\$	150.00	40sn
1	WINDSCREEN MOULDING	\$	190.00	—
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	130.00	30sn
1	REAR LEFT TYRE	\$	300.00	X
1	REAR LEFT TYRE RIM	\$	380.00	—
1SET	REAR BUMPER CLIP	\$	75.00	—
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	60.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	65.00	X
1SET	BUMPER LOWER REAR RIVET	\$	70.00	X
1SET	BUMPER LOWER REAR CLIP	\$	75.00	X
1	TAILLAMP CLIP LH	\$	40.00	X
1	Rear Bumper Protector	\$	170.00	40sn
2	SEAM SEALANT	\$	180.00	X
TOTAL		\$	2,115.00	

TOTAL PARTS \$ 12,730.41**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	600
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100
To check steering geometry and computer wheel alignment	\$	220.00	60
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	120
To pull and jack out vehicle body frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	20

Trans-cab Auto Services Pte Ltd

AAD2007-114

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 390H

To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To rust-proofing and apply undercoat of the affected areas.	\$		250.00	<i>301</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>601</i>
Putty and spray painting of the affected portion.	\$		3,500.00	<i>4401</i>
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	<i>nn</i>	380.00	<i>X</i>
To check ABS and brake efficiency, final checking and testing.	\$	<i>nn</i>	380.00	<i>X</i>
TOTAL	\$		10,180.00	
Over All Total	\$		22,910.41	

LUMP SUM (REPAIR DAY)

~~20 DAYS~~*5 days*