



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI19019055/Evf3e2-1

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 06-08-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKW 9067Y	<b>Veh. Inspected</b>	SMD 5428S
<b>Policy No.</b>	DMPCSN30736819000	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM19D205057C02	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JENNY LEW	<b>Assign Date</b>	30/07/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA SHUTTLE	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	GP71213369	<b>Colour</b>	BLACK
<b>Odometer</b>	137092	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	185/60 R15	MICHELIN	6 mm
<b>L/H Front Tyre</b>	185/60 R15	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	185/60 R15	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	185/60 R15	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	23/10/2019	<b>Inspection Date</b>	29/10/2019
<b>Survey held at</b>	BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER		
<b>Repairer</b>	XIN YUN AUTO PTE LTD		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**