

JIN AUTO SERVICES PTE LTD

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62894656 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

*Not Authorized
4/8/20
Telephone After 4 days.
4/5*

M/S India International Insurance Pte Ltd

DEAR SIR

ESTIMATED REPAIR COST FOR VEHICLE SLM 7987X NV350

List Items

- 1 LH FENDER PANEL
- 1 REAR BUMPER
- 1 REAR BUMPER CLIPS
- 1 REAR END PANEL
- 1 TAILLAMP
- 1 SLIDING DOOR
- 1 REAR BUMPER SIDE RETAINER

LESS10%

Special Nett Items

- 1 SEALANT
- 1 COMPANY ART WORK

To remove and renew Interior seat carpets etc
To remove and refit rear electrical wiring,
To remove and replace the above damaged parts,
To spray paint on the replaced and repaired parts,
To apply undercoating on the repaired and replaced
To remoe and refix both side glass

TOTAL :

NETT ITEM

<i>body</i>	\$ 2,508.60	✓
<i>de/ro.</i>	\$ 767.20	✓
<i>rer</i>	\$ 30.00	✓
<i>11</i>	\$ 1,850.00	X
<i>11</i>	\$ 224.80	X
<i>2-11</i>	\$ 1,497.70	X
<i>2nd</i>	\$ 28.00	✓
	\$ 6,906.30	
	\$ (690.63)	
	\$ 6,215.67	

<i>rer</i>	\$ 280.00	<i>80</i>
<i>rer</i>	\$ 700.00	<i>500</i>
	\$ 120.00	<i>60</i>
	\$ 50.00	<i>20</i>
	\$ 2,250.00	<i>900</i>
	\$ 1,750.00	<i>800</i>
	\$ 120.00	<i>60</i>
	\$ 240.00	<i>200</i>
	\$ 11,725.67	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: