

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2020		30 Jul 2020 18:03 Edit Adj Rpt	S\$14,500.00 Edit Estimates	S\$14,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	0 , Co. Reg. No.: 0		
Main Claimant:	TAN HUIXIU , ID: S8219019H		
Vehicle Reg. No.:	SMP7730S	Date of Loss:	29/07/2020 14:00 - :59 [9 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM20D202666/C02/CHNGPW	Policy/Cover Note No.:	DMCVSN30863119000
Vehicle Reg. No. (Insured):	GBF5492A	Policy No. (Claimant):	VP/P2352397
		Excess:	S\$0.00
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/08/2020]		
Adj Asg. Remarks:	third party choose Adrian Ling as SJE. survey revert		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SMP7730S (SNM20D202666/C02/CHNGPW)**
[GBF5492A]
TP
TAN HUIXIU
Jul 29 2020 2:00PM
[0]
Vision Autowork Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Video					1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print	
1	30/07/20 16:52	Video - Accident [Linked Accident Report Documents]		Load MP4		
2	30/07/20 16:52	Video - Accident [Linked Accident Report Documents]		Load MP4		
Assessment Reports					1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print	
1	30/07/20 16:53	Accident Statement		Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	12/10/20 11:01	Adjuster Immediate Advice		Load HTM		
Photos/Images					3 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print	
1	30/07/20 16:46	Driving License [Linked Accident Report Documents]		Load JPG	☒	
2	30/07/20 16:46	Insurance Cert [Linked Accident Report Documents]		Load JPG	☒	
3	30/07/20 16:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
4	30/07/20 16:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
5	30/07/20 16:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
6	30/07/20 16:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
7	30/07/20 16:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
8	30/07/20 16:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
9	30/07/20 16:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	11/10/20 00:21	General View		Load JPG	☒	
2	11/10/20 00:21	General View		Load JPG	☒	
3	11/10/20 00:21	General View		Load JPG	☒	
4	11/10/20 00:21	General View		Load JPG	☒	
5	11/10/20 00:21	General View		Load JPG	☒	
6	11/10/20 00:21	General View		Load JPG	☒	
7	11/10/20 00:21	General View		Load JPG	☒	
8	11/10/20 00:21	General View		Load JPG	☒	
9	11/10/20 00:21	General View		Load JPG	☒	
10	11/10/20 00:21	General View		Load JPG	☒	
11	11/10/20 00:21	General View		Load JPG	☒	
12	11/10/20 00:21	General View		Load JPG	☒	
13	11/10/20 00:21	General View		Load JPG	☒	

Video			1 per page ▾	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
14	11/10/20 00:21	General View	 Load JPG	☒
15	11/10/20 00:21	General View	 Load JPG	☒
16	11/10/20 00:21	General View	 Load JPG	☒
17	11/10/20 00:21	General View	 Load JPG	☒
18	11/10/20 00:21	General View	 Load JPG	☒
19	11/10/20 00:21	General View	 Load JPG	☒
20	11/10/20 00:21	General View	 Load JPG	☒
21	11/10/20 00:21	General View	 Load JPG	☒
22	11/10/20 00:21	General View	 Load JPG	☒
23	11/10/20 00:21	General View	 Load JPG	☒
24	11/10/20 00:21	General View	 Load JPG	☒
25	11/10/20 00:21	General View	 Load JPG	☒
26	11/10/20 00:21	General View	 Load JPG	☒
27	11/10/20 00:21	General View	 Load JPG	☒
28	11/10/20 00:21	General View	 Load JPG	☒
29	11/10/20 00:21	General View	 Load JPG	☒
30	11/10/20 00:21	General View	 Load JPG	☒
31	11/10/20 00:21	General View	 Load JPG	☒
32	11/10/20 00:21	General View	 Load JPG	☒
33	11/10/20 00:21	General View	 Load JPG	☒
34	11/10/20 00:21	General View	 Load JPG	☒
35	11/10/20 00:21	General View	 Load JPG	☒
36	11/10/20 00:21	General View	 Load JPG	☒
37	11/10/20 00:21	General View	 Load JPG	☒
38	11/10/20 00:21	General View	 Load JPG	☒
39	11/10/20 00:21	General View	 Load JPG	☒
40	11/10/20 00:21	General View	 Load JPG	☒
41	11/10/20 00:21	General View	 Load JPG	☒
42	11/10/20 00:21	General View	 Load JPG	☒
43	11/10/20 00:21	General View	 Load JPG	☒
44	11/10/20 00:21	General View	 Load JPG	☒
45	11/10/20 00:21	General View	 Load JPG	☒
46	11/10/20 00:21	General View	 Load JPG	☒
47	11/10/20 00:21	General View	 Load JPG	☒
48	11/10/20 00:21	General View	 Load JPG	☒
49	11/10/20 00:21	General View	 Load JPG	☒
50	11/10/20 00:21	General View	 Load JPG	☒
51	11/10/20 00:21	General View	 Load JPG	☒
52	11/10/20 00:21	General View	 Load JPG	☒
53	11/10/20 00:21	General View	 Load JPG	☒
54	11/10/20 00:21	General View	 Load JPG	☒
55	11/10/20 00:21	General View	 Load JPG	☒
56	11/10/20 00:21	General View	 Load JPG	☒
57	11/10/20 00:21	General View	 Load JPG	☒
58	11/10/20 00:21	General View	 Load JPG	☒
59	11/10/20 00:21	General View	 Load JPG	☒
60	11/10/20 00:21	General View	 Load JPG	☒
61	11/10/20 00:21	General View	Load JPG	☒

Video			1 per page ▾	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
62	11/10/20 00:21	General View	 Load JPG	☒
63	11/10/20 00:21	General View	 Load JPG	☒
64	11/10/20 00:21	General View	 Load JPG	☒
65	11/10/20 00:21	General View	 Load JPG	☒
66	11/10/20 00:21	General View	 Load JPG	☒
67	11/10/20 00:21	General View	 Load JPG	☒
68	11/10/20 00:21	General View	 Load JPG	☒
69	11/10/20 00:21	General View	 Load JPG	☒
70	11/10/20 00:21	General View	 Load JPG	☒
71	11/10/20 00:21	General View	 Load JPG	☒
72	11/10/20 00:21	General View	 Load JPG	☒
73	11/10/20 00:21	General View	 Load JPG	☒
74	11/10/20 00:21	General View	 Load JPG	☒
75	11/10/20 00:21	General View	 Load JPG	☒
76	11/10/20 00:21	General View	 Load JPG	☒
77	11/10/20 00:21	General View	 Load JPG	☒
78	11/10/20 00:21	General View	 Load JPG	☒
79	11/10/20 00:21	General View	 Load JPG	☒
80	11/10/20 00:21	General View	 Load JPG	☒
81	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
82	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
83	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
84	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
85	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
86	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
87	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
88	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
89	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
90	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
91	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
92	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
93	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
94	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
95	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
96	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
97	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
98	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
99	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
100	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
101	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
102	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
103	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
104	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
105	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
106	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
107	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
108	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
109	11/10/20 00:23	Reinspection Photo	Load JPG	☒

Video			1 per page ▾	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
110	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
111	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
112	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
113	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
114	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
115	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
116	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
117	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
118	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
119	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
120	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
121	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
122	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
123	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
124	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
125	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
126	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
127	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
128	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
129	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
130	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
131	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
132	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
133	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
134	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
135	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
136	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
137	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
138	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
139	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
140	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
141	11/10/20 00:23	Reinspection Photo	 Load JPG	☒
142	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
143	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
144	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
145	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
146	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
147	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
148	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
149	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
150	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
151	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
152	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
153	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
154	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
155	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
156	11/10/20 00:24	Reinspection Photo	 Load JPG	☒
157	11/10/20 00:24	Reinspection Photo	Load JPG	☒

Video			1 per page	✓
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
158	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
159	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
160	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
161	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
162	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
163	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
164	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
165	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
166	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
167	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
168	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
169	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
170	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
171	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
172	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
173	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
174	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
175	11/10/20 00:24	Reinspection Photo	 Load JPG	✓
176	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
177	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
178	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
179	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
180	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
181	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
182	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
183	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
184	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
185	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
186	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
187	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
188	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
189	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
190	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
191	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
192	11/10/20 00:25	Reinspection Photo	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/07/20 18:03	Pre-Repair Survey	 Load PDF	
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	30/07/20 16:42	Sketch Plan [Linked Accident Report Documents]	 Load JPG	✓
2	30/07/20 16:42	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	✓

Linked Accident Report Documents

Video			1 per page	✓
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print

Video				1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print
1	30/07/20 16:52	Video - Accident		Load MP4	
2	30/07/20 16:52	Video - Accident		Load MP4	
Assessment Reports				1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print
1	30/07/20 16:53	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print
1	30/07/20 16:46	Driving License		Load JPG	☒
2	30/07/20 16:46	Insurance Cert		Load JPG	☒
3	30/07/20 16:46	Accident Photo		Load JPG	☒
4	30/07/20 16:46	Accident Photo		Load JPG	☒
5	30/07/20 16:46	Accident Photo		Load JPG	☒
6	30/07/20 16:46	Accident Photo		Load JPG	☒
7	30/07/20 16:46	Accident Photo		Load JPG	☒
8	30/07/20 16:46	Accident Photo		Load JPG	☒
9	30/07/20 16:46	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print
1	30/07/20 16:42	Sketch Plan		Load JPG	☒
2	30/07/20 16:42	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20007893/ATF3S2**Date:** 20/10/2020REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30863119000
Claimant Vehicle No :	SMP7730S	Insured Vehicle No :	GBF5492A
Date of Loss:	29/07/2020	Nature of Claim:	TP
		Claim No:	SNM20D202666/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP7730S	Engine No:	G4FGKU247102
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMLU997563
Reg. Date:	16/10/2019 (Man. Year: 2019)	Odometer:	46784 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,091.92	14,533.92	17,558.00	54.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,540.00	3,610.00	6,930.00	65.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	42,631.92	18,143.92	24,488.00	57.44
Approved Total (Overridden) (\$\$)		14,500.00		
	42,631.92	14,500.00	28,131.92	65.99
+ GST 7.00/7.00% (\$\$)	2,984.23	1,015.00	1,969.23	65.99
Nett Amount (\$\$)	45,616.15	15,515.00	30,101.15	65.99

INSPECTION

Date of Assignment:	30/07/2020	
Date Inspected:	03/08/2020	Inspected At: Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	14.0 days	

10/20/2020

Adjuster Report

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Oct 2020)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP7730S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	474.40 FL	*474.40 FL
2	1		*FRONT BUMPER TOWING COVER	Not Necessary	10.00 FL	*- FL
3	1		*FRONT BUMPER NUMBER PLATE HOLDER	Not Necessary	20.00 FL	*- FL
4	1		*FRONT BUMPER LOWER LIP	Cut	71.70 FL	*71.70 FL
5	2		*FRONT BUMPER FOGLAMP C/W BRACKET RH	Cracked	330.00 FL	*330.00 FL
6	2		*FRONT BUMPER FOG LAMP LOWER GARNISH	Not Necessary	230.80 FL	*- FL
7	2		*FRONT BUMPER SIDE RETAINER	Necessary	32.00 FL	*32.00 FL
8	2		*FRONT BUMPER AIR VENT	Cracked	48.80 FL	*48.80 FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	695.80 FL	*498.00 FL
10	1		*FRONT BUMPER SPONGE	Cracked	110.70 FL	*110.70 FL
11	1		*FRONT BUMPER LOWER BEAM	Cracked	119.00 FL	*119.00 FL
12	1		*FRONT BUMPER TOP RUBBER	Not Necessary	25.40 FL	*- FL
13	1		*FRONT ENGINE UNDER COVER	Torn	133.30 FL	*133.30 FL
14	1		*FRONT FENDER LH	Repair	1,227.70 FL	*- FL
15	2		*FRONT FENDER INNER COWLING	Torn	171.40 FL	*171.40 FL
16	1		*HEAD LAMP (LED)	N/s Cracked	6,069.80 FL	*2,396.00 FL
17	1		*HEAD LAMP LOWER BRACKET	N/s Cracked	48.00 FL	*24.00 FL
18	1		*CENTRE GRILLE	Cracked	1,214.30 FL	*628.00 FL
19	1		*CENTRE GRILLE TOP COVER GARNISH	Not Necessary	84.50 FL	*- FL
20	1		*CENTER GRILLE LOGO	Necessary	26.20 FL	*26.20 FL
21	1		*BONNET	Not Necessary	1,970.70 FL	*- FL
22	1		*BONNET INSULATOR	Not Necessary	221.10 FL	*- FL
23	1		*BONNET LOCK	Not Necessary	130.00 FL	*- FL
24	1		*FRONT SUPPORT PANEL	Cracked	949.30 FL	*949.30 FL
25	2		*FRONT AIRCON CONDENSER SIDE GARNISH	Not Necessary	77.40 FL	*- FL
26	1		*AIRCON CONDENSER	Not Necessary	713.70 FL	*- FL
27	1		*RESONATOR BOX	Cracked	94.50 FL	*94.50 FL
28	1		*RESONATOR DUCT	Not Necessary	96.80 FL	*- FL
29	1		*RADIATOR	Not Necessary	510.50 FL	*- FL
30	1		*HORN	Not Necessary	78.30 FL	*- FL
31	1		*REAR BUMPER	Distorted	459.40 FL	*459.40 FL
32	2		*REAR BUMPER MUDFLAP	Not Necessary	46.00 FL	*- FL
33	2		*REAR BUMPER LAMP	Cracked	403.00 FL	*403.00 FL
34	1		*REAR BUMPER LAMP WIRE HARNESS	Cut	121.00 FL	*121.00 FL
35	2		*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	56.00 FL	*- FL
36	1		*REAR BUMPER CENTRE (BLACK)	Distorted	353.50 FL	*353.50 FL
37	2		*REAR BUMPER RETAINER	Necessary	58.80 FL	*58.80 FL
38	1		*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
39	2		*REAR BUMPER REINFORCEMENT BRACKET	Damaged	10.00 FL	*10.00 FL
40	5		*REAR BUMPER BRACKET	Damaged 3pcs Only	393.00 FL	*15.00 FL
41	1		*REAR BUMPER SIDE INNER LOWER GARNISH	Not Necessary	37.20 FL	*- FL
42	2		*REAR FENDER INNER COWLING (FRONT)	Not Necessary	112.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*REAR FENDER INNER COWLING (REAR)	Not Necessary	120.00 FL	*- FL
44	2		*REAR FENDER INNER TRIM	Torn	416.00 FL	*416.00 FL
45	2		*TAILLAMP	Cracked	2,104.20 FL	*1,752.00 FL
46	2		*TAILLAMP PANEL	Repair	386.20 FL	*- FL
47	1		*BOOTLID	Dented	1,782.40 FL	*1,782.40 FL
48	1		*BOOTLID LAMP	O/s Damaged	1,328.40 FL	*664.20 FL
49	1		*BOOTLID LOGO	Necessary	54.70 FL	*54.70 FL
50	1		*BOOTLID EMBLEM ELITE	Necessary	63.90 FL	*63.90 FL
51	1		*BOOTLID EMBLEM AVANTE	Necessary	31.20 FL	*31.20 FL
52	1		*BOOTLID OUTER SWITCH BUTTON	Not Necessary	196.20 FL	*- FL
53	1		*BOOTLID DETECTOR (OUTER)	Cracked	369.70 FL	*85.00 FL
54	1		*BOOTLID DETECTOR (INNER)	Not Necessary	358.60 FL	*- FL
55	1		*BOOTLID REVERSE CAMERA	Damaged	826.10 FL	*653.00 FL
56	2		*BOOTLID HINGE	Not Necessary	188.60 FL	*- FL
57	2		*BOOTLID STOPPER	Not Necessary	14.00 FL	*- FL
58	1		*BOOLID INSULATOR	Not Necessary	146.80 FL	*- FL
59	1		*BOOTLID TOP LOCK	Damaged	116.20 FL	*116.20 FL
60	1		*BOOTLID LOWER LOCK	Not Necessary	16.00 FL	*- FL
61	1		*BOOTLID WEATHER STRIP	Cut	92.50 FL	*92.50 FL
62	1		*REAR END PANEL	Dented	454.60 FL	*454.60 FL
63	1		*REAR END PANEL TOP GARNISH	Cracked	59.80 FL	*59.80 FL
64	1		*REAR FLOOR PANEL	Repair	246.50 FL	*- FL
65	1		*REAR FLOOR PANEL TOP BOARD	Deformed	219.10 FL	*219.10 FL
66	1		*REAR TOOLS SPONGE	Not Necessary	164.90 FL	*- FL
67	1		*REAR SPARE TYRE BOLT	Damaged	12.00 FL	*12.00 FL
68	1		*REAR CHASSIS RH	Repair	1,694.10 FL	*- FL
69	1		*REAR BLIND SPOT	O/s Cracked	2,499.20 FL	*1,249.60 FL
70	2		*REAR BLIND SPOT BRACKET	Not Necessary	338.60 FL	*- FL
71	1		*REAR BLIND SPOT WIRE HARNESS	Not Necessary	684.90 FL	*- FL
72	1		*CENTER EXHAUST	Not Necessary	896.60 FL	*- FL
73	1		*CENTER EXHAUST INSULATOR	Not Necessary	35.20 FL	*- FL
74	1		*SET CENTER EXHAUST GASKET	Not Necessary	16.00 FL	*- FL
75	1		*REAR EXHAUST PIPE	Bent	688.40 FL	*688.40 FL
76	1		*REAR EXHAUST INSULATOR	Not Necessary	98.50 FL	*- FL
77	1		*SET REAR EXHAUST GASKET	Not Necessary	16.00 FL	*- FL
78	2		*REAR EXHAUST MOUNTING	Not Necessary	39.60 FL	*- FL
79	1		*FRONT SEAT	Damaged	2,156.72 FS	*1,000.00 FS
80	1		*FRONT NUMBER PLATE	Dented	80.00 FS	*50.00 FS
81	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
82	1		*SET FRONT ENGINE UNDER COVER CLIP	Not Necessary	50.00 FS	*- FS
83	1		*SET CENTER GRILLE TOP COVER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
84	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*- FS
85	1		*SET FRONT AIRCON CONDENSER SIDE GARNISH CLIP	Not Necessary	30.00 FS	*- FS
86	1		*SET BONNET INSULATOR CLIP	Not Necessary	60.00 FS	*- FS
87	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	120.00 FS	*- FS
88	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
89	1		*REAR NUMBER PLATE	Dented	80.00 FS	*50.00 FS
90	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
91	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
92	1		*SET TAIL LAMP CLIP	Necessary	40.00 FS	*20.00 FS
93	1		*TAILLAMP PANEL SEALANT	Not Necessary	60.00 FS	*- FS
94	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
95	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	80.00 FS	*60.00 FS
96	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
97	1		*REAR END PANEL INSULATION SEALANT	Necessary	150.00 FS	*60.00 FS
98	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS

Report was unsubmitted during this print-out.

10/20/2020				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
99	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	39,113.22
					- List Item Discount on L Items 20.00/20.00% (\$)	7,021.30
					Total Parts (\$)	32,091.92
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS.	New	4,400.00	1,600.00
2	SPRAY PAINTING TO AFFECTED AREA.	New	3,600.00	1,400.00
3	REMOVE AND REFIX AIRCON CONDENSER AND REFILL AIRCON GAS.	New	120.00	60.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	New	80.00	60.00
5	REFOCUS HEADLAMP BEAM.	New	60.00	0.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	430.00	0.00
7	TUFF COAT.	New	250.00	60.00
8	WIRING CHECK.	New	180.00	30.00
9	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	New	350.00	80.00
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	New	80.00	50.00
11	REAR CHASSIS ALIGNMENT.	New	250.00	0.00
12	TRANSFER BOOTLID MECHANISM.	New	80.00	80.00
13	CONDUCT WATER LEAKAGE TEST.	New	80.00	0.00
14	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT.	New	80.00	0.00
15	REMOVE AND REFIX REAR EXHAUST PIPE.	New	180.00	0.00
16	REMOVE AND REFIX REAR BLIND SPOT SENSOR.	New	120.00	60.00
17	REMOVE AND REFIX REVERSE CAMERA.	New	80.00	50.00
18	REMOVE AND REFIX FRONT SEAT.	New	120.00	80.00
Gross Labour Cost (\$\$)			10,540.00	3,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >