

~~Request 15 days~~

E-mail: visionautowork@gmail.com

DATE : 30.07.20

Denise

KMH D841CMLU997563

CLAIM DETAIL : PARTS

CLAIM DETAIL PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 474.40	\$ 474.40
2	FRONT BUMPER TOWING COVER <i>new</i>	1	\$ 10.00	\$ 10.00
3	FRONT BUMPER NUMBER PLATE HOLDER <i>Distorted new</i>	1	\$ 20.00	\$ 20.00
4	FRONT BUMPER LOWER LIP <i>lit</i>	1	\$ 71.70	\$ 71.70
5	FRONT BUMPER FOGLAMP C/W BRACKET RH <i>cracked new</i>	2	\$ 165.00	\$ 330.00
6	FRONT BUMPER FOG LAMP LOWER GARNISH	2	\$ 115.40	\$ 230.80
7	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 16.00	\$ 32.00
8	FRONT BUMPER AIR VENT <i>cracked</i>	2	\$ 24.40	\$ 48.80
9	FRONT BUMPER REINFORCEMENT <i>Distorted</i>	1	\$ 695.80	\$ <u>695.80</u>
10	FRONT BUMPER SPONGE <i>cracked</i>	1	\$ 110.70	\$ 110.70
11	FRONT BUMPER LOWER BEAM <i>cracked</i>	1	\$ 119.00	\$ 119.00
12	FRONT BUMPER TOP RUBBER <i>Not in</i>	1	\$ 25.40	\$ 25.40
13	FRONT ENGINE UNDER COVER <i>torn</i>	1	\$ 133.30	\$ 133.30
14	FRONT FENDER LH <i>Repair</i>	1	\$ 1,227.70	\$ 1,227.70
15	FRONT FENDER INNER COWLING <i>torn</i>	2	\$ 85.70	\$ 171.40
16	HEAD LAMP (LED) <i>LH cracked</i>	2	\$ 3,034.90	\$ 6,069.80
17	HEAD LAMP LOWER BRACKET <i>LH cracked</i>	2	\$ 24.00	\$ <u>48.00</u>
18	CENTER GRILLE <i>cracked</i>	1	\$ 1,214.30	\$ <u>1,214.30</u>
19	CENTER GRILLE TOP COVER GARNISH <i>Not in</i>	1	\$ 84.50	\$ 84.50
20	CENTER GRILLE LOGO <i>new</i>	1	\$ 26.20	\$ 26.20
21	BONNET <i>Not in</i>	1	\$ 1,970.70	\$ 1,970.70
22	BONNET INSULATOR <i>3 not in</i>	1	\$ 221.10	\$ 221.10
23	BONNET LOCK <i>Not in</i>	1	\$ 130.00	\$ 130.00
24	FRONT SUPPORT PANEL <i>cracked</i>	1	\$ 949.30	\$ <u>949.30</u>
25	FRONT AIRCON CONDENSER SIDE GARNISH <i>Not in</i>	2	\$ 38.70	\$ 77.40
26	AIRCON CONDENSER <i>Not in</i>	1	\$ 713.70	\$ 713.70
27	RESONATOR BOX <i>cracked</i>	1	\$ 94.50	\$ 94.50

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMP7730K
 MODEL : HYUNDAI ELANTRA
 DATE OF ACCIDENT : 29.07.20
 TIME OF ACCIDENT : 14:45HRS

28	RESONATOR DUCT <i>3 new</i>	1	\$ 96.80	\$ 96.80
29	RADIATOR	1	\$ 510.50	\$ 510.50
30	HORN <i>new</i>	1	\$ 78.30	\$ 78.30
31	FRONT SEAT <i>Dmgd</i>	1	\$ 2,695.90	\$ 2,695.90
32	REAR BUMPER <i>Distorted</i>	1	\$ 459.40	\$ 459.40
33	REAR BUMPER MUDFLAP <i>new</i>	2	\$ 23.00	\$ 46.00
34	REAR BUMPER LAMP <i>crushed</i>	2	\$ 201.50	\$ 403.00
35	REAR BUMPER LAMP WIRE HARNESS <i>new</i>	1	\$ 121.00	\$ 121.00
36	REAR BUMPER NUMBER PLATE LAMP <i>new</i>	2	\$ 28.00	\$ 56.00
37	REAR BUMPER CENTRE (BLACK) <i>Distorted</i>	1	\$ 353.50	\$ 353.50
38	REAR BUMPER RETAINER <i>new</i>	2	\$ 29.40	\$ 58.80
39	REAR BUMPER REINFORCEMENT <i>crushed</i>	1	\$ 294.80	\$ 294.80
40	REAR BUMPER REINFORCEMENT BRACKET <i>2nd</i>	2	\$ 5.00	\$ 10.00
41	REAR BUMPER BRACKET <i>2nd</i>	5	\$ 78.60	\$ 393.00
42	REAR BUMPER SIDE INNER LOWER GARNISH <i>new</i>	1	\$ 37.20	\$ 37.20
43	REAR FENDER INNER COWLING (FRONT) <i>3rd</i>	2	\$ 56.00	\$ 112.00
44	REAR FENDER INNER COWLING (REAR) <i>1st</i>	2	\$ 60.00	\$ 120.00
45	REAR FENDER INNER TRIM <i>torn</i>	2	\$ 208.00	\$ 416.00
46	TAILLAMP <i>crushed</i>	2	\$ 1,052.10	\$ 2,104.20
47	TAILLAMP PANEL <i>Repair</i>	2	\$ 193.10	\$ 386.20
48	BOOTLID <i>Dented</i>	1	\$ 1,782.40	\$ 1,782.40
49	BOOTLID LAMP <i>RH Dmgd</i>	2	\$ 664.20	\$ 1,328.40
50	BOOTLID LOGO <i>2</i>	1	\$ 54.70	\$ 54.70
51	BOOTLID EMBLEM 'ELITE' <i>new</i>	1	\$ 63.90	\$ 63.90
52	BOOTLID EMBLEM 'AVANTE'	1	\$ 31.20	\$ 31.20
53	BOOTLID OUTER SWITCH BUTTON <i>new</i>	1	\$ 196.20	\$ 196.20
54	BOOTLID DETECTOR (OUTER) <i>crushed</i>	1	\$ 369.70	\$ 369.70
55	BOOTLID DETECTOR (INNER) <i>Not in</i>	1	\$ 358.60	\$ 358.60
56	BOOTLID REVERSE CAMERA <i>Dmgd</i>	1	\$ 826.10	\$ 826.10
57	BOOTLID HINGE <i>new</i>	2	\$ 94.30	\$ 188.60
58	BOOTLID STOPPER <i>Not in</i>	2	\$ 7.00	\$ 14.00
59	BOOTLID INSULATOR <i>new</i>	1	\$ 146.80	\$ 146.80
60	BOOTLID TOP LOCK <i>Dmgd</i>	1	\$ 116.20	\$ 116.20
61	BOOTLID LOWER LOCK <i>new</i>	1	\$ 16.00	\$ 16.00
62	BOOTLID WEATHER STRIP <i>lt</i>	1	\$ 92.50	\$ 92.50
63	REAR END PANEL <i>Dented</i>	1	\$ 454.60	\$ 454.60

+
+
+
1000/snd
✓
+
✓
+
✓
✓
15
+
+
✓
1752
+
✓
684.20
✓
✓
+
85
+
653
+
+
+
+
✓
✓

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMP7730K
 MODEL : HYUNDAI ELANTRA
 DATE OF ACCIDENT : 29.07.20
 TIME OF ACCIDENT : 14:45HRS

64	REAR END PANEL TOP GARNISH <i>cluded</i>	1	\$ 59.80	\$ 59.80	✓
65	REAR FLOOR PANEL <i>Repair</i>	1	\$ 246.50	\$ 246.50	+
66	REAR FLOOR PANEL TOP BOARD <i>cluded</i>	1	\$ 219.10	\$ 219.10	✓
67	REAR TOOLS SPONGE <i>Neu</i>	1	\$ 164.90	\$ 164.90	+
68	REAR SPARE TYRE BOLT <i>Byd</i>	1	\$ 12.00	\$ 12.00	✓
69	REAR CHASSIS RH <i>Repair</i>	1	\$ 1,694.10	\$ 1,694.10	+
70	REAR BLIND SPOT <i>RH cluded</i>	2	\$ 1,249.60	\$ 2,499.20	1249.60
71	REAR BLIND SPOT BRACKET <i>Neu</i>	2	\$ 169.30	\$ 338.60	+
72	REAR BLIND SPOT WIRE HARNESS <i>Neu</i>	1	\$ 684.90	\$ 684.90	+
73	CENTER EXHAUST <i>2</i>	1	\$ 896.60	\$ 896.60	+
74	CENTER EXHAUST INSULATOR <i>Neu</i>	1	\$ 35.20	\$ 35.20	+
75	CENTER EXHAUST GASKET (SET)	1	\$ 16.00	\$ 16.00	+
76	REAR EXHAUST PIPE <i>Repair But</i>	1	\$ 688.40	\$ 688.40	✓
77	REAR EXHAUST INSULATOR <i>Neu</i>	1	\$ 98.50	\$ 98.50	+
78	REAR EXHAUST GASKET (SET) <i>Neu</i>	1	\$ 16.00	\$ 16.00	+
79	REAR EXHAUST MOUNTING <i>Neu</i>	2	\$ 19.80	\$ 39.60	+

16217.40
 12973.92
 TOTAL PRICE \$ 37,802.40
 LESS 20% \$ 7,560.48
 SUB TOTAL PRICE \$ 30,241.92
 SN: 1000

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Dented</i>	1	\$ 80.00	\$ 80.00	50
2	FRONT BUMPER CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT ENGINE UNDER COVER CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	+
4	CENTER GRILLE TOP COVER GARNISH CLIP (S) <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
5	FRONT FENDER INNER COWLING CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	+
6	FRONT AIRCON CONDENSER SIDE GARNISH CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00	+
7	BONNET INSULATOR CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
8	FRONT SUPPORT PANEL SEALANT <i>Neu</i>	1	\$ 120.00	\$ 120.00	+
9	RADIATOR COOLANT <i>Neu</i>	1	\$ 60.00	\$ 60.00	40
10	REAR NUMBER PLATE <i>Dented</i>	1	\$ 80.00	\$ 80.00	50
11	REAR BUMPER CLIP (SET) <i>m</i>	1	\$ 80.00	\$ 80.00	30
12	BOOT LID INSULATOR CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
13	TAIL LAMP CLIP (SET) <i>Neu</i>	1	\$ 40.00	\$ 40.00	20
14	TAILLAMP PANEL SEALANT <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
15	REAR FENDER INNER COWLING CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
16	REAR FENDER INNER TRIM CLIPS (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	60

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMP7730K
 MODEL : HYUNDAI ELANTRA
 DATE OF ACCIDENT : 29.07.20
 TIME OF ACCIDENT : 14:45HRS

17	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	<i>20</i>
18	REAR END PANEL INSULATION SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
19	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
20	REVERSE SENSOR <i>Part 2</i>	1	\$ 220.00	\$ 220.00	<i>200</i>
			<i>560</i> TOTAL	\$ 1,850.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	<i>600</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>400</i>
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>60</i>
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>60</i>
5	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>+</i>
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>+</i>

1120

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,800.00	<i>1000</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	<i>1000</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>80</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>+</i>
8	TRANSFER BOOTLID MECHANISM	\$ 80.00	<i>✓</i>

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMP7730K**
 MODEL : **HYUNDAI ELANTRA**
 DATE OF ACCIDENT : 29.07.20
 TIME OF ACCIDENT : 14:45HRS

9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
10	REMOVE AND REFIX FUEL TANK TO FACILITE FLOOR PANEL REPLACEMENT	\$ 80.00	X
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
12	REMOVE AND REFIX REAR BLIND SPOT SENSOR	\$ 120.00	60
13	REMOVE AND REFIX REVERSE CAMERA	\$ 80.00	50
14	REMOVE AND REFIX FRONT SEAT	\$ 120.00	80
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

TOTAL \$ 10,540.00

2480

ESTIMATE REPORT

TOTAL PARTS COST : \$ 32,091.92
 TOTAL LABOUR COST : \$ 10,540.00
 TOTAL REPAIR COST : \$ 42,631.92

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Adrian L

L/S 03/08/20

12 Days.

total: 18,43.92

L/S: 14.5K..

14.5K

14 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: