

Steve (LKK)
Without Prejudice
04/08/20, 2.30pm
Lumpsum
Resurvey After Spray
3 repair days

Adjustment of Spare Parts Costs for Repairs SFW 1922R
Chassis no: KMHDH41CMCU423262

Item	Qty	List Items Vehicle parts description	\$	
1		1 front bumper ✓ DEF	458	
2		1 front bumper side retainer ✓ BR	38	
3	1 set	Rear bumper fasteners ✓ NEC	48	20 ✓
4		1 front bumper sponge ✗ NN	115	
5		1 front bumper lower center grille ✗ NN	235	
6		1 front bumper lower center grille chrome ✗ NN	155	
7		1 front bumper lower engine garnish ✓ BR	165	
8	1set	front bumper lower engine garnish fasteners ✓ NEC	38	20 ✓
9		1 front grille ✓ BR	265	
10		1 front grille logo emblem ✓ NEC	90	
11		1 front support panel ✗ NN	510	
12		1 front support panel top garnish ✗ NN	150	
13		1 front bonnet ✗ NN	760	
14		1 front RH fender ✗ NN	345	
15		1 front RH fender inner shield ✗ NN	195	
16		1 front RH headlamp ✓ CUT	655	
17		1 front RH fog lamp ✓ BR	220	
18		1 front bumper reinforcement ✗ NN	380	
			4822	1931
		Less 20%	964.4	-20%
			3857.6	1544.80

Special Nett Items

1 front car plate sealing nut ✓ NEC 100 30 ✓

Adjustment of Labour Costs for Repairs

Spraying of affected areas 400 200 ✓

Carry out body cavity preservation 80 30 ✓

To remove & replaced damaged parts including
repositioning replacement parts & panel beat 600 200 ✓

Check wiring 50 30 ✓

to realign headlamp focus 40 30 ✓

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Total labour

P - 1544.80
N + L - 520
2064.80

1170

N + L = 520

L/S - 1651.84
= 1650

Acknowledged by Repairer

Signature:

Date: