

ASS. REQ. BY:

Steve

REF:

CS/CTI 20007977/Esf3

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMU 2430

Yr Regn:

27/7/90

Type: ☒ M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

c.c

1496

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

56

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GP7-2005246

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/SSR 16

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

29/7/90

D.O.I.

3/8/90

Survey held at

Xin Yun Auto

Des. of Damages ☒ Frt

Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-79K

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.B.H.C.

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMU243D Honda Shuttle Hybrid 1.5 Auto

No	Qty	Parts Description	Estimated Parts Price
			\$ 1,233.20
1	1	Front bumper assy / <i>DD</i>	\$ 85.00
2	1	Front bumper right bracket ?	\$ 85.00
3	1	Front bumper right side retainer / <i>DR</i>	\$ 260.60
4	1	Front bumper reinforcement / <i>BT</i>	\$ 205.00
5	1	Front bumper lower grille / <i>CR4</i>	\$ 68.30
6	1	Front bumper tow cover / <i>CR4</i>	\$ 108.10
7	2	Front bumper lower garnish X	\$ 280.10
8	1	Front bumper lower lip X	\$ 397.50
9	1	Front grille assy / <i>BR</i>	\$ 68.30
10	1	Front grille emblem / <i>CUT</i>	\$ 191.50
11	1	Front grille chrome moulding / <i>BR</i>	\$ 1,696.70
12	1	Front bonnet assy / <i>DD</i>	\$ 98.60
13	2	Front bonnet hinges / <i>BT</i>	\$ 105.00
14	2	Front bonnet rubber / <i>CUT</i>	\$ 281.50
15	1	Front bonnet inner board / <i>CR4</i>	\$ 798.30
16	1	Front support panel assy / <i>DD</i>	\$ 197.30
17	1	Front support panel top garnish ?	\$ 45.00
18	2	Front support panel rubber stopper ?	\$ 2,250.00
19	1	Front right headlamp / <i>BR</i>	\$ 2,250.00
20	1	Front left headlamp / <i>DR</i>	\$ 97.50
21	1	Front right headlamp lower bracket ?	\$ 97.50
22	1	Front left headlamp lower bracket ?	\$ 882.30
23	1	Front right fender assy / <i>DD</i>	\$ 68.20
24	1	Front right fender assy / <i>DD</i>	\$ 208.60
25	1	Front right fender inner cowling X	\$ 978.40
26	1	Front left fender inner cowling X	\$ 1,900.00
27	1	Compressor X	\$ 985.00
28	1	Condenser assy / <i>DD</i>	\$ 256.20
29	1	Condenser suction pipe ?	\$ 256.20
30	1	Condenser discharge pipe ?	\$ 251.20
31	1	Front aircon fan cowling ?	\$ 1,540.00
32	1	Radiator assy ?	\$ 485.00
33	1	Fan motor ?	\$ 250.00
34	2	Radiator fan x2pc ?	\$ 150.00
35	1	Front radiator expansion tank <i>CR4</i> ?	\$ 98.00
36	2	Front radiator top rubber mounting ?	

37	1	Front wiper tank ✓ CPV	\$	125.00
38	1	Engine manifold assy ?	\$	685.00
39	1	Manifold sensor ?	\$	455.00
40	1	Manifold intake hose ?	\$	225.00
41	1	Manifold line ?	\$	585.00
42	1	Manifold gasket ?	\$	125.00
43	3	Engine mounting X	\$	178.40
44	2	Driveshaft left X	\$	1,500.00
45	2	Engine hose X	\$	328.30
46	1	Coolant line X	\$	250.00

Parts sub-total

\$ 23,665.80

\$ 23,665.80



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMU243D Honda Shuttle Hybrid 1.5 Auto

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	10	Front bumper clips / <i>NC</i>	\$ 50.00	31
2	6	Front bumper lower grille clips / <i>NC</i>	\$ 30.00	17
3	8	Front bonnet inner board clips / <i>NC</i>	\$ 30.00	20
4	6	Front grille chrome moulding clips / <i>NC</i>	\$ 30.00	20
5	6	Front grille clips / <i>NC</i>	\$ 20.00	10
6	6	Front right fender inner cowling clips X	\$ 30.00	
7	1	Front right quarter glass sealant X	\$ 60.00	
8	10	Front right door inner board clips X	\$ 30.00	
9	8	Front support panel top garnish clips / <i>NC</i>	\$ 30.00	10
10	1	Front no plate with cashing / <i>OR</i>	\$ 80.00	35
<u>Special Nett Items</u>			\$ 390.00	
Total parts			\$ 24,055.80	



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMU243D Honda Shuttle Hybrid 1.5 Auto

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,600.00 800
2	To putty and spray painting front portion.	\$ 1,600.00 1200
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To apply anti rust proofing to front affected area.	\$ 120.00 30
5	To remove and install front undercarriage parts.	\$ 120.00 X
6	To balance front right wheel.	\$ 60.00 X
7	To conduct wheel alignment.	\$ 120.00 X
8	To remove and install front bonnet lock mechanism assy.	\$ 60.00 30
9	To remove and install rear bumper sensor.	\$ 80.00 30
10	To conduct chassis alignment.	\$ 350.00 X
11	To remove and install condensor, compressor and check airocn system, top up gas, check leakage	\$ 350.00 121
12	To remove and install radiator, water pump, check water related system, check leakage	\$ 350.00 50
13	To remove and install manifold assy	\$ 350.00 ?
14	Need to remove and check engine and gearbox	\$ 500.00 X
15	Towing service.	\$ 100.00 60
Total labour :		\$ 5,810.00

Total parts :

Total labour : 5,810.00

Total repair cost : ~~5,810.00~~ 29,865.80

Steve (LKK) 3/8/20, 11.30 am

Not Authn (Rev)

Express - \$ 800

P/P

My Defr Spry
10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: