

ASS. REC. BY:

Steve

REF:

CS/CTI 20007977 / Est 3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$ 800.00

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMU 2430 Yr Regn: 27/7/20Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle C.C. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 56 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP7-2005246Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55R16R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 29/7/20 D.O.I. 3/8/20Survey held at Xin Yun AutoDes. of Damages ☒ Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-79K

\$ 16,924.88

1/4 * ~~15,920.40~~ @ 10 days~~(\$ 17,915.40 Red 52%)~~

(\$ 16,565.92/RED - 49%)

Date/Time, File Pass to?

22/09/2020

1) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 10Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format:

Lump Sum ☒ \$ 16,924.88 P/P)



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMU243D Honda Shuttle Hybrid 1.5 Auto

No	Qty	Parts Description	Unit	Estimated Price	
25	1	Front bumper assy / DD		\$ 1,233.20	585 ✓
43-44	2	Front bumper right bracket / BT (ex brown bracket)		\$ 85.00	74 ✓
41-42	3	Front bumper right side retainer / BR		\$ 85.00	16 ✓
40	1	Front bumper reinforcement / BT		\$ 260.60	235 ✓
30	5	Front bumper lower grille / CRV		\$ 205.00	78 ✓
38	6	Front bumper tow cover / CRV		\$ 68.30	16 ✓
39	7	Front bumper lower garnish / BR		\$ 108.10	145 ✓
60	8	Front bumper lower lip (brown garnish) / BR		\$ 280.10	110 ✓
45-48-49	1	Front grille assy / BR		\$ 397.50	263 ✓
47-105	1	Front grille emblem / (cuff emblem base)		\$ 68.30	44 ✓
46	11	Front grille chrome moulding / BR		\$ 191.50	185 ✓
19	12	Front bonnet assy / DD		\$ 1,696.70	520 ✓
20-21	2	Front bonnet hinges / BT		\$ 98.60	48 ✓
23	14	Front bonnet rubber / CRV		\$ 105.00	20 ✓
13	15	Front bonnet inner board / CRV		\$ 281.50	120 ✓
24	16	Front support panel assy / DD		\$ 798.30	500 ✓
17	1	Front support panel top garnish / CRV X NN		\$ 197.30	X
50	18	Front support panel rubber stopper / X NN		\$ 45.00	X
51	19	Front right headlamp / BR		\$ 2,250.00	1560 ✓
20	1	Front left headlamp / BR		\$ 2,250.00	1560 ✓
82	21	Front right headlamp lower bracket / BT		\$ 97.50	115 ✓
33	22	Front left headlamp lower bracket / BT		\$ 97.50	115 ✓
52	23	Front right fender assy / DD		\$ 882.30	170 ✓
53	24	Front right fender assy / DD		\$ 68.20	170 ✓
25	1	Front right fender inner cowling X bracket NN		\$ 208.60	X
26	1	Front left fender inner cowling X bracket NN		\$ 978.40	X
27	1	Compressor X NN		\$ 1,900.00	X
66	28	Condenser assy / DD		\$ 985.00	625 ✓
29	1	Condenser suction pipe / X NN		\$ 256.20	X
7	30	Condenser discharge pipe / BT		\$ 256.20	130 ✓
31	1	Front aircon fan cowling / X NN		\$ 251.20	X
54	32	Radiator assy / BT		\$ 1,540.00	1015 ✓
33	1	Fan motor / X NN		\$ 485.00	X
34	2	Radiator fan x2pc / X NN		\$ 250.00	X
35	1	Front radiator expansion tank / CRV X NN		\$ 150.00	X
36	2	Front radiator top rubber mounting / X NN		\$ 98.00	X

Rubber fan cowling / BR

- 37 1 Front wiper tank ~~CR4~~ X NN
- 38 (56) 1 Engine manifold assy 7 - DR
- 39 1 Manifold sensor ? X NN
- 40 1 Manifold intake hose X NN
- 41 1 Manifold line X NN
- 42 1 Manifold gasket ? X NN
- (62) 43 3 Engine mounting X - DT
- 44 2 Driveshaft left X NN
- (53) 45 21 Engine hose X ~~Left Pipe~~ DT
- 46 1 Coolant line X NN

\$	125.00	X
\$	685.00	380 /
\$	455.00	X
\$	225.00	X
\$	585.00	X
\$	125.00	X
\$	178.40	165 /
\$	1,500.00	X
\$	328.30	145 /
\$	250.00	X

Parts sub-total

\$	23,665.80
\$	23,665.80

- ~~Engl mail mounty bracket RH / BR~~
- ~~Battery / CR4~~
- ~~" Red cover / DR~~
- ~~Pick up hose / CR4~~
- ~~oil gauge lens / DR~~
- ~~Air filter assy / DR~~
- ~~Emblem Intake manifold / MC~~
- ~~cowl M cover R, L / MS~~
- ~~Radiator spray tank / CR4~~
- ~~Engine gasket seal / MC~~
- ~~Engine rocker cover / DR~~
- ~~Timing cover / DR~~
- ~~F-1 Fender logo R, L / MC~~
- ~~Beam Insulator / TN~~
- ~~Engine~~



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMU243D Honda Shuttle Hybrid 1.5 Auto

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Front bumper clips / <i>APC</i>	\$ 50.00 <i>31</i>
2	6	Front bumper lower grille clips / <i>APC</i>	\$ 30.00 <i>19</i>
3	8	Front bonnet inner board clips / <i>APC</i>	\$ 30.00 <i>20</i>
4	6	Front grille chrome moulding clips / <i>APC</i>	\$ 30.00 <i>20</i>
5	6	Front grille clips / <i>APC</i>	\$ 20.00 <i>10</i>
6	6	Front right fender inner cowling clips X <i>NIM</i>	\$ 30.00
7	1	Front right quarter glass sealant X <i>NIM</i>	\$ 60.00
8	10	Front right door inner board clips X <i>NIM</i>	\$ 30.00
9	8	Front support panel top garnish clips / <i>APC</i>	\$ 30.00 <i>10</i>
10	1	Front no plate with cashing / <i>GR</i>	\$ 80.00 <i>35</i>
<u>Special Nett Items</u>			<u>\$ 390.00</u>
Total parts			\$ 24,055.80



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMU243D Honda Shuttle Hybrid 1.5 Auto

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,600.00 800
2	To putty and spray painting front portion.	\$ 1,600.00 1200
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To apply anti rust proofing to front affected area.	\$ 120.00 30
5	To remove and install front undercarriage parts.	\$ 120.00 X
6	To balance front right wheel.	\$ 60.00 X
7	To conduct wheel alignment.	\$ 120.00 X
8	To remove and install front bonnet lock mechanism assy.	\$ 60.00 30
9	To remove and install rear bumper sensor.	\$ 80.00 30
10	To conduct chassis alignment.	\$ 350.00 X
11	To remove and install condensor, compressor and check airocn system, top up gas, check leakage	\$ 350.00 120
12	To remove and install radiator, water pump, check water related system, check leakage	\$ 350.00 50
13	To remove and install manifold assy	\$ 350.00 100
14	Need to remove and check engine and gearbox	\$ 500.00 X
15	Towing service.	\$ 100.00 60
Total labour :		\$ 5,810.00

Total parts :

Total labour : 5,810.00

Total repair cost : 5,810.00

33,490.80

Store (LKK) 3/8/20, 11.30 am

Not Author (Rem)

Excess - \$ 800

P/P

My Defr spray
10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMU243D Honda Shuttle Hybrid 1.5 Auto

①	1	2	Windscreen stopper cover / MIS	\$	50.00	26 ✓
②	2	1	Radiator cowling / BR	\$	125.00	90 ✓
③	3	1	Engine oil strick / BR	\$	35.00	20 ✓
④	4	1	Air cleaner housing set / BR	\$	225.00	125 ✓
⑤	5	1	Air housing emblem / nec	\$	55.00	26 ✓
⑥	6	1	Air intake tube / CUT	\$	45.00	33 ✓
⑦	7	1	Washer hose / CUT	\$	45.00	20 ✓
⑧	8	1	Engine gasket seal packing / nec	\$	45.00	36 ✓
⑨	9	1	Engine cover cylinder / nec	\$	350.00	250 ✓
⑩	10	1	Washer tank / CRU	\$	85.00	52 ✓
⑪	11	1	Speaker audible (Horn) / BT	\$	95.00	75 ✓
⑫	12	1	Timng cover / BR	\$	450.00	315 ✓
⑬	13	1	Wipper garnish / BR	\$	225.00	185 ✓
⑭	14	1	Radiator mounting / MIS	\$	50.00	13 ✓
⑮	15	1	Battery terminal cover / CRU	\$	25.00	15 ✓
⑯	16	1	A/c shroud / BR	\$	125.00	80 ✓
⑰	17	1	Bonnet lock / BT	\$	95.00	85 ✓
⑱	18	2	Fender bracket / BT	\$	35.00	80 ✓
⑲	19	1	Engine side torque bracket No.2 flat (silv) / BT	\$	85.00	60 ✓
⑳	20	1	Torque mounting at side silver color crack (Top mounting RH) (Engine \$ cover) / BR	\$	95.00	72 ✓
㉑	21	2	Fog lamp / BR	\$	600.00	540 ✓
㉒	22	1	Fog lamp cover / CUT.	\$	170.00	144 ✓
㉓	23	1	Front grill lower mounting (grille) / BR	\$	160.00	145 ✓

\$ 3,270/-



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMU243D Honda Shuttle Hybrid 1.5 Auto

					Estimated Parts Price	
No	Qty	Parts Description	Supplementary			
1	2	Front bumper side garnish	✓	BR	\$ 120.00	40 ✓
2	1	DUCT top cover	✓	CRU	\$ 150.00	66 ✓
3	1	Air assy	✓	BR	\$ 85.00	52 ✓