

Vehicle No : SMG 2878 E Nissan Sylphy (A)  
 Workshop : MG Solution Pte Ltd

MNTBBABIT20033835

TP/0130/19

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist.%	Our Recommendation (S \$)	Dist.%
To Supply :					
1 pc boot lid	Distorted	1,299.00		850.90 (1,299.00)	10
1 pc boot lid 'Sylphy' emblem	Necessary	72.00		72.00	✓ 10
1 pc boot lid centre emblem	Necessary	122.00		46 (122.00)	10
1 pc boot lid lock	Bent	105.00		105.00	✓ 10
1 pc boot lid lock catch	Bent	78.00		78.00	× 10
1 pc boot lid RH hinge	Bent	196.00		196.00	× 10
1 pc boot lid LH hinge	Bent	196.00		196.00	× 10
1 pc boot lid inner trim	Crumpled	382.00		382.00	× 10
1 set boot lid inner trim clips	Necessary	50.00		50.00	× 10
1 pc boot lid RH lamp assy	Cracked	203.00		203.00	× 10
1 pc boot lid LH lamp assy	Refit	203.00		--	× 10
1 pc boot lid weatherstrip	Bent	155.00		155.00	✓ 10
1 pc rear bumper	Dented	873.00		625 (873.00)	10
1 set rear bumper clips	Necessary	50.00		30 50.00	10
1 pc rear bumper RH side reflector	Cracked	84.00		84.00	✓ 10
1 pc rear bumper RH side reflector cover	Refit	132.00		--	✓ 10
1 pc rear bumper RH side retainer	Cracked	78.00		35 78.00	10
1 pc rear bumper LH side retainer	Cracked	78.00		35 78.00	10
1 pc rear bumper RH bracket arm	Dented	109.00		50.40 (109.00)	10
1 pc rear bumper LH bracket arm	Refit	109.00		--	× 10
1 pc rear bumper sponge	Cracked	203.00		137.80 (203.00)	10
1 pc RH tail lamp assy	Cracked	338.00		338.00	✓ 10
1 set RH tail lamp lock clips	Necessary	28.00		28.00	✓ 10
1 pc LH tail lamp assy	Cracked	338.00		338.00	✓ 10
1 set LH tail lamp lock clips	Necessary	28.00		28.00	✓ 10
1 pc end panel	Dented / Distorted	844.00		428.40 (844.00)	10
1 pc end panel inner trim	Deformed	231.00		231.00	✓ 10
1 pc rear keyless sensor	Cracked	187.00		86.70 (187.00)	10
1 pc spare tyre panel top board	Refit	408.00		--	× 10
1 pc rear RH fender inner trim	Deformed	502.00		502.00	× 10
1 set rear RH fender inner trim clips	Necessary	40.00		40.00	× 10
1 pc rear LH fender inner trim	Refit	502.00		--	× 10
1 set rear LH fender inner trim clips	Necessary	40.00		40.00	× 10
Sub-Total :-		8,263.00		6,909.00	
Total Discount :-		--		690.90	
		8,263.00		6,218.10	
Special Nett Items :-					
1 set rear bumper reverse sensor	Dented / Malfunctioned	350.00		200.00	✓
Total For Parts :-		8,613.00		6,418.10	
Labour Charges :					

3704.20 S.N: 20  
 3333.78

Vehicle No : SMG 2878 E Nissan Sylphy (A)  
 Workshop : MG Solution Pte Ltd

TP/0130/19

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
Remove and replace the above listed parts, knock straighten and reshape, cut and weld body panel parts where necessary, reposition and realign, replacement parts to the original position including adjustment.		1,300.00		<del>1,000.00</del>	800
Apply rust coating on repaired and replaced panels.		100.00		60.00	✓
Check wiring and lighting system.		70.00		40.00	✓
Remove, reinstall and replace rear inner fenders, boards and trims to assist repairs.		240.00		<del>150.00</del>	80
Remove, reinstall and replace rear bumper reverse sensors and wire harness to assist repairs.		100.00		40.00	✓
Remove, reinstall and adjust boot lid reverse camera.		100.00		60.00	✓
Spray Painting :					
Putty and spray repaired and replaced body panels.		1,450.00		<del>1,200.00</del>	800
Grand Total :-		11,973.00		8,968.10	

Surveyed By : Lawrence Ng

1880

total: 5413.78

h/s: A.3K.

06 Days.