

Section A - Accident Details

Registration Number	SHB5636C
Case Reference Number	TAX/07/20/2054
Registration Date	17/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	CHAN SOO CHIEW
Type of Accident	Side Swipe
Accident Date and Time	27/7/2020 2:30 PM
Accident Reported Date and Time	27/7/2020 4:30 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107654
Special Instruction to ARC, if any	TP / LEFT SIDE MIRROR / NTUC - LKK
Prepared Date and Time	28/7/2020 10:25 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,296.00	\$530.00
Total Spare Part Cost	\$5,739.87	\$1,463.07
Total Other Cost	\$600.00	\$80.00
TOTAL COST	\$8,142.87	\$2,273.07 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	28/07/2020 10:37 AM	28/07/2020 12:38 PM
Signature		<i>Sun Pin</i>
Remarks		P/P, before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2008-0093	Invoice Number	
Quotation Date	13.08.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
RESPRAY MIRROR COVER LH	\$180.00	\$80.00
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,296.00	\$530.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$30.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
Total Other Costs	\$600.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53802-47100	FENDER SUB-ASSY, FR, LH	1.00	\$977.80	100.00	\$0.00	Replace	Repair
		53876-47060	LINER, FR FENDER, LH	0.00	\$210.30	0.00	\$0.00	Replace	Not Given
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$54.60	25.00	\$40.95	Replace	Replace
		61014-47020	PILLAR, FRONT BODY, LH	0.00	\$350.00	0.00	\$0.00	Replace	Not Given
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,879.40	100.00	\$0.00	Replace	Repair
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$668.90	0.00	\$0.00	Replace	Not Given
		67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,300.70	100.00	\$0.00	Replace	Repair
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		60118-47020	COVER SUB-ASSY, FRONT PILLAR, UPR LH	1.00	\$100.40	25.00	\$75.30	Replace	Replace
		87940-47440	MIRROR ASSY, OUTER REAR VIEW, LH	1.00	\$1,339.30	10.00	\$1,205.37	Replace	Replace
		87945-47060-A1	COVER, OUTER MIRROR, LH	1.00	\$108.60	25.00	\$81.45	Replace	Replace
		68126-47010	GLASS, FRONT DOOR FIX WINDOW, LH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/08/2020

User ID : PohSuan

		68216-47010	WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH	0.00	\$76.40	0.00	\$0.00	Replace	Check <input checked="" type="checkbox"/>
Total					\$7,323.04		\$1,463.07		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1463.07 /
 + 200.00 /
 + 610.00 /

 2273.07 /

P/P

\$ 2,273.07

2 days