



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Date: 15 November 2019

Your Ref: CMTD1902127

Our Ref: TP-0228/10/19

Motor Claims Department
M/s. Sompo Insurance Pte. Ltd.
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

Attention: Mr. Gnoh Pau Loong

Dear Sir,

Inspection of 2017 Toyota Dyna Lorry (M)
Registration No.: GBG 1953 H
Odometer Reading: 25953 km
Chassis No.: KDY23-I8029040

We refer to your instructions to us to conduct a paper survey of the above vehicle. A pre-repair survey was conducted on 03-05-2019 and resurvey after repairs on 08-05-2019. The repairer did not arrange for further inspections during repairs.

The following documents were received: -

- 1) Copy of survey reports by M/s. Sincere Appraisal Services Pte Ltd
- 2) 42 copies of photos depicting damages sustained by GBG 1953 H
- 3) Accident reports by drivers of GBG 1953 H and SLP 4412 S

The vehicle sustained rear damages during an accident on 30-04-2019.

Repair cost submitted was \$6,700.00 lump-sum.

We append below our findings: -

<u>Replacement of Parts</u>		<u>Revised Amount</u>	<u>Our Recommendation</u>
1pc.	Rear tail gate assy – repairable	\$ 1,697.00	\$ -
4pcs.	Rear tail gate hinges – repairable	260.00	-
2pcs.	Rear tail gate reflector – serviceable	166.00	-
1pc.	Rear tail gate left lower lock hinge	176.00	176.00
2pcs.	Rear tail gate left rubber stopper	28.00	28.00
1pc.	Rear tail gate left rubber stopper bracket	58.00	58.00
1pc.	Rear left tail lamp	562.00	562.00

1pc.	Rear left tail lamp bracket	\$ 114.00	\$ 114.00
2pcs.	Rear tail lamp bracket round reflector – 1pc LH	244.00	122.00
2pcs.	Rear number plate lamp – no evidence of damage	89.00	-
1pc.	Rear number plate support bracket	120.00	120.00
1pc.	Rear hook	180.00	180.00
1pc.	Rear spare tyre bracket carrier – no evidence of damage	380.00	-
1pc.	Rear spare tyre lock holder – no evidence of damage	283.00	-
		<u>4,357.00</u>	<u>1,360.00</u>
	Less 25%	<u>1,089.25</u>	<u>340.00</u>
		<u>\$ 3,267.75</u>	<u>\$ 1,020.00</u>

Special Nett Items:-

1pc.	Rear tail gate 70km/h sticker	\$ 30.00	\$ 15.00
1pc.	Rear tail gate 12pax sticker	30.00	15.00
1pc.	Rear tail gate 1500kg sticker	30.00	15.00
1pc.	Rear tail gate DYNA sticker	30.00	20.00
1set	Rear tail gate sticker – not fitted	30.00	-
1pc.	Rear tail gate aluminium plate – reused/not necessary	650.00	-
1pc.	Rear step panel – bracket	250.00	80.00
1pc.	Rear centre towing panel – crossmember	650.00	400.00
1pc.	Rear spare tyre – serviceable	450.00	-
1pc.	Rear left lower luggage box assy	650.00	250.00
1pc.	Rear left lower luggage box bracket	200.00	120.00
1pc.	Rear number plate	80.00	40.00
		<u>6,347.75</u>	<u>1,975.00</u>
	Total For Parts:-	<u>\$ 6,347.75</u>	<u>\$ 1,975.00</u>

Labour Charges:-

Labour for panel beating rear affected area and replace rear damaged parts. – repair tail gate, floor panel, end panel	\$ 800.00	\$ 800.00
To putty and spray painting rear portion.	800.00	600.00
To check rear lighting and wiring.	30.00	30.00
To apply anti rust proofing to rear affected area.	100.00	50.00
To remove and install rear left tail gate lock.	60.00	30.00
To remove and install rear tail gate aluminium plate. – not necessary	100.00	-
Towing service.	80.00	80.00
	<u>8,317.75</u>	<u>3,565.00</u>
Total:-	<u>\$ 8,317.75</u>	<u>\$ 3,565.00</u>

Lump-sum repairs: \$ 6,700.00 \$ 2,850.00

Estimated period of repairs: 5 working days

Pre-accident Market Value : About \$ 58,000.00

COE rebate : \$ 30,005.00

Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA
Motor Appraiser

Surveyed by:



LAWRENCE NG, MSAAA
Motor Appraiser