



No. 51 Ubi Avenue 1 #01-04
Paya Ubi Industrial Park
Singapore 408933
Tel : 6747 5277 Fax : 6444 0200
Co.Reg.No. : 201707802C

Store (LKK)
OD - Not Auth -
EX - \$5000
P/P, R, B/L

Quotation No. : 110820
Date : 4/8/20
No. of Pages : 1 of 2
GST.Reg.No. : 201707802C
10 repair days

Vehicle No. : SMS 1059 X
Make / Model : Lotus Elise SC 1.8 MT
Vin : SCCZC11158HN31928

S/NO.	Parts Description	QTY	SGD \$
1	Front Clam Shell / <i>OR</i>	1	\$ 8,500.00
2	Rear Clam Shell / <i>OR</i>	1	\$ 9,000.00
3	Door Hinge Cover Panel RH / <i>OR</i>	1	\$ 650.00
4	Bracket Front Liner / Access Panel Mounting / <i>MC</i>	1	\$ 25.00
5	Pop Rivet Domed Black Bracket to Clam Shell / <i>MC</i>	4	\$ 46.00
6	Grille Front Intake RH / <i>OR</i>	1	\$ 85.00
7	Grille Rear Transom RH / <i>OT</i>	1	\$ 55.00
8	Clip Central Grille Retention / <i>MC</i>	4	\$ 72.00
9	Bracket Clip to Clam Shell / <i>MC</i>	4	\$ 180.00
10	Pop Rivet 3.2mm x 11mm Black bracket to Clam shell / <i>MC</i>	4	\$ 40.00
11	Clip Outer Grilles Retention / <i>MC</i>	2	\$ 34.00
12	Seal Neoprene Grille to Clam shell / <i>MC</i>	1	\$ 13.00
13	Grille Perforated Oval holes rear body to diffuser RH / <i>OT</i>	1	\$ 125.00
14	ECE inboard Lamp RH-? LH- <i>OR</i>	2	\$ 1,520.00
15	ECE Outboard Lamp RH-? LH- <i>OR</i>	2	\$ 1,460.00
16	Headlamp Assembly RH / <i>OR</i>	1	\$ 1,500.00
17	Headlamp Assembly LH / ?	1	\$ 1,500.00
18	Lamp front indicator RH / <i>OR</i>	1	\$ 245.00
19	Lamp front indicator LH / ?	1	\$ 245.00
20	Glass, Flat 1 Set (mirror) / <i>OR</i>	2	\$ 290.00
21	Diffuser Assembly Silver / <i>OT</i>	1	\$ 635.00
22	Aerofoil Assembly body mounted 10' MY (rear spl) / <i>OR</i>	1	\$ 415.00
23	Plinth Mirror Mounting (mirror) / <i>MC</i>	1	\$ 35.00
24	Engine Coverlid No Antenna Hole / <i>OR</i>	1	\$ 560.00
25	Grille Front intake central with driving lamp / <i>OR (RH)</i>	1	\$ 145.00
26	Oil Cooler RH / <i>DD</i>	1	\$ 480.00
27	Stud plate bracket Fixing Rear / <i>MC</i>	1	\$ 20.00
28	Stud plate bracket Fixing Front / <i>MC</i>	1	\$ 35.00
29	Striker / Lift assembly engine cover lid / <i>OT</i>	1	\$ 610.00
30	Bracket latch retention / ?	1	\$ 75.00
31	Latch assembly (lock pin) / <i>MC</i>	1	\$ 65.00
32	Badge Lotus raised Chrome Letters / <i>MC</i>	1	\$ 30.00
33	Lower ARM Front RH / ?	1	\$ 500.00
34	Lower ARM Rear RH / ?	1	\$ 550.00
35	Upper Arm Front RH / ?	1	\$ 420.00
36	Upper Arm Rear RH / ?	1	\$ 420.00
37	Oil cooler Hose Front / ?	1	\$ 150.00
38	Mirror Housing / <i>OR</i>	2	\$ 720.00
Remarks :		Parts Total :	\$ 31,450.00
		15% :	\$ 36,167.50

760
730



No. 51 Ubi Avenue 1 #01-04
Paya Ubi Industrial Park
Singapore 408933
Tel : 6747 5277 Fax : 6444 0200
Co.Reg.No. : 201707802C

Quotation No. : 110820
Date : 11/8/2020
No. of Pages : 2 of 2

GST.Reg.No. : 201707802C

Vehicle No. : SMS 1059 X

Make / Model : Lotus Elise SC 1.8 MT

Vin : SCCZC11158HN31928

S/NO.	Labour Description	Repairer's Estimate (\$\$)
1	To check electrical system and repair wire hardness for front bumper.	\$ 200 250.00
2	To transfer front bumper component to new front bumper	\$ 250 300.00
3	To remove and reinstall front interior trims, granishes, etc for necessary repairs	\$ 250 300.00
4	To remove and reinstall exhaust silencer for necessary repairs	\$ 250 300.00
5	To straighten, repair, realign on affected area and replace damaged parts for front bumper	\$ 2000 2,400.00
6	To check electrical system and repair wire hardness for rear bumper	\$ 200 250.00
7	To transfer tailgate component parts to new tailgate	\$ 200 250.00
8	To remove, replace and / or transfer rear reverse sensors & control unit	\$ 200 300.00
9	To straighten, repair, realign on affected area and replace damaged parts for rear bumper	\$ 2000 2,400.00
10	To conduct chassis alignment	\$? 350.00
11	To spray painting, blending on effected and adjacent area including right hand side skirt	1700 \$ 1500 2,000.00
12	To spray anti-rust coating on new and affected panels	\$ 100 400.00
13	To remove, replace and reinstall suspension for front right hand and rear right hand	\$? 500.00
14	To inspection, diagnosis, reset and perform coding programming on:- I) Rear reverse camera and sensor systems II) Security lock and rear boot system	\$ 300 500.00
15	To remove and repair drive shaft	\$? 300.00
16	To remove and replace rim tyres, including tyres balancing.	\$? 400.00

Labour Total :

\$ 11,200.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: