



No. 51 Ubi Avenue 1 #01-04  
Paya Ubi Industrial Park  
Singapore 408933  
Tel : 6747 5277 Fax : 6444 0200  
Co.Reg.No. : 201707802C

*Stew (LKK)*

*OD - Not Author -*

*Excess - \$ 5000*

*PIP, Ry BL*

Quotation No.

Date

No. of Pages

GST.Reg.No. : 201707802C

110820

11/8/2020

1 of 2

*4/8/20*

*10 repair days*


Vin : SCCZC11158HN31928

Vehicle No. : SMS 1059 X

Make / Model : Lotus Elise SC 1.8 MT

| S/NO.         | Parts Description                                               | QTY | SGD \$       |
|---------------|-----------------------------------------------------------------|-----|--------------|
| 1             | Front Clam Shell <i>OR</i>                                      | 1   | \$ 8,500.00  |
| 2             | Rear Clam Shell <i>OR</i>                                       | 1   | \$ 9,000.00  |
| 3             | Door Hinge Cover Panel RH <i>OR</i>                             | 1   | \$ 650.00    |
| 4             | Bracket Front Liner / Access Panel Mounting <i>MC</i>           | 1   | \$ 25.00     |
| 5             | Pop Rivet Domed Black Bracket to Clam Shell <i>MC</i>           | 4   | \$ 46.00     |
| 6             | Grille Front Intake RH <i>OR</i>                                | 1   | \$ 85.00     |
| 7             | Grille Rear Transom RH <i>OT</i>                                | 1   | \$ 55.00     |
| 8             | Clip Central Grille Retention <i>MC</i>                         | 1   | \$ 72.00     |
| 9             | Bracket Clip to Clam Shell <i>MC</i>                            | 4   | \$ 180.00    |
| 10            | Pop Rivet 3.2mm x 11mm Black bracket to Clam shell <i>MC</i>    | 4   | \$ 40.00     |
| 11            | Clip Outer Grilles Retention <i>MC</i>                          | 4   | \$ 34.00     |
| 12            | Seal Neoprene Grille to Clam shell <i>MC</i>                    | 2   | \$ 13.00     |
| 13            | Grille Perforated Oval holes rear body to diffuser RH <i>OT</i> | 1   | \$ 125.00    |
| 14            | ECE inboard Lamp <i>RH - 9 x MM LH - OR</i>                     | 2   | \$ 1,520.00  |
| 15            | ECE Outboard Lamp <i>RH - 7 x MM LH - OR</i>                    | 2   | \$ 1,460.00  |
| 16            | Headlamp Assembly RH <i>OR</i>                                  | 1   | \$ 1,500.00  |
| 17            | Headlamp Assembly LH <i>9 x MM</i>                              | 1   | \$ 1,500.00  |
| 18            | Lamp front indicator RH <i>OR</i>                               | 1   | \$ 245.00    |
| 19            | Lamp front indicator LH <i>9 x MM</i>                           | 1   | \$ 245.00    |
| 20            | Glass, Flat 1 Set <i>(mirror) - OR</i>                          | 2   | \$ 290.00    |
| 21            | Diffuser Assembly Silver <i>OT</i>                              | 1   | \$ 635.00    |
| 22            | Aerofoil Assembly body mounted 10' MY <i>(rear split) - OR</i>  | 1   | \$ 415.00    |
| 23            | Plinth Mirror Mounting <i>(mirror) - MIS</i>                    | 1   | \$ 35.00     |
| 24            | Engine Coverlid No Antenna Hole <i>OR</i>                       | 1   | \$ 560.00    |
| 25            | Grille Front intake central with driving lamp <i>OR (RH)</i>    | 1   | \$ 145.00    |
| 26            | Oil Cooler RH <i>DD</i>                                         | 1   | \$ 480.00    |
| 27            | Stud plate bracket Fixing Rear <i>MIS</i>                       | 1   | \$ 20.00     |
| 28            | Stud plate bracket Fixing Front <i>MIS</i>                      | 1   | \$ 35.00     |
| 29            | Striker / Lift assembly engine cover lid <i>OT</i>              | 1   | \$ 610.00    |
| 30            | Bracket latch retention <i>9 x MM</i>                           | 1   | \$ 75.00     |
| 31            | Latch assembly <i>(lock pin) - Jem. P.J</i>                     | 1   | \$ 65.00     |
| 32            | Badge Lotus raised Chrome Letters <i>MC</i>                     | 1   | \$ 30.00     |
| 33            | Lower ARM Front RH <i>9 x MM</i>                                | 1   | \$ 500.00    |
| 34            | Lower ARM Rear RH <i>9 x MM</i>                                 | 1   | \$ 550.00    |
| 35            | Upper Arm Front RH <i>9 x MM</i>                                | 1   | \$ 420.00    |
| 36            | Upper Arm Rear RH <i>OT</i>                                     | 1   | \$ 420.00    |
| 37            | Oil cooler Hose Front <i>9 x MM</i>                             | 1   | \$ 150.00    |
| 38            | Mirror Housing <i>OR</i>                                        | 2   | \$ 720.00    |
| Parts Total : |                                                                 |     | \$ 31,450.00 |
| 15% :         |                                                                 |     | \$ 36,167.50 |

Remarks :



|                                                                                                                                          |                                             |                                |           |
|------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|--------------------------------|-----------|
| No. 51 Ubi Avenue 1 #01-04<br>Paya Ubi Industrial Park<br>Singapore 408933<br>Tel : 6747 5277 Fax : 6444 0200<br>Co.Reg.No. : 201707802C | Quotation No.                               | :                              | 110820    |
|                                                                                                                                          | Date                                        | :                              | 11/8/2020 |
|                                                                                                                                          | No. of Pages                                | :                              | 2 of 2    |
|                                                                                                                                          | GST.Reg.No. : 201707802C                    |                                |           |
| Vehicle No. : <u>SMS 1059 X</u>                                                                                                          | Make / Model : <u>Lotus Elise SC 1.8 MT</u> | Vin : <u>SCCZC11158HN31928</u> |           |

| S/NO. | Labour Description                                                                                                                                          | Repairer's Estimate (\$\$) |
|-------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|
| 1     | To check electrial system and repair wire hardness for front bumper.                                                                                        | \$ 200 250.00              |
| 2     | To transfer front bumper component yo new front bumper                                                                                                      | \$ 250 300.00              |
| 3     | To remove and reinstall front interior trims, granishes, etc for necessary repairs                                                                          | \$ 250 300.00              |
| 4     | To remove and reinstall exhaust silencer for necessary repairs                                                                                              | \$ 250 300.00              |
| 5     | To straighten, repair, realign on affected area and replace damaged parts for front bumper                                                                  | \$ 2000 2,400.00           |
| 6     | To check eletrical system and repair wire hardness for rear bumper                                                                                          | \$ 200 250.00              |
| 7     | To transfere tailgate component parts to new tailgate                                                                                                       | \$ 200 250.00              |
| 8     | To remove , replace and / or transfer rear reverse sensors & contro unit                                                                                    | \$ 200 300.00              |
| 9     | To straighte, repair, realign on affected area and replace damaged parts for rear bumper                                                                    | \$ 2000 2,400.00           |
| 10    | To conduct chassus alignment                                                                                                                                | \$ ? 350.00                |
| 11    | To spray painting, blending on effected and adjacent area including right hand side skirt                                                                   | 1700 \$ 1500 2,000.00      |
| 12    | To spray anti-rust coating on new and affected panels                                                                                                       | \$ 100 400.00              |
| 13    | To remove , replace and reinstall suspension for front right hand and rear right hand                                                                       | 300 \$ ? 500.00            |
| 14    | To inspection, diagnosis , reset and perform coding programming on:-<br>I) Rear reverse camera and sensor systems<br>II) Security lock and rear boot system | \$ 300 500.00              |
| 15    | To remove and repair drive shaft                                                                                                                            | \$ ? X 300.00              |
| 16    | To remove and replace rim tyres, including tyres                                                                                                            | 200 \$ ? 400.00            |

**LKK Auto Consultants** hence notify

the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) to be supplied and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**\$ 11,200.00**

**47,367.50**