



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2007087
INV Date 19/10/2020
Reference CC6/LPC20007970/Ubs3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. GBH 5870G
Insured Veh. YM 8542K
Claim No. 20/20/20/VC00/023513
Policy No. Z/20/VC00/106989
Accident Date 01/08/2020
Inspection Date 03/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC20007970/Ubs3q2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 19-10-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 8542K	Veh. Inspected	GBH 5870G
Policy No.	Z/20/VC00/106989	Coverage (\$)	0.00
Claim No.	20/20/20/VC00/023513	Excess (\$)	0.00
Assign From		Assign Date	03/08/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200 (M)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	VSKYBAM20Z0155661	Colour	GREY
Odometer	41065	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	DUNLOP	6 mm
L/H Front Tyre	175/70 R14	DUNLOP	6 mm
R/H Rear Tyre	175/70 R14	DUNLOP	6 mm
L/H Rear Tyre	175/70 R14	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/08/2020	Inspection Date	03/08/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 5870G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR FENDER N/S	BADLY DENTED	2,945.10	1,553.00
1	SLIDING DOOR N/S	TO REPAIR SEE LABOUR	1,945.20	-
1	SLIDING DOOR GLASS N/S	CUT	950.00	650.00
	LESS 10% DISCOUNT		-	-220.30
			5,840.30	1,982.70
<u>SPECIAL NETT ITEMS</u>				
1	SLIDING DOOR GLASS SEALANT N/S (SN)	NECESSARY	50.00	40.00
1	SLIDING DOOR GLASS INNER SEAL N/S (SN)	NECESSARY	50.00	30.00
			100.00	70.00
<u>LABOUR</u>				
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO DISMANTLE & REPLACED SLIDING DOOR GLASS.		150.00	100.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF SLIDING DOOR N/S.		1,000.00	600.00
	TO PUTTY & SPRAY PAINTING.		880.00	400.00
			2,160.00	1,130.00
GRAND TOTAL			8,100.30	3,182.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CC6/LPC20007970/Ubs3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 5870G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 5870G

RE-INSPECTION

