

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Estimate No: EST2000150
Date: 03 Aug 2020

Veh Reg No: SGY5360M
Make/Model: MITSUBISHI LANCER
1.5 MIVEC GLS 4 A/T
Chasis No: JMYSRCY2A8U001302
Reg. Date: 28/09/2007
Your Ref No: SLH2672M

Claim Type: Third Party
Accident Date: 30/07/2020
TP Veh Reg No: SLH2672M

Estimate Repair Cost to Vehicle No :SGY5360M

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC BONNET <i>Dented</i>	662.00 ✓	
2	2 PCS BONNET HINGES <i>new</i>	142.00 +	
3	1 PC BONNET RUBBER <i>new</i>	58.00 +	
4	1 PC BONNET LOCK <i>Dented</i>	164.00 ✓	
5	1 PC FRT BRACE PANEL <i>Best</i>	91.00 ✓	
6	1 PC FRT SUPPORT TOP PANEL <i>Best</i>	525.00 ✓	
7	1 PC FRT SUPPORT PANEL TOP COVER <i>Dented</i>	101.00 ✓	
8	1 PC HEADLAMP LH <i>cracked</i>	691.00 ✓	
9	1 PC HEADLAMP PANEL LH <i>new</i>	135.00 +	
10	1 PC HEADLAMP RH <i>cracked</i>	691.00 ✓	
11	1 PC HEADLAMP PANEL RH <i>new</i>	135.00 +	
12	1 PC FRT GRILLE <i>cracked</i>	256.00 ✓	
13	1 PC FRT GRILLE EMBLEM <i>new</i>	51.00 ✓	
14	1 PC FRT GRILLE CHROME <i>cracked</i>	177.00 ✓	
15	1 PC FRT BUMPER <i>Disfected</i>	810.00 ✓	
16	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	320.00 ✓	
17	1 PC FRT BUMPER UPPER BEAM <i>Best</i>	170.00 ✓	
18	2 PCS FRT BUMPER SIDE RETAINERS <i>new</i>	72.00 ✓	
19	1 PC FRT BUMPER FOG LAMP RH <i>2</i>	286.00 +	
20	1 PC FRT BUMPER FOG LAMP COVER RH <i>new</i>	71.00 +	
21	1 PC FRT BUMPER FOG LAMP LH <i>new</i>	286.00 +	
22	1 PC FRT BUMPER FOG LAMP COVER LH	71.00 +	
23	1 PC FRT BUMPER GRILLE <i>Dented</i>	112.00 ✓	
24	1 PC FRT BUMPER SPOILER RH <i>2 repair</i>	362.00 +	
25	1 PC FRT BUMPER SPOILER LH	362.00 +	
26	1 PC FRT TOWING COVER <i>Dented</i>	48.00 ✓	
27	1 PC HORN <i>new</i>	121.00 +	
28	1 PC FRT WIPER WATER TANK <i>new</i>	108.00 +	
29	1 PC FRT BUMPER TOP RUBBER <i>new</i>	71.00 +	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD

190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199

FAX: 6725 0853

ATTN: Motor Claim Department

Estimate No: EST2000150

Date: 03 Aug 2020

Veh Reg No: **SGY5360M**

Make/Model: MITSUBISHI LANCER
1.5 MIVEC GLS 4 A/T

Chasis No: JMYSRCY2A8U001302

Reg. Date: 28/09/2007

Your Ref No: SLH2672M

Claim Type: Third Party

Accident Date: 30/07/2020

TP Veh Reg No: SLH2672M

Estimate Repair Cost to Vehicle No :SGY5360M

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
30	1 PC RADIATOR <i>3 new</i>	1,116.00 <i>x</i>	
31	1 PC RADIATOR FAN	80.00 <i>x</i>	
32	1 PC RADIATOR FAN MOTOR COWLING ASSY <i>new</i>	368.00 <i>x</i>	
33	1 PC AIR CONDENSER <i>Best</i>	969.00 <i>✓</i>	
34	1 PC AIRCON DISCHARGE PIPE <i>3 new</i>	263.00 <i>x</i>	
35	1 PC AIRCON RECEIVER PIPE	196.00 <i>x</i>	
36	1 PC BOOT LID <i>Dented</i>	669.00 <i>✓</i>	
37	1 PC BOOT LID LOGO <i>new</i>	66.00 <i>✓</i>	
38	1 PC BOOT LID LANCER EMBLEM <i>3 new</i>	52.00 <i>✓</i>	
39	1 PC BOOT LID EX EMBLEM	34.00 <i>✓</i>	
40	1 PC BOOT LID TRIM <i>new</i>	202.00 <i>x</i>	
41	1 PC BOOT LID LOCK <i>Damaged</i>	160.00 <i>✓</i>	
42	1 PC BOOT LID LOCK CHECKER <i>new</i>	<i>x</i> 41.00 <i>✓</i>	
43	1 PC BOOT LID RUBBER <i>lit</i>	185.00 <i>✓</i>	
44	1 PC REAR PANEL <i>Dented</i>	438.00 <i>✓</i>	
45	1 PC REAR PANEL TRIM <i>Dented</i>	172.00 <i>✓</i>	
46	1 PC REAR FENDER INNER TRIM LH <i>new</i>	254.00 <i>x</i>	
47	1 PC REAR FENDER INNER TRIM RH <i>torn</i>	254.00 <i>✓</i>	
48	1 PC TAIL LAMP LH <i>cracked</i>	320.00 <i>✓</i>	
49	1 PC TAIL LAMP RH <i>new</i>	320.00 <i>x</i>	
50	1 PC SPARE TYRE PANEL <i>Reps</i>	776.00 <i>x</i>	
51	1 PC SPARE TYRE COVER <i>new</i>	177.00 <i>x</i>	
52	1 PC REAR BUMPER <i>Distorted</i>	669.00 <i>✓</i>	
53	1 PC REAR BUMPER REINFORCEMENT <i>Best</i>	196.00 <i>✓</i>	
54	2 PCS REAR BUMPER SIDE RETAINERS <i>new</i>	68.00 <i>✓</i>	
55	2 PCS REAR BUMPER REFLECTORS <i>cracked</i>	80.00 <i>✓</i>	
56	1 PC REAR BUMPER TOWING COVER <i>missing</i>	31.00 <i>✓</i>	
57	2 PCS REAR NUMBER PLATE LAMPS <i>new</i>	162.00 <i>x</i>	
58	1 PC EXHAUST PIPE TOP ALUMINIUM PLATE <i>new</i>	277.00 <i>x</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD

190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199

FAX: 6725 0853

ATTN: Motor Claim Department

Estimate No: EST2000150

Date: 03 Aug 2020

Veh Reg No: SGY5360M

Make/Model: MITSUBISHI LANCER
1.5 MIVEC GLS 4 A/T

Chasis No: JMYSRCY2A8U001302

Reg. Date: 28/09/2007

Your Ref No: SLH2672M

Claim Type: Third Party

Accident Date: 30/07/2020

TP Veh Reg No: SLH2672M

Estimate Repair Cost to Vehicle No :SGY5360M

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
		15,744.00	
	Less 10%	1,574.40	14,169.60
	Special Net		
59	1 SET FRT SUPPORT PANEL TOP COVER CLIPS <i>see</i>	40.00 <i>20</i>	
60	1 SET FRT GRILLE CLIPS <i>see</i>	30.00 <i>20</i>	
61	1 SET FRT BUMPER GRILLE CLIPS <i>see</i>	30.00 <i>20</i>	
62	1 PC FRT NUMBER PLATE <i>Best</i>	50.00 <i>✓</i>	
63	1 SET FRT BUMPER CLIPS <i>see</i>	40.00 <i>30</i>	
64	1 SET BOOT LID TRIM CLIPS <i>see in</i>	40.00 <i>+</i>	
65	1 SET REAR PANEL TRIM CLIPS <i>see</i>	30.00 <i>10</i>	
66	1 SET REAR FENDER INNER TRIM CLIPS LH <i>see in</i>	40.00 <i>+</i>	
67	1 SET REAR FENDER INNER TRIM CLIPS RH <i>see</i>	40.00 <i>30</i>	
68	1 SET REVERSE SENSORS <i>Damaged</i>	250.00 <i>20</i>	
69	1 SET REAR BUMPER CLIPS <i>see</i>	40.00 <i>30</i>	
70	1 PC REAR NUMBER PLATE <i>Best</i>	50.00 <i>✓</i>	
		680.00	680.00
	Labour		
71	1 TO REMOVE AND REPLACE THE FRONT DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,400.00 <i>800</i>	
72	1 TO SPRAY PAINTING FRONT PORTION	1,300.00 <i>800</i>	
73	1 TO SPRAY UNDERSEAL (FRONT)	100.00 <i>50</i>	
74	1 TO CHECK FRONT WIRING	50.00 <i>30</i>	
75	1 TO REFILL AIRCON GAS	120.00 <i>✓</i>	
76	1 TO REMOVE AND REPLACE THE REAR DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,400.00 <i>800</i>	
77	1 TO SPRAY PAINTING REAR PORTION	1,500.00 <i>800</i>	
78	1 TO SPRAY UNDERSEAL (REAR)	120.00 <i>60</i>	
79	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00 <i>+</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD

190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199

FAX: 6725 0853

ATTN: Motor Claim Department

Estimate No: EST2000150

Date: 03 Aug 2020

Veh Reg No: SGY5360M

Make/Model: MITSUBISHI LANCER
1.5 MIVEC GLS 4 A/T

Chasis No: JMYSRCY2A8U001302

Reg. Date: 28/09/2007

Your Ref No: SLH2672M

Claim Type: Third Party

Accident Date: 30/07/2020

TP Veh Reg No: SLH2672M

Estimate Repair Cost to Vehicle No :SGY5360M

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
80	1 TO REMOVE AND REPLACE REAR BOOT TRIM	100.00 60	
81	1 TO REMOVE AND REPLACE REVERSE SENSOR	100.00 50	
82	1 TO CHECK REAR WIRING	50.00 30	
		3600	
		6.390.00	6.390.00
	Total		S\$ 21,239.60
	Add GST @ 7%		1,486.77
	Total Amount Payable		<u>S\$ 22,726.37</u>

TOTAL: SINGAPORE DOLLAR TWENTY TWO THOUSAND SEVEN HUNDRED TWENTY SIX AND CENTS THIRTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

Adrian Lj
1/5 04/08/20

12 Days.

total: 12470.50

1/5 : 8K (Nett Value)

8K.

14 Days.