

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 26 Aug 2020

## **Preliminary Advice**

Insured Vehicle No : GBE1272A

TP Vehicle No : YP4951Z

Accident Date : 29/07/2020

Make : ISUZU NPR85UH5A

Assignment Date : 03/08/2020

Date of Inspection : 04/08/2020

Est. Duration of Repair : 8

Inspection At : CHENG HOE MOTOR PTE LTD (YISHUN)  
BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A  
SINGAPORE 768761

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear front portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 10,672.55 |
| Revised Amount              | :S\$ | 8,735.30  |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 8,735.30  |
| Lump Sum Repair             | :S\$ | 6,950.00  |

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( x ) Lump Sum repair

- ( ) The above survey was conducted on a 'without prejudice' basis.