

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd  
20 McCallum Street  
#09-01 Tokio Marine Centre  
Singapore 069046

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ong Chin Kiat

Date: 05 Aug 2020

**Preliminary Advice**

Insured Vehicle No	: SMD3015M	Accident Date	: 30/07/2020
TP Vehicle No	: SHB6202P	Assignment Date	: 03/08/2020
Make	: HYUNDAI I40	Est. Duration of Repair	: 9
Date of Inspection	: 04/08/2020		
Inspection At	: BIFROST AUTO PTE LTD (HQ) 176 SIN MING DRIVE, #03-09 SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,562.32
Revised Amount	:S\$	26,525.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	26,525.40

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :