



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20007979/Evf3e2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 17-08-2020



Code : AGI

#### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SGB 7589D	<b>Veh. Inspected</b>	SME 8158X
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10006882	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IVY RATILLA	<b>Assign Date</b>	03/08/2020

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MITSUBISHI ATTRAGE 1.2	<b>c.c</b>	1193
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	MMBSTA13AJH003599	<b>Colour</b>	BLUE
<b>Odometer</b>	27466	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

#### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	185/60 R15	DUNLOP	5 mm
<b>L/H Front Tyre</b>	185/60 R15	DUNLOP	5 mm
<b>R/H Rear Tyre</b>	185/60 R15	DUNLOP	5 mm
<b>L/H Rear Tyre</b>	185/60 R15	DUNLOP	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

#### 5. General Information

<b>Accident Date</b>	01/08/2020	<b>Inspection Date</b>	04/08/2020
<b>Survey held at</b>	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>8 Working Days</b>
-------------------------------------	-----------------------