

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20007983/T1DA3Q2  
**Date:** 28/08/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100437986
<b>Claimant</b>		
<b>Vehicle No :</b> SHD1108B	<b>Insured Vehicle No :</b>	GBA7480Y
Date of Loss: 31/07/2020	Nature of Claim: TP	Claim No: 3660863745SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD1108B</b>		
Make & Model:	KIA OPTIMA, 1.7 D (A)	Engine No:	D4DFDH314360
Reg. Date:	03/02/2016 (Man. Year: 2015)	Chassis No:	KNAGM414MF5659495
Colour:	Silver	Odometer:	375944 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	957.90	808.50	149.40	15.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	490.00	530.00	51.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,977.90</b>	<b>1,298.50</b>	<b>679.40</b>	<b>34.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,000.00</b>		
	<b>(S\$)</b>	1,977.90	1,000.00	977.90 49.44
	<b>+ GST 7.00/7.00% (S\$)</b>	138.45	70.00	68.45 49.44
	<b>Nett Amount (S\$)</b>	<b>2,116.35</b>	<b>1,070.00</b>	<b>1,046.35 49.44</b>
	<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>	

INSPECTION

Date of Assignment:	03/08/2020	
Date Inspected:	04/08/2020	Inspected At: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR N/S DOOR	Bent	765.00 FL	*765.00 FL	
2	2		*REAR N/S DOOR HINGES	Repair	66.00 FL	*- FL	
3	1		*REAR N/S FENDER STICKER	Not Necessary	60.00 FS	*- FS	
4	1		*SET N/S DOOR STICKER	Necessary	100.00 FS	*100.00 FS	
5	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS	
					<b>Sub Total (\$\$)</b>	<b>1,041.00</b>	<b>885.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	83.10	76.50
					<b>Total Parts (\$\$)</b>	<b>957.90</b>	<b>808.50</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE AND REFIT THE REAR N/S DOOR INNER COMPONENT INTO NEW SHELL DOOR	New	150.00	60.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE REAR N/S FENDER ,ETC	New	350.00	200.00
3	TO PUTTY AND SPRAY PAINTING ON REAR N/S DOOR ,REAR N/S FENDER	New	400.00	200.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,020.00</b>	<b>490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >