

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007985/KPA3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100467237

Claimant
Vehicle No : SLD9765D **Insured Vehicle No :** SJY241X

Date of Loss: 31/07/2020 Nature of Claim: TP Claim No: 5442118628SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD9765D		
Make & Model:	HONDA JAZZ, 1.3 CVT (A)	Engine No:	L13B11010300
Reg. Date:	01/07/2016 (Man. Year: 2016)	Chassis No:	JHMGK3850GX240592
Colour:	Metallic Maroon	Odometer:	74003 km
Engine Capacity:	1318 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,596.80	2,402.24	194.56	7.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	1,760.00	360.00	16.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,716.80	4,162.24	554.56	11.76
Approved Total (Overridden) (\$\$)		3,300.00		
(\$\$)	4,716.80	3,300.00	1,416.80	30.04
+ GST 7.00/7.00% (\$\$)	330.18	231.00	99.18	30.04
Nett Amount (\$\$)	5,046.98	3,531.00	1,515.98	30.04
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		8.00		
Nett Liability (\$\$)		3,899.00		

INSPECTION

Date of Assignment: 03/08/2020

Date Inspected: 03/08/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Bent	435.60 FL	*435.60 FL
2	1		*FRONT RH FENDER INNER SHIELD	Cracked	71.50 FL	*71.50 FL
3	6		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	23.40 FL	*23.40 FL
4	1		*FRONT RH DOOR	Bent	1,050.20 FL	*1,050.20 FL
5	1		*FRONT RH DOOR FRAME STICKER	Necessary	20.20 FL	*20.20 FL
6	1		*FRONT RH DOOR INNER RUBBER	Serviceable	83.10 FL	*- FL
7	1		*FRONT RH DOOR TOP HINGE	Bent	40.10 FL	*40.10 FL
8	1		*FRONT RH DOOR BOTTOM HINGE	Bent	40.10 FL	*40.10 FL
9	1		*FRONT RH SHOCK ABSORBER	Bent	310.90 FL	*310.90 FL
10	1		*FRONT RH KNUCKLE ARM	Necessary	280.30 FL	*280.30 FL
11	1		*FRONT RH WHEEL BEARING	Necessary	168.00 FL	*168.00 FL
12	1		*FRONT RH LOWER ARM	Serviceable	160.10 FL	*- FL
13	1		*FRONT RH SPORT RIM	Dented	450.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,133.50	2,890.30
- List Item Discount on L Items 20.00/20.00% (\$)	536.70	488.06
Total Parts (\$)	2,596.80	2,402.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT BUMPER ASSY ,FRT RH FENDER ,FRT RH DOOR & ATTACHMENT ,SIDE MIRROR ,KNOCK & REPAIR FRT RH W/SCREEN PILLAR & REALIGN THE SAME	New	800.00	600.00
2	REMOVE & REFIX SEAT ,CARPET SAFETY BELT	New	100.00	60.00
3	REMOVE & REFIX FRT RH UNDER CARRIAGE AND CHECK STEERING & DRIVE SHAFT	New	200.00	180.00
4	PUTTY & RESPRAY ON FRT RH W/SCREEN PILLAR ,RH ROCKER PANEL ,FRT RH SIDE MIRROR ,FRT RH FENDER ,FRT RH DOOR ,FRT BUMPER & ALL AFFECTED AREAS	New	900.00	800.00
5	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
6	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			2,120.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >