

dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

03 AUG 2020

ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 55655
Date Estimated : 01/08/2020
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR -
Tan Chee Kiong
33 Lorong G
Telok Kurau
Singapore
Singapore 426204

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL551H	WBAKB22090C951160	11/11/2011	730LiA	0

DESCRIPTION

To replace rear bumper panel and attachments, rework bootlid and tail panel

2550 ~~3,825.00~~

To respray rear bumper, bootlid and tail panel

1939 ~~2,282.20~~

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 ~~271.00~~

To check electrical wiring systems and lightings at the rear section for proper function.

150 ~~177.00~~

Sundries

? 150.00

Total Labour 1: 0,705.20

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
Trim panel ?	1	2,945.60	2,945.60
RR BUMPER CARRIER ?	1	870.00	870.00
RR BUMPER RH MOUNT ?	1	198.30	198.30
RR BUMPER ADAPTER ?	1	45.75	45.75
REAR BUMPER TRIM PRIMED <i>de</i>	1	242.25	242.25
RR BUMPER CTR GUIDE ?	1	67.45	67.45
BOOTLID CHROME TRIM STRIP <i>X</i>	1	85.35	85.35
EMBLEM GROMMET <i>rec</i>	2	0.85	1.70
MODEL LETTERING 730Li <i>rec</i>	1	64.45	64.45
BMW EMBLEM 82MM <i>rec</i>	1	71.60	71.60
RR BUMPER RH REFLECTOR <i>sca</i>	1	37.75	37.75
RR RH FENDER LIGHT <i>sca</i>	1	788.55	788.55
RR RH BOOTLID LIGHT ?	1	465.75	465.75
DECOUPLING RING PDC TORQUE CONVERTE <i>rec</i>	4	5.10	20.40
BUMPER PDC SENSOR (A90 SOPHISTOGRAU <i>dis</i>	1	370.00	370.00

Total Parts : 6,274.90

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55655
Date Estimated : 01/08/2020
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL551H	WBAKB22090C951160	11/11/2011	730LiA	0

Claims OD / <u>3rd Party</u> Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time _____	Excess S\$ _____
Surveyor's Name <u>RASUL</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days <u>6 days</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Labour 1	:	6,705.20
Parts	:	6,274.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	908.61
Grand Total	:	13,888.71

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **