

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

03 AUG 2020

ESTIMATE

Estimate No. : b1 55655 Page No. : 1 of 5
Date Estimated : 01/08/2020
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR - Tan Chee Kiong 33 Lorong G Telok Kurau Singapore Singapore 426204	- ACCOUNT - 219 India Int'L Insurance Pte Ltd 64 Cecil Street #04-05 IOB Building Singapore 049711
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL551H	WBAKB22090C951160	11/11/2011	730LiA	0

DESCRIPTION

To replace rear bumper panel and attachments, rework bootlid and tail panel

~~2550~~ 3,825.00

To respray rear bumper, bootlid and tail panel

~~1939~~ 2,282.20

To remove and install boot compartment carpet and garnish to facilitate repairs.

~~230~~ 271.00

To check electrical wiring systems and lightings at the rear section for proper function.

~~150~~ 177.00

Sundries

~~80~~ 150.00

Total Labour 1: 6,705.20

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
Trim panel ? xsu	1	2,945.60	2,945.60
RR BUMPER CARRIER ? xsu	1	870.00	870.00
RR BUMPER RH MOUNT ? cm	1	198.30	198.30
RR BUMPER ADAPTER ? cm	1	45.75	45.75
REAR BUMPER TRIM PRIMED de	1	242.25	242.25
RR BUMPER CTR GUIDE ? xsu	1	67.45	67.45
BOOTLID CHROME TRIM STRIP xsu	1	85.35	85.35
EMBLEM GROMMET nee	2	0.85	1.70
MODEL LETTERING 730LI nee	1	64.45	64.45
BMW EMBLEM 82MM nee	1	71.60	71.60
RR BUMPER RH REFLECTOR sca	1	37.75	37.75
RR RH FENDER LIGHT sca	1	788.55	788.55
RR RH BOOTLID LIGHT ? xsu	1	465.75	465.75
DECOUPLING RING PDC TORQUE CONVERTE nee	4	5.10	20.40
BUMPER PDC SENSOR (A90 SOPHISTOGRAU dis	1	370.00	370.00

Total Parts : 6,274.90

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55655
Date Estimated : 01/08/2020
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL551H	WBAKB22090C951160	11/11/2011	730LiA	0

Claims OD / 3rd Party Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess S\$ _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	6,705.20
Parts	:	6,274.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	908.61
Grand Total	:	13,888.71

THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Simle Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 55655**
Date Estimated : **01/08/2020**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Tan Chee Kiong
33 Lorong G
Telok Kurau
Singapore
Singapore 426204

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL551H	WBAKB22090C951160	11/11/2011	730LiA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER (PDC) scr ✓	1,695.75	1.00		1,695.75
# COVERING REAR RIGHT cra ✓	134.30	1.00		134.30
# RR BUMPER VENTILATION COVERING cra ✓	27.70	1.00		27.70

SUPPLEMENTARY ITEMS

Total Labour :	150.00
Total Parts :	1,857.75
Total Labour & Parts :	2,007.75
Deduction for Excess :	0.00
Total Repair Costs less Excess:	2,007.75
GST @7%:	140.54
Grand Total :	2,148.29